TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Hartmann Fleet Professionals GmbH
Leerenstraße 25
29683 Bad Fallingbostel

Expertise

Protocol number: 48372943
Order No. / Reference: 27174971
Inspection date: 26 Oct 2026

Manufacturer: Mercedes-Benz	Model: Vito 116 CDI Extralang HA BASE
VIN: W1V44760514103714	





Vehicle details

Manufacturer / Type / Model / Equipment	
Mercedes-Benz Vito 116 CDI Extralang HA BASE	
Vehicle Identification number	W1V44760514103714
Mileage (Read)	174,950 km
First registration	25 Aug 2022
Number of holders	1
Fuel type	Diesel
Engine displacement / Cylinder	1,950 ccm / 4
Power	120 kW
Gearbox / Number of gears	Manual / 6
Type of drive	Rear drive
Type of vehicle	Van
Colour / colour code	Navyblau MB 5610
Doors / Seats	4 / 2
Upholstery type	Cloth
Colour of upholstery	Black-Grey

Vehicle details

Maintenance booklet / proof	Non-existent	**Next maintenance in**	649 Tag(e)
Key is / should be	4 / 4	**FZG documents**	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	GM181938
Previous damage / Accident	None detectable	**Repainting**	None detectable
Inspection conditions	sufficient	**Lifting equipment / pit**	yes
Test drive	Not performed	**Engine function test**	Performed
Manufacturer key number/ type code number	2222 / BBJ 03137		
Emission standard	EURO6	**fine dust sticker**	
Permitted total weight	2,800 kg	**Empty weight**	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	225/55 R17 109T	Winter tyres on Steel rim with wheel cover	Continental	6mm / 6mm
2)	225/55 R17 109T	Winter tyres on Steel rim with wheel cover	Continental	6mm / 6mm

Additional tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	225/55 R17 109H	Summer tyres on Steel	Continental	3mm / 3mm
2)	225/55 R17 109H	Summer tyres on Steel	Continental	1mm / 1mm

Replacement

Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
E	225/55 R17 109H	Summer tyres on Steel	Continental	6 mm

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

Equipment

Standard equipment

- Screw-in towing eye front/rear
- Passenger side airbag
- ATTENTION ASSIST (ATTENTION ASSIST can assist the driver on long, monotonous journeys by monitoring attention. If signs of fatigue or increasing inattention are detected, it suggests a break.)
- Fixing points in the roof frame
- third brake light
- COC documents
- Diesel particulate filter
- Electronic Stability Program (ADAPTIVE ESP) with integrated anti-lock braking system (ABS) (traction control (ASR) - electronic brake force distribution (EBD) - brake assist (BAS))
- Parking brake
- Generator management (Generator management helps reduce fuel consumption and CO2 emissions. The generator is switched off and the vehicle's electrical system is powered by the battery when it is sufficiently charged. This relieves the engine of the burden of charging the battery, for example, during acceleration. - When braking and during coasting downhill, the generator is switched on and the vehicle's kinetic energy is recuperated to charge the battery.)
- Communication module (LTE) for digital services
- Headrests (2), front
- Paint finish: Solid color paint
- Steering wheel adjustable for tilt and height
- Headlight range control
- Multifunction steering wheel (with trip computer)
- Package: BlueEFFICIENCY (Efficiency Package)
- Upholstery: Caluma fabric, black
- Tires: Premium protection tires (3 years)
- Headlights: halogen technology
- Key: 3-button remote control
- electromechanical power steering
- Seats: Driver's seat
- 12V socket
- continuous partition wall
- Pre-installation for Remote Services Plus
- Maintenance interval indicator >>ASSYST<
- Heat-insulating glass all around
- Registration as a truck
- Axle ratio i = 3.267
- Driver's side airbag
- Exterior mirrors, manually adjustable (2)
- Outdoor temperature display
- Battery: Backup battery for starting process
- Battery: fleece battery 12 V / 92 Ah
- Hill start assist
- Brake lights, adaptive
- Front cupholder
- Electronic tachometer
- Chassis: Standard chassis
- HVO-capable vehicle
- Electric window regulator driver/passenger (with anti-pinch protection, quick lowering and raising)
- Generator 14 V / 200 A
- Speed limit 210 km/h
- Transmission: 6-speed manual transmission TSG 380
- Weight variant 2,800 kg
- Seatbelt warning device for front passenger seat
- Seatbelt warning device for driver's seat
- Lockable glove box
- Boot lid
- Interior trim of cargo area, side
- Instrument cluster with pixel matrix display (operated via the buttons on the multifunction steering wheel - round instruments for speedometer and tachometer or fuel level and coolant temperature - high-quality pixel matrix display in white and red between the large round instruments)
- Mercedes-Benz emergency call system (communication module (LTE) for digital services breakdown management)
- Breakdown management
- Tires: Tires without specified make
- Tires: Summer tires
- Sliding door on the right, cargo/passenger compartment
- Crosswind Assist
- Seats: Adjustable passenger seat
- Start-stop function
- Cruise control
- First aid kit
- Warning triangle
- Immobiliser
- Central locking with radio remote control
- Registration certificate, Part II

Extra equipment

- Upgrading/downgrading (upgrading to 3.05 t GVW)
- Comfort roof control unit in conjunction with rain sensor
- Burglar and theft alarm system (without interior monitoring)
- Generator 14 V / 250 A
- Rear camera not foldable
- Tempmatic controlled air conditioning
- LED light strip in the cargo area
- Navigation accessories: Live Traffic Information
- Radio: Digital Radio DAB
- Tires: 225/55R17
- Spare wheel under the rear of the vehicle with jack
- Wheels: Steel rims 6.5 J x 17
- Keys: 2 additional master keys
- Seats: Comfort driver's seat
- Seat heating on driver's side
- Electrically adjustable and heated exterior mirrors, left and right
- Driving light assistant (automatically switching on driving lights)
- Interior lining of the cargo area up to roof height (wood)
- Large fuel tank, approx. 70 liters
- Center console with storage compartment
- Halogen fog lights
- Rain sensor
- Tire pressure monitoring (on front and rear axles (wireless))
- High-resolution reversing camera with guide lines
- Seats: Comfort passenger seat
- Seat heating on passenger side

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. Lifting equipment and/or a pit were available for examining the vehicle.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.

Value reducing factors

No.	Component group	Description
1	Bonnet	Insulation lining - Broken / torn - Replace
2	Door - front left side	Door - Dent / paintcoat damage - Smart repair
3	Side panel - rear right side	Side panel - Scratch(es) - Smart repair
4	2nd wheel set	2 tyres - Worn - Replace
5	Body	Body - Glued / labelled - De-glue / neutralise
6	Sill - left side	Sill - Dent / paintcoat damage - Repair and paint
7	Roof	Roof rail - right side - Scratch(es) - Paint
8	Sliding door, right	Sliding door - Scratch(es) - Paint
9	Mudguard - left side	Mudguard - left side - Deformed - Replace
10	Bonnet	Bonnet - Corrosion - Repair and paint
11	Boot lid / rear door	Boot lid - Corrosion - Repair and paint
12	Roof	Roof - Corrosion - Repair and paint

Wear and tear

No.	Component group	Description
1	Front bumper	Front bumper (unpainted) - Scratch(es) - No deduction
2	Door - front right side	Door - Scratch(es) - No deduction
3	Vehicle glazing	Windscreen - Stone chips - No deduction
4	Seat - front	Seat cover - right side - Broken / torn - No deduction
5	Rear bumper	Rear bumper (unpainted) - Scratch(es) - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
  (Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
  (Functional testing of driver assistance systems is not included in the scope of services!)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

No apparent prior damage that had been repaired could be found on the vehicle.

Comments

- Winterradsatz ist kein Bestandteil des Auslieferungsumfangs.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)




Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel

Figure 9: Interior 360° view (Online Link)



Figure 10: Cargo area



Figure 11: VIN



Figure 12: Mounted tyres



Figure 13: Documents



Figure 14: Additional tyres



Figure 15: Additional tyres



Figure 16: Navigation



Figure 17: Misc.



Figure 18: Misc.



Figure 19: Misc.



Figure 20: Misc.



Figure 21: Misc.



Figure 22: Misc.




Figure 23: Misc.



Figure 24: Misc.




Figure 25: Misc.



Figure 26: Misc.



Figure 27: Misc.



Figure 28: Misc.



Figure 29: Misc.



Figure 30: Misc.



Figure 31: Misc.



Figure 32: Misc.



Damage 1: Bonnet: Insulation lining - Broken / torn - Replace



Damage 2: Door - front left side: Door - Dent / paintcoat damage - Smart repair



Damage 2: Door - front left side: Door - Dent / paintcoat damage - Smart repair




Damage 2: Door - front left side: Door - Dent / paintcoat damage - Smart repair



Damage 3: Side panel - rear right side: Side panel - Scratch(es) - Smart repair



Damage 3: Side panel - rear right side: Side panel - Scratch(es) - Smart repair



Damage 4: 2nd wheel set: 2 tyres - Worn - Replace



Damage 4: 2nd wheel set: 2 tyres - Worn - Replace



Damage 5: Body: Body - Glued / labelled - De-glue / neutralise



Damage 5: Body: Body - Glued / labelled - De-glue / neutralise



Damage 6: Sill - left side: Sill - Dent / paintcoat damage - Repair and paint



Damage 6: Sill - left side: Sill - Dent / paintcoat damage - Repair and paint



Damage 7: Roof: Roof rail - right side - Scratch(es) - Paint



Damage 7: Roof: Roof rail - right side - Scratch(es) - Paint



Damage 8: Sliding door, right: Sliding door - Scratch(es) - Paint



Damage 8: Sliding door, right: Sliding door - Scratch(es) - Paint



Damage 8: Sliding door, right: Sliding door - Scratch(es) - Paint




Damage 8: Sliding door, right: Sliding door - Scratch(es) - Paint



Damage 9: Mudguard - left side: Mudguard - left side - Deformed - Replace



Damage 9: Mudguard - left side: Mudguard - left side - Deformed - Replace



Damage 9: Mudguard - left side: Mudguard - left side - Deformed - Replace



Damage 10: Bonnet: Bonnet - Corrosion - Repair and paint



Damage 10: Bonnet: Bonnet - Corrosion - Repair and paint



Damage 10: Bonnet: Bonnet - Corrosion - Repair and paint



Damage 10: Bonnet: Bonnet - Corrosion - Repair and paint



Damage 10: Bonnet: Bonnet - Corrosion - Repair and paint



Damage 10: Bonnet: Bonnet - Corrosion - Repair and paint




Damage 11: Boot lid / rear door: Boot lid - Corrosion - Repair and paint



Damage 11: Boot lid / rear door: Boot lid - Corrosion - Repair and paint



Damage 11: Boot lid / rear door: Boot lid - Corrosion - Repair and paint



Damage 12: Roof: Roof - Corrosion - Repair and paint




Damage 12: Roof: Roof - Corrosion - Repair and paint



Damage 12: Roof: Roof - Corrosion - Repair and paint



Damage 12: Roof: Roof - Corrosion - Repair and paint




Damage 12: Roof: Roof - Corrosion - Repair and paint



Wear and tear 2: Door - front right side: Door - Scratch(es) - No deduction



Wear and tear 2: Door - front right side: Door - Scratch(es) - No deduction



Wear and tear 4: Seat - front: Seat cover - right side - Broken / torn - No deduction



Wear and tear 4: Seat - front: Seat cover - right side - Broken / torn - No deduction



Wear and tear 5: Rear bumper: Rear bumper (unpainted) - Scratch(es) - No deduction



Wear and tear 5: Rear bumper: Rear bumper (unpainted) - Scratch(es) - No deduction