MACADAM








## Skoda Octavia (UKL): 2CPM508

| | | | |
|---|---|---|---|
| Vinnumber: | **TMBJG8NX5PY017392** | Versionname: | **Octavia Combi Clever 2.0TDi 115pk/cv 5p DSG7** |
| First Registrationdate: | **7/10/2022** | Fiscalpower: | |
| Expertise Mileage: | **76717** | Power Kw: | **85** |
| Bodytype: | | Type of rims (mounted) | **Aluminium** |
| Gearbox: | **Automatic** | | |
| Transmission: | | | |
| Fueltype: | **Diesel** | | |
| Maintenance | **OK** | | |
| Battery functioning | **Yes** | | |
| Type of rims (mounted) | **Aluminium** | | |
| Certificate of Conformity | **Yes** | | |
| Category | **Passenger Car** | | |
| Registration Certificate Car (BE) | **Yes** | | |

## Options

| | | | |
|---|---|---|---|
| Number of keys total | **3** | Luggage cover | |
| GPS | | Type of Tow bar | **No Tow bar** |
| Type of Maintenance book | **Digital maintenance** | | |
| Type of GPS storage | **HD** | | |

## Tyres

| | | | | |
|---|---|---|---|---|
| Summer tyres: | **206/60/16/92 V** | | | |
| | Fr.L. | **Goodyear: 3 mm** | Fr.R. | **Goodyear: 3 mm** |
| | Re.L. | **Goodyear: 6 mm** | Re.R. | **Goodyear: 6 mm** |

| | |
|---|---|
| Tyre profile depth FL | **3.0** |
| Tyre profile depth FR | **3.0** |
| Tyre profile depth RL | **6.0** |
| Tyre profile depth RR | **6.0** |
| Tyre size FL | **206/60 R 16 92 V** |
| Tyre size FR | **206/60 R 16 92 V** |
| Tyre size RL | **206/60 R 16 92 V** |
| Tyre size RR | **206/60 R 16 92 V** |
| Tyre type FL | **Summer** |
| Tyre type FR | **Summer** |
| Tyre type RL | **Summer** |
| Tyre type RR | **Summer** |
| Tyre make FL | **259** |
| Tyre make FR | **259** |
| Tyre make RL | **259** |
| Tyre make RR | **259** |

## Assistance equipment

| | | | |
|---|---|---|---|
| Spare wheel | **Yes** | Jack | **Yes** |

**Ignition key, Broken, Replace**




**Seat cover FL, Worn, Acceptable**




Floor covering FL, Burned, Smart repair




Seat cover FR, Stain, Cleaning




Bumper F, Dent(s) and scratch(es), Spot repair






Alloy rim FL, Scratch(es), Repair and paint (complete)






Door RL, Scratch(es), Acceptable






Wing RL, Dent(s), Acceptable





Boot carpet, Stain, Cleaning




**Boot lid covering R, Scratch(es), Acceptable**







**Rear bulkhead lining, Scratch(es), Acceptable**



**Bumper R, Scratch(es), Repair and paint (complete)**









**Roof pillar R, Dent(s), Acceptable**




**Wing RR, Scratch(es), Acceptable**





**Alloy rim FR, Scratch(es), Repair and paint (complete)**







**Outside rear-view mirror housing R, Scratch(es), Acceptable**





**Door RR, Scratch(es), Acceptable**




**Roof, Scratch(es), Repair and paint (complete)**



# Onderhoudshistorie van: TMBJG8NX5PY017392

ALPHABET

| | |
|---|---|
| **Kenteken** | 2CPM508 |
| **Merk Model** | Skoda  Octavia Combi Clever 2.0TDi 115pk/cv 5p DSG7 |
| **Brandstofsoort** | Diesel |
| **Datum deel1** | 10/7/22 |

| Datum reparatie | Kilometerstand | Reparatie omschrijving | Bewerking |
|---|---|---|---|
| 6/20/25 | 56,265 | brandblusapparaat | |
| 6/20/25 | 56,265 | Inspectie met olieververvanging (vast in | Uitvoeren |
| 6/20/25 | 56,265 | klein materiaal | |
| 6/20/25 | 56,265 | koelwatervloeistof | Bijvullen/-laden |
| 6/20/25 | 56,265 | luchtfilter interieur | Vervangen |
| 6/20/25 | 56,265 | remvloeistof | Vervangen |
| 6/20/25 | 56,265 | ruitenwisserrubber achter | Vervangen |
| 6/20/25 | 56,265 | ruitenwisserrubber vooraan | Vervangen |
| 6/20/25 | 56,265 | ruitenwisservloeistof | Bijvullen/-laden |
| 2/14/24 | 28,827 | Inspectie met olieververvanging (vast in | Uitvoeren |
| 2/14/24 | 28,827 | klein materiaal | |
| 2/14/24 | 28,827 | ruitenwisservloeistof | Bijvullen/-laden |