Volkswagen

VIN: WVWZZZE1ZNP033483

Estimated repair cost

510.00 EUR
TOTAL



Description

Registration number 2FBA759	**First registration date** -	**Odometer** 92869 km
Color -	**Model year** -	**Upholstery** -
Number of doors -	**Number of seats** -	**Generation** -

Statement details

Inspection loc
PARC LIZY

Control

Detected issues

Engine / Sound	✓ Ok	Vehicle leak proofness	✓ Ok
Exhaust / Clarity	✓ Ok		

Defects & corrections

#	Element	Defect	Correction	net cost
001	Tyre repair kit complete / -	Missing	Replace	100.42 EUR



Bodywork time	Paint time	Part Price	Lumpsum
-	-	-	**100.42 EUR**
Bodywork cost	**Paint cost**	**MaterialCost**	
-	-	-	

002	coc / -	Missing	Acceptable	-

All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.



Bodywork time	Paint time	Part Price	Lumpsum
-	-	-	-
Bodywork cost	**Paint cost**	**MaterialCost**	
-	-	-	

003	Door sill / Front Left	Dent	Smart repair	49.00 EUR



Bodywork time	Paint time	Part Price	Lumpsum
-	-	-	**49.00 EUR**
Bodywork cost	**Paint cost**	**MaterialCost**	
-	-	-	

004	Bumper / Back Painted : Yes	Dent	Repair	194.00 EUR



Bodywork time	Paint time	Part Price	Lumpsum
1.00 h	**1.40 h**	-	-
Bodywork cost	**Paint cost**	**MaterialCost**	
75.00 EUR	**119.00 EUR**	-	

005	Wheel trim / Back Right Rim/Tyre diameter : 18 "	Scratched	Replace	58.79 EUR



Bodywork time	Paint time	Part Price	Lumpsum
0.10 h	-	**51.29 EUR**	-
Bodywork cost	**Paint cost**	**MaterialCost**	
7.50 EUR	-	-	

006	Door sill / Back Right	Dent	Acceptable	-



Bodywork time	Paint time	Part Price	Lumpsum
-	-	-	-
Bodywork cost	**Paint cost**	**MaterialCost**	
-	-	-	

007	Door panel / Back Right	Dent	Smart repair	49.00 EUR



Bodywork time	Paint time	Part Price	Lumpsum
-	-	-	**49.00 EUR**
Bodywork cost	**Paint cost**	**MaterialCost**	
-	-	-	

008	Seat / Front Right	Stained	Cleaning	0.00 EUR

All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.



Bodywork time	Paint time	Part Price	Lumpsum
-	-	-	-
Bodywork cost	**Paint cost**	**MaterialCost**	
-	-	-	

009	Wheel trim / Front Right Rim/Tyre diameter : 18 "	Scratched	Replace	58.79 EUR



Bodywork time	Paint time	Part Price	Lumpsum
0.10 h	-	51.29 EUR	-
Bodywork cost	**Paint cost**	**MaterialCost**	
7.50 EUR	-	-	

Loose Items

- [x] Quick charging cable (Type 2, Mode 3)
- [x] Registration certificate
- [x] Registration certificate owner
- [x] Spare Key
- [ ] Tyre repair kit complete
- [x] Rear parcel shelf

Main set of tyres

Front Left	MICHELIN	215/55/18 99 V All-season	4 mm
Front Right	MICHELIN	215/55/18 99 V All-season	4 mm
Back Left	MICHELIN	215/55/18 99 V All-season	4 mm
Back Right	MICHELIN	215/55/18 99 V All-season	4 mm

All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.

Pictures


Front left


Rear left


Boot opened


Rear right


Rear passenger compartment


Dashboard from rear seat


Front passenger compartment


Front right




Odometer


Navigation


Spare Tyre


Cable

All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.




Vin


Other


Tyre repair kit complete / - / Missing


coc / - / Missing


Door sill / Front Left / Dent


Door sill / Front Left / Dent


Door sill / Front Left / Dent



Bumper / Back / Dent


Bumper / Back / Dent


Bumper / Back / Dent


Wheel trim / Back Right / Scratched


Wheel trim / Back Right / Scratched


Door sill / Back Right / Dent


Door panel / Back Right / Dent


Door panel / Back Right / Dent

All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.



Door panel / Back Right / Dent



Seat / Front Right / Stained



Seat / Front Right / Stained



Wheel trim / Front Right / Scratched



Wheel trim / Front Right / Scratched



Wheel trim / Front Right / Scratched

All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.