# MERCEDES-BENZ CLA SHOOTING BRAKE

## Vehicle information


| | | | |
|---|---|---|---|
| Make: | **MERCEDES-BENZ** | License: | **2CHQ240** |
| Gearbox: | | Body color: | |
| Model: | **CLA SHOOTING BRAKE** | VIN: | **W1K5M8GB9PN325331** |
| Fuel type: | | Power: | **118 kW** |
| Version: | **1.3 CLA 250 E BUSINESS SOLUTION DCT** | First registration | **01/08/2022** |
| Mileage: | **74344 km** | N° of doors: | |


## Damage summary

| | |
|---|---|
| **Interior** | 1 |
| **Right** | 2 |
| **Roof & others** | 1 |

## Commercial pictures






































## Options according to the inspector

| | |
|---|---|
| GPS | **Yes** |

## Damages


**Alloy rim FR polished**
Scratch(es)
Repair and paint (complete)
Right







**Bodywork**
Damaged
Acceptable
Roof & others





**Service**
Maintenance
Check
Interior



**Step R**


Dent(s) and scratch(es)

Repair and paint (complete)

Right









## Tyres

**Front Left**

Summer

Aluminium

205/55/17/91/W

Pirelli

5.0 mm

**Front Right**

Summer

Aluminium

205/55/17/91/W

Pirelli

5.0 mm

**Rear Left**

Summer

Aluminium

205/55/17/91/W

Pirelli

5.0 mm

**Rear Right**

Summer

Aluminium

205/55/17/91/W

Pirelli

5.0 mm

## Checks

| | | | |
|---|---|---|---|
| Battery level | **40** | Category | **Passenger Car** |
| Certificate of Conformity | **Yes** | Compressor | **Yes** |
| Maintenance | **NOT OK** | Number of charging cables (normal) | **1** |
| Number of charging cables (rapid charge) | **1** | Number of keys total | **2** |
| Registration Certificate Car (BE) | **Yes** | Registration Certificate Home (BE) | **No** |
| Repair kit | **Yes** | Reset to factory settings | **Yes, vehicle is reset to factory settings** |
| Statutory inspection | **01/08/2028** | Statutory inspection | **OK** |
| Type of Maintenance book | **Digital maintenance** | | |

**Information on the content and the scope of the inspection report:**

- The assessment is based on the sales standards specified by the customer.
- Acceptable usage damages according to the sales standards are not always documented in this status report.
- The specified repair methods and/or resulting repair times have been determined, taking into account modern industrial repair methods.
- The purchasing dealer should assess individual repair costs.
- The inspection was carried out in a non-disassembly condition. Macadam cannot be held responsible for any missing information. For further information, please contact the seller.