

PEUGEOT 508 SW

Vehicle information

Brand:	PEUGEOT	License plate:	
Gearbox:		Body color:	
Model:	508 SW	LEVEL:	VR3FCYHZTLY051578
Fuel type:		Power:	96 kW
Version:	PEUGEOT 508 SW 1.5 BLUEHDI 130 S&S AUTO	First registration	05/02/2021
Mileage:	123262 km	Number of doors:	

Summary of damages

RIGHT	1
LEFT	1
Interior	2
Roof & other	3

Commercial photos





Options according to the inspector

GPS

Yes

Damages

Right rear wing

, poor repair

- Repair and paint (complete)




Bodywork

Damaged -

Acceptable.

Roof & other










Lettré Body Shop
Logo Removal
Roof & more



Ignition key
not working (well)
Acceptable
Interior



Damaged Interior

- Acceptable

Interior





Alloy wheel, left-hand side,
scratch(es)
- Repair and paint (complete
)



Pavillon
Bosse(s)
PDR - Paintless
Dent Repair Roof & Oth



Tires

Front Left
 Summer
 Aluminum
 215/60/16/95/V
 Bridgestone
 2.0 mm
Front Right
 Summer
 Aluminum
 215/60/16/95/V
 Bridgestone
 2.0 mm
Left Back
 Summer
 Aluminum
 215/60/16/95/V
 Bridgestone
 4.0 mm
Rear Right
 Summer
 Aluminum
 215/60/16/95/V
 Bridgestone
 4.0 mm

Controls

Category	Private vehicle	Registration certificate - home address section	No
Vehicle registration certificate	Yes	Certificate of Conformity	Yes
Compressor	Yes	Vehicle inspection	OK
Vehicle inspection	05/02/2027	Interview	OK
Interview	over 17600 km	Repair kit	Yes
Number of charging cables (220V)	0	Number of charging cables (fast charging)	0
Total number of keys	2	Charge level	70
Factory reset	Yes, the vehicle has been reset to factory settings.		Digital interview
	Type of maintenance log		

Information on the content and scope of the inspection report:

- The evaluation is based on the sales standards specified by the client.
- Acceptable wear and tear according to sales standards is not always documented in this condition report.
- The specified repair methods and/or resulting repair times were determined taking into account modern industrial repair methods.
- The reseller must assess individual repair costs.
- The inspection was carried out without dismantling. Macadam cannot be held responsible for any missing information. For further information, please contact the seller.