TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
ARS Altmann AG Automobillogistik
Römerstraße 3
64560 Riedstadt

Expertise

Protocol number: 48410540
Order No. / Reference: 27208793
Inspection date: 27 Oct 2026

Manufacturer: Opel	Model: Zafira Life 2.0 D M Aut. Selection
VIN: VXEVEEHS7MZ115999	





Vehicle details

Manufacturer / Type / Model / Equipment	
Opel Zafira Life 2.0 D M Aut. Selection	
Vehicle Identification number	VXEVEEHS7MZ115999
Mileage (Read)	84,232 km
First registration	3 Feb 2022
Number of holders	1
Fuel type	Diesel
Engine displacement / Cylinder	1,997 ccm / 4
Power	106 kW
Gearbox / Number of gears	Automatic / 8
Type of drive	Front drive
Type of vehicle	Van
Colour / colour code	Jade Weiß
Doors / Seats	4 / 9
Upholstery type	Cloth
Colour of upholstery	Grey-Black
Vehicle with smoke odor	no

TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
ARS Altmann AG Automobillogistik
Römerstraße 3
64560 Riedstadt

Vehicle details

Maintenance booklet / proof	digital proof / complete	**Next maintenance in**	1 Monat(e)
Last service on / at	11/2024 at 51,942 km		
Key is / should be	1 / 2	**FZG documents**	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	GF962989
Previous damage / Accident	Detectable	**Repainting**	Detectable
Inspection conditions	sufficient	**Lifting equipment / pit**	No
Test drive	Not performed	**Engine function test**	Performed
Manufacturer key number/ type code number	3003 / BBV 00264		
Emission standard	EURO6	**fine dust sticker**	
Permitted total weight	2,750 kg	**Empty weight**	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	225/55 R17 109T	Winter tyres on Light alloy	Pirelli	6mm / 6mm
2)	225/55 R17 109T	Winter tyres on Light alloy	Pirelli	7mm / 7mm

Additional tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	225/55 R17 101Y	Summer tyres on Steel	Pirelli	6mm / 6mm
2)	225/55 R17 101Y	Summer tyres on Steel	Pirelli	6mm / 6mm

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

Equipment

Standard equipment

- Low beam automatically
- Airbag for driver and passenger side
- Airbag: Curtain airbags, in the 2nd and 3rd rows of seats
- Automatic activation of the hazard warning lights
- Exterior mirror housings in black
- On-board computer
- Diesel particulate filter
- Electronic Stability Program (ESP Plus)
- Electric front windows
- Transmission: 8-speed automatic transmission
- Glazed tailgate, with rear window wiper and heater
- Air conditioning
- LED daytime running lights
- Headlight range adjustment, manual
- Rear fog lights with reversing lights
- Package: Driver Assistance Package 2
- Radio: Digital radio reception DAB+
- Rain sensor
- Tire pressure warning
- Sliding door trim with cover, in vehicle color
- Side protection strips in vehicle color
- Seat belts: Three-point seat belts in all seats
- Seats: 9 seats in fabric, Meltem Grey
- Sun visors driver and passenger side
- Traction Control (TC) Plus
- Exterior door handles, in car color
- Central locking with remote control
- Storage compartments
- Airbag: Head airbags, driver and front passenger
- Anti-lock braking system (ABS)
- Exterior mirrors, electrically adjustable, heated and folding
- Hill Start Assist
- third brake light
- Tachometer
- Window: Window, driver's side in the 2nd row of seats, fixed
- Manual handbrake
- Child safety lock, mechanical
- Paint finish: Solid
- Steering wheel: Comfort steering wheel
- Fog light
- Package: Driver Assistance Package 1
- Rear parking pilot
- Radio: Multimedia radio with 7" touchscreen color display
- Tire repair kit
- Wheels: Steel wheels 7J x 17 with full wheel cover
- Side impact protection
- Power steering
- Safety steering column, height and length adjustable
- Solar Protect thermal insulation glazing
- 12V socket
- Door: Sliding door, passenger side
- Immobiliser
- Ignition keys (2), both foldable

Extra equipment

- luggage compartment cover
- Heated seats for driver and front passenger
- Solar Protect heat-insulating glazing (extra dark tinted in the rear)
- Xenon headlights with LED daytime running lights
- Package: Innovation Package (Head-Up Display - Park Pilot, front and rear - 180° panoramic reversing camera - Blind Spot Warning - Multimedia Navi Pro with 7" touchscreen, voice control, Bluetooth, hands-free system, USB, Apple CarPlay, Android Auto, OpelConnect)

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. No lifting equipment or pit was available for inspecting the vehicle. Therefore, inspection of the vehicle's underside was only possible to a limited extent.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.

Value reducing factors

No.	Component group	Description
1	Mudguard - left side	Mudguard - left side - Stone chips - Smart repair
2	Side panel - rear left side	Side panel - Stone chips - Smart repair
3	Door - front right side	Door - Stone chips - Smart repair
4	Front bumper	Front bumper - Scratched - Smart repair

Wear and tear

No.	Component group	Description
1	Interior	Interior - Soiled - No deduction
2	Rear bumper	Rear bumper - Scratch(es) - No deduction
3	Vehicle glazing	Windscreen - Stone chips - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.

Missing parts

Description
Documents - Log book
Equipment - Tirefit complete
Equipment - Vehicle key

Accident damages

No.	Accident
1	Side right

Repainting

No.	Repainting
1	Side panel - rear right side

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
  (Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
  (Functional testing of driver assistance systems is not included in the scope of services!)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations of light commercial vehicles published by Alphabet Fleet Management GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

Non-repaired previous damages were found at the vehicle. The necessary repair costs are listed in the expert report or if necessary, are listed in detail in a separately enclosed repair cost calculation.

Comments

- Winterradsatz ist kein Bestandteil des Auslieferumfangs.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)




Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel



Figure 9: Cargo area



Figure 10: VIN



Figure 11: Mounted tyres




Figure 12: Documents



Figure 13: Documents



Figure 14: Additional tyres



Figure 15: Navigation



Figure 16: Misc.




Figure 17: Misc.



Figure 18: Misc.



Figure 19: Misc.



Figure 20: Misc.



Figure 21: Misc.



Figure 22: Misc.




Figure 23: Misc.




Figure 24: Misc.



Figure 25: Misc.



Figure 26: Misc.



Damage 1: Mudguard - left side: Mudguard - left side - Stone chips - Smart repair



Damage 1: Mudguard - left side: Mudguard - left side - Stone chips - Smart repair



Damage 2: Side panel - rear left side: Side panel - Stone chips - Smart repair



Damage 2: Side panel - rear left side: Side panel - Stone chips - Smart repair



Damage 2: Side panel - rear left side: Side panel - Stone chips - Smart repair



Damage 3: Door - front right side: Door - Stone chips - Smart repair



Damage 3: Door - front right side: Door - Stone chips - Smart repair



Damage 4: Front bumper: Front bumper - Scratched - Smart repair



Damage 4: Front bumper: Front bumper - Scratched - Smart repair



Missing part 3: Equipment: Vehicle key - Missing - Replace



Accident 1: Side right



Accident 1: Side right



Accident 1: Side right



Accident 1: Side right



Accident 1: Side right



Repainting 1: Side panel - rear right side

TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
ARS Altmann AG Automobillogistik
Römerstraße 3
64560 Riedstadt



Repainting 1: Side panel - rear right side