TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Mosolf SE & Co.KG
August-Horch-Straße 1
04519 Rackwitz

Expertise

Protocol number: 48427621
Order No. / Reference: 27090415
Inspection date: 27 Oct 2026

Manufacturer: Opel	Model: Combo Cargo XL 1.5 D EHZ Edition
VIN: W0VEFYHYCMJ854523	





Vehicle details

Manufacturer / Type / Model / Equipment	
Opel Combo Cargo XL 1.5 D EHZ Edition	
Vehicle Identification number	W0VEFYHYCMJ854523
Mileage (Read)	56,112 km
First registration	21 Mar 2022
Number of holders	1
Next periodical technical inspection	02/2026
(Report on hand)	
Fuel type	Diesel
Engine displacement / Cylinder	1,499 ccm / 4
Power	75 kW
Gearbox / Number of gears	Manual / 5
Type of drive	Front drive
Type of vehicle	Van
Colour / colour code	Jade Weiß
Doors / Seats	4 / 3
Upholstery type	Cloth
Colour of upholstery	Black-Grey

Vehicle details

Maintenance booklet / proof	digital evidence / incomplete	**Next maintenance in**	41,700 km
Last service on / at	06/2025 at 47,811 km		
Key is / should be	2 / 2	**FZG documents**	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	GF943784
Previous damage / Accident	Detectable	**Repainting**	None detectable
Inspection conditions	sufficient	**Lifting equipment / pit**	yes
Test drive	Not performed	**Engine function test**	Performed
Manufacturer key number/ type code number	1844 / AIQ 00729		
Emission standard	EURO6	**fine dust sticker**	
Permitted total weight	2,355 kg	**Empty weight**	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	215/65 R16 98H	All-season tyres on Steel rim with wheel cover	Uniroyal	5mm / 5mm
2)	215/65 R16 102V	All-season tyres on Steel rim with wheel cover	Maxxis	6mm / 6mm

Replacement

Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
	Tirefit	Expiration date 05/2026		

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

Equipment

Standard equipment

- Cover strip for sliding door track (in car color)
- ABS including brake assist and adaptive brake light
- Driver's side airbag
- Anti-lock braking system (ABS) with cornering brake control and brake assist
- Automatic dipped headlights
- Exterior mirrors, electrically adjustable, heated and manually folding
- Battery discharge protection
- Floor covering: Cargo area floor, painted
- Diesel particulate filter, maintenance-free (incl. SCR catalyst with AdBlue)
- Third brake light
- Electronic Stability Program (ESP Plus)
- Electric front windows
- Cruise control (steering wheel remote control)
- Rear wing doors, asymmetrically split, sheet metal, 180° opening angle
- Headrests (2), front, height adjustable
- Steering column, adjustable for reach and height
- Upholstery: Cloth
- Wheels: Tire repair kit (with tire sealant and 12-volt compressor (without jack))
- Wheels: Steel wheels 6.5 J x 16 (tires 205/60 R16 XL 96H - wheel hub cover)
- Side impact protection
- Side protection strips (in black)
- Seats: Single passenger seat, fixed
- 12-volt power outlet in the center console
- Daytime running light
- Partition wall, closed
- Doors: Sliding door, passenger side, sheet metal
- Immobiliser
- Central locking with remote control
- Storage compartments (Edition) (Storage compartment in the instrument panel, driver's side, closed - Storage compartment in the center console, front - Storage shelf above the windshield, open - Storage compartment in the front doors, suitable for 1.5-liter beverage bottles - Glove compartment, closed - Storage compartment on the dashboard, passenger side, closed)
- Exterior mirror housings in body color
- Hill Start Assist
- On-board computer
- Tachometer
- Three-point seat belts on all seats (belt force limiter, front - double belt tensioners, front - warning tone and light for unfastened seat belts, front)
- Speed limiter
- Transmission: 5-speed transmission
- Air conditioning, front, with particle and odor filter (recirculation mode, manual - glove compartment, split)
- Paint finish: Solid color paint
- Rear parking pilot
- Radio BT with Graphic Info Display (Audio: - Bluetooth audio streaming Telephone: - Hands-free calling via Bluetooth interface - Display of phonebook and call lists - Up to 5 mobile phones can be paired General: - Use of voice control of the paired smartphone possible (e.g. Siri, Google voice control) - USB interface - 4 speakers)
- Speed-sensitive power steering
- Seats: Driver's seat adjustable in 6 ways: length, height and backrest angle (with lumbar support and armrest)
- Traction control with engine and brake intervention (TC Plus)
- Lashing eyes (6) in the cargo area
- Heat-insulating glazing, tinted
- Central locking: Ignition keys (2), one of which is foldable

Extra equipment

- All-season tyres
- Package: Grip & Go (IntelliGrip (Adaptive traction system with 5 selectable modes): - ESP off - ESP standard - Snow mode - Mud mode - Sand mode - Hill descent control - Metal underbody protection - 215/65 R 16 SL 98H off-road tires - Raised suspension)
- Seats: Double passenger seat
- FlexCargo partition wall with window (with pass-through function below the passenger double seat including protective bag for the load - interior rearview mirror, manually dimmable)
- Rear wing doors, asymmetrically split, glazed, 180° opening angle (rear window wiper - rear window heater)
- Package: Professional (foldable double passenger seat with storage table, sliding on the backrest of the middle seat of the double passenger seat - seat belt warning, single passenger seat - electric parking brake - FlexCargo partition, without window, with pass-through function under the double passenger seat - wooden floor in the load compartment)

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. Lifting equipment and/or a pit were available for examining the vehicle.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.

Value reducing factors

No.	Component group	Description
1	Screen cleaning	Cover washing container - Broken / torn - Replace
2	Misc.	Main inspection - Due - Replace
3	Sill - left side	Sill - Paint defect - Smart repair
4	Rear bumper	Bumper with Parktronic (inkl. PDC) - Malposition - Replace

Missing parts

Description
Equipment - Tirefit complete

Accident damages

No.	Accident
1	Side - left
2	Side right

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
  (Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
  (Functional testing of driver assistance systems is not included in the scope of services!)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

Non-repaired previous damages were found at the vehicle. The necessary repair costs are listed in the expert report or if necessary, are listed in detail in a separately enclosed repair cost calculation.

Comments

Die beigefügte Reparaturkostenkalkulation wurde nach bestem Wissen und Gewissen unter eingeschränkten Besichtigungsbedingung im demontagefreien Zustand erstellt. Es können aufgrund verdeckter Beschädigung erhebliche Mehrkosten und somit Abweichung der für den Unfall ausgewiesenen Reparaturkosten nicht ausgeschlossen werden.

Bei den Unfällen wurden nur Teil Instandsetzung berechnet.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)



Figure 5: Interior - front



Figure 6: Interior - rear




Figure 7: Instrument cluster



Figure 8: Instrument panel

Figure 9: Interior 360° view (Online Link)



Figure 10: Cargo area




Figure 11: VIN



Figure 12: Mounted tyres




Figure 13: Documents




Figure 14: Documents



Figure 15: Documents



Figure 16: Misc.



Figure 17: Misc.



Figure 18: Misc.



Figure 19: Misc.



Figure 20: Misc.



Figure 21: Misc.



Figure 22: Misc.



Figure 23: Misc.




Figure 24: Misc.



Figure 25: Misc.




Figure 26: Misc.




Figure 27: Misc.



Damage 1: Screen cleaning: Cover washing container - Broken / torn - Replace



Damage 1: Screen cleaning: Cover washing container - Broken / torn - Replace



Damage 2: Misc.: Main inspection - Due - Replace



Damage 3: Sill - left side: Sill - Paint defect - Smart repair



Damage 3: Sill - left side: Sill - Paint defect - Smart repair



Damage 4: Rear bumper: Bumper with Parktronic (inkl. PDC) - Malposition - Replace



Damage 4: Rear bumper: Bumper with Parktronic (inkl. PDC) - Malposition - Replace



Damage 4: Rear bumper: Bumper with Parktronic (inkl. PDC) - Malposition - Replace




Damage 4: Rear bumper: Bumper with Parktronic (inkl. PDC) - Malposition - Replace



Missing part 1: Equipment: Tirefit complete - Missing - Replace



Accident 1: Side - left



Accident 1: Side - left



Accident 1: Side - left



Accident 1: Side - left



Accident 1: Side - left



Accident 1: Side - left



Accident 1: Side - left



Accident 2: Side right



Accident 2: Side right




Accident 2: Side right




Accident 2: Side right



Accident 2: Side right



Accident 2: Side right



Accident 2: Side right



Accident 2: Side right



Accident 2: Side right



Accident 2: Side right



Accident 2: Side right



Accident 2: Side right



Accident 2: Side right



Accident 2: Side right



Accident 2: Side right



Accident 2: Side right



Accident 2: Side right



Accident 2: Side right



Accident 2: Side right



Accident 2: Side right