BMW X3

Vehicle information


Make:	**BMW**	License:	**2DPS018**
Gearbox:		Body color:	
Model:	**X3**	VIN:	**WBA61DP0909R94404**
Fuel type:		Power:	**120 kW**
Version:	**2.0 XDRIVE30E (120KW) AUTO**	First registration	**17/05/2023**
Mileage:	**111653 km**	N° of doors:	

Damage summary


Front	1
Interior	1
Right	1
Roof & others	1

Commercial pictures


































Options according to the inspector

GPS	**Yes**


Damages

Bodywork
Damaged
Acceptable
Roof & others












Engine insulation
Hole
Replace
Front






Interior
Damaged
Acceptable
Interior






Wing RR
Dent(s)
Paintless dent repair
Right





Tyres

Front Left
Summer
Aluminium
225/60/18/104/W
Pirelli
6.0 mm
Front Right
Summer
Aluminium
225/60/18/104/W
Pirelli
6.0 mm
Rear Left
Summer
Aluminium
225/60/18/104/W
Pirelli
6.0 mm
Rear Right
Summer
Aluminium
225/60/18/104/W
Pirelli
6.0 mm

Checks

Battery level	**40**	Category	**Passenger Car**
Certificate of Conformity	**Yes**	Compressor	**N/A**
Maintenance	**OK**	Maintenance	**+ 26000 km**
Number of charging cables (normal)	**2**	Number of charging cables (rapid charge)	**1**
Number of keys total	**2**	Registration Certificate Car (BE)	**Yes**
Registration Certificate Home (BE)	**No**	Repair kit	**N/A**
Reset to factory settings	**Yes, vehicle is reset to factory settings**	Runflat	**N/A**
Statutory inspection	**OK**	Statutory inspection	**17/05/2027**
Type of Maintenance book	**Digital maintenance**		

Information on the content and the scope of the inspection report:

- The assessment is based on the sales standards specified by the customer.
- Acceptable usage damages according to the sales standards are not always documented in this status report.
- The specified repair methods and/or resulting repair times have been determined, taking into account modern industrial repair methods.
- The purchasing dealer should assess individual repair costs.
- The inspection was carried out in a non-disassembly condition. Macadam cannot be held responsible for any missing information. For further information, please contact the seller.