TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
ARS Altmann AG Automobillogistik
Römerstraße 3
64560 Riedstadt

Expertise

Protocol number: 48459409
Order No. / Reference: 27192785
Inspection date: 2 Nov 2026

Manufacturer: CUPRA	Model: Leon Sportstourer 1.4 e-Hybrid (150 kW System)
VIN: VSSZZZKL9PR054393	





Vehicle details

Manufacturer / Type / Model / Equipment	
CUPRA Leon Sportstourer 1.4 e-Hybrid (150 kW System)	
Vehicle Identification number	VSSZZZKL9PR054393
Mileage (Read)	64,780 km
First registration	4 Jul 2023
Number of holders	1
Fuel type	Hybr.B/E ext.aufl
Engine displacement / Cylinder	1,395 ccm / 4
Power	110 kW
Gearbox / Number of gears	Automatic / 6
Type of drive	Front drive
Type of vehicle	Station wagon
Colour / colour code	Magnetic Grau Metallic
Doors / Seats	5 / 5
Upholstery type	Cloth
Colour of upholstery	Black

Vehicle details

Maintenance booklet / proof	digital evidence / incomplete	**Next maintenance in**	-300 km
Last service on / at	01/2026 at 53,557 km		
Key is / should be	2 / 2	**FZG documents**	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	GQ529096
Previous damage / Accident	Detectable	**Repainting**	None detectable
Inspection conditions	sufficient	**Lifting equipment / pit**	No
Test drive	Not performed	**Engine function test**	Performed
Manufacturer key number/ type code number	7593 / ART 00046		
Emission standard	EURO6	**fine dust sticker**	
Permitted total weight	2,090 kg	**Empty weight**	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	225/40 R18 92Y	Summer tyres on Light alloy	Dunlop	4mm / 4mm
2)	225/40 R18 92Y	Summer tyres on Light alloy	Bridgestone	4mm / 4mm

Additional tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	225/40 R18 92W	Winter tyres on Light alloy	Continental	4mm / 4mm
2)	225/40 R18 92W	Winter tyres on Light alloy	Continental	6mm / 6mm

Replacement

Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
	Tirefit	Expiration date 03/2027		

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

Equipment

Standard equipment

- Storage compartment in the doors
- Airbag: Airbag for driver and front passenger
- Electrically adjustable, folding and heated exterior mirrors
- third brake light
- Roof rails in Glossy Black
- Tachometer
- Electronic parking brake including auto-hold function
- Electric window regulator with anti-pinch protection and one-touch function
- Speed limiter
- Transmission: 6-speed DSG
- Heated rear window
- ISOFIX child seat restraint system, in the 2nd row left and right
- Headrests, 2 front
- Headrests, 3 rear
- Steering wheel: CUPRA sport multifunction steering wheel with shift paddles
- Fatigue detection
- Emergency call service
- Package: Light and Sight Package
- Radio: Digital radio reception DAB+
- Tire pressure monitoring system
- Wheels: Tyre fit
- Servotronic
- Seat belts - three-point automatic, front and rear
- Seats: Driver's seat with height adjustment
- Seats: Lumbar support for driver/passenger seat
- Seats: Rear seat backrest asymmetrically split and foldable
- Sun visor on driver and passenger side with make-up mirror and lighting
- 12V socket in the trunk
- Ultrasonic parking aid, rear
- Variable luggage compartment floor
- Lashing eyes in the luggage compartment
- Electronic immobilizer
- Central locking with remote control
- Adaptive chassis control DCC
- Airbag: Passenger airbag deactivation
- Exterior mirror caps painted in "Dark Aluminium"
- CURA CONNECT
- Electronic differential lock (XDS) for front axle
- Drive Profile CUPRA
- Electronic Stability Control (ESC)
- Luggage compartment lighting
- luggage compartment roller blind
- Cruise control system (CCS)
- Illuminated glove compartment
- rear window wiper
- Keyless Go (engine start/stop button)
- Climatronic air conditioning with 3-zone temperature control
- Trim strips on the side windows (outside) in Glossy Black
- Rear center armrest with pass-through option
- front center armrest
- Navigation system
- Otto particulate filter
- Package: Full LED package
- Radio accessories: 2 USB-C ports front / 2 rear (charging function)
- Side windows from the 2nd row of seats and rear window are dark tinted.
- Seats: Passenger seat with height adjustment
- Seats: Remote release for folding down the rear seat backrest into the boot
- Seats: Front sports bucket seats in "Sharp Textil"
- Smart Ambient Light
- Lane departure warning system
- Start-stop system and recuperation
- Illuminated door sill trims, front
- Front Assist area monitoring system with City Emergency Braking function
- Virtual Cockpit
- thermal insulation glazing

Extra equipment

- Airbag: Rear side airbag and driver's side knee airbag
- Mode 3 Type 2 charging cable, 16 A
- Package: Driving Assistance Package XL for navigation system (Adaptive Cruise Control up to 210 km/h with Predictive Cruise Control PCC - High Beam Assist - Side Assist incl. Blind Spot Assist - Exit Assist & Exit Warning - Travel Assist - Emergency Assist - Lane Assist Plus - Traffic Sign Recognition)
- Anti-theft alarm system including interior monitoring, backup horn and tow-away protection
- Package: Winter Package (heated front seats - heated steering wheel)
- Radio accessories: Wireless Full Link Connectivity (Android Auto - Apple CarPlay)
- 230V power outlet in the luggage compartment
- Vision Plus (reversing camera - parking assist with front parking aid)

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. No lifting equipment or pit was available for inspecting the vehicle. Therefore, inspection of the vehicle's underside was only possible to a limited extent.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.

Value reducing factors

No.	Component group	Description
1	Wheel / tyres	Alloy rim - rear right side - Scratch(es) - Loss in value
2	Misc.	Inspection / maintenance - Due - Perform
3	Front bumper	Front bumper - Scratch(es) - Paint

Wear and tear

No.	Component group	Description
1	Rear bumper	Rear bumper - Scratch(es) - No deduction
2	Bonnet	Bonnet - Stone chips - No deduction
3	Interior	Interior - Scratch(es) - No deduction
4	Sill - left side	Sill - Scratch(es) - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.

Previous damages

No.	Previous damage	Extent of damage (Net)
1	Front, Provided by user / customer, from 4 Feb 2025	2.419,75 €

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
  (Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
  (Functional testing of driver assistance systems is not included in the scope of services!)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

According to available information previous damages were repaired at the vehicle. Traces of repairs, which allow conclusions about the area of repair, were not recognizable during the inspection.

Comments

- Fahrzeugmodellbezeichnung laut Rechnung: "CUPRA Leon Sportstourer 1.4 e-Hybrid (150 kW System)".

- Die Unterbodenbesichtigung war nur ebenerdig & eingeschränkt möglich. Mehrkosten sind möglich.

- Winterradsatz ist kein Bestandteil des Auslieferumfangs.

TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
ARS Altmann AG Automobillogistik
Römerstraße 3
64560 Riedstadt



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)




Figure 5: Interior - front




Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel



Figure 9: Cargo area




Figure 10: VIN



Figure 11: Mounted tyres



Figure 12: Documents



Figure 13: Documents



Figure 14: Additional tyres



Figure 15: Navigation



Figure 16: Misc.



Figure 17: Misc.



Figure 18: Misc.



Figure 19: Misc.




Figure 20: Misc.



Figure 21: Misc.



Figure 22: Misc.



Figure 23: Misc.



Figure 24: Misc.



Figure 25: Misc.



Figure 26: Misc.



Figure 27: Misc.




Figure 28: Misc.



Figure 29: Misc.



Figure 30: Misc.



Figure 31: Misc.



Figure 32: Misc.



Figure 33: Misc.




Damage 1: Wheel / tyres: Alloy rim - rear right side - Scratch(es) - Loss in value




Damage 1: Wheel / tyres: Alloy rim - rear right side - Scratch(es) - Loss in value



Damage 2: Misc.: Inspection / maintenance - Due - Perform




Damage 3: Front bumper: Front bumper - Scratch(es) - Paint



Damage 3: Front bumper: Front bumper - Scratch(es) - Paint



Damage 3: Front bumper: Front bumper - Scratch(es) - Paint



Damage 3: Front bumper: Front bumper - Scratch(es) - Paint