MACADAM










Volkswagen Crafter: VRK56P

Vinnumber:	**WV1ZZZSY0P9004436**	Versionname:	**Crafter 35 2.0 TDI 103kW FWD GB L3H3 automaat**
First Registrationdate:	**24/08/2022**	Fiscalpower:	
Expertise Mileage:	**246422**	Power Kw:	**103**
Bodytype:		Body colour	**Candywit**
Gearbox:	**Automatic**	Paint type	**Opaque**
Transmission:		Type of rims (mounted)	**Steel**
Fueltype:	**Diesel**	Parking lot	**1191**
Number of seats	**2**		
Type of rims (mounted)	**Steel**		
Maintenance needed	**No**		

Options

Number of keys total	**2**	Rear parking sensors	
Manual climate control		Sliding door right-side	
Radio multimedia		Rear view camera	

Tyres

Location	Position	Measures	Depth	Make	Type
Front	Left	205 / 75 / 16 / 118 / R / Steel	6,8 mm	Continental	All season
	Right	205 / 75 / 16 / 118 / R / Steel	6,8 mm	Continental	All season
Rear	Left	205 / 75 / 16 / 118 / R / Steel	7,2 mm	Continental	All season
	Right	205 / 75 / 16 / 118 / R / Steel	8,4 mm	Continental	All season

Assistance equipment

Seat cover FL, Worn, Replace




Door FL, Dent(s) and scratch(es), Repair and paint (complete)







Side wall RL, Dent(s), Repair and paint (complete)





Windscreen, Stone chip(s), Windscreen repair





Bumper F, Dent(s) and scratch(es), Replace




Side wall RR, Dent(s), Repair and paint (complete)





Side bar R, Deformed / Strained, Replace




Outer sill R, Scratch(es), Repair and paint (complete)




Sliding door R, Dent(s), Repair and paint (complete)





Door FR, Dent(s) and scratch(es), Repair and paint (complete)







Outer door handle FR, Scratch(es), Replace




Outside rear-view mirror housing R, Scratch(es), Replace




Wheel aperture RL, Dent(s) and scratch(es), Repair and paint (complete)




Wheel aperture RR, Dent(s) and scratch(es), Repair and paint (complete)




Side wall panel FR, Crack, Replace




Side wall panel RR, Crack, Replace





Side wall panel FL, Broken, Replace




Bumper corner RL, Scratch(es), Replace





Bumper corner RR, Hole, Replace






Bodywork, Chemical polution, Polish






Onderhoudshistorie van: WV1ZZZSY0P9004436

ALPHABET

Kenteken	VRK56P
Merk Model	Volkswagen Crafter 35 2.0 TDI 103kW FWD GB L3H3 automaat
Brandstofsoort	Diesel
Datum deel1	8/24/22

Datum reparatie	Kilometerstand	Reparatie omschrijving
10/8/26	244,133	Vervanging band
9/21/26	241,667	Distributie riem
9/21/26	241,667	Onderhoudsbeurt
8/19/26	238,970	Vervanging band
7/17/26	232,386	Sleutelbatterij
6/12/26	229,893	APK
6/12/26	229,893	Remblokken achterzijde
6/12/26	229,893	Vervanging band
4/8/26	222,737	Gloeistift
12/2/25	207,397	Onderhoudsbeurt
12/2/25	207,397	Ruitenwisserblad(en) voorzijde
12/2/25	207,397	Vervanging band
9/2/25	199,999	Airco reinigen
9/2/25	199,999	Brandstoffilter
9/2/25	199,999	Brandstoftoevoeging
9/2/25	199,999	Distributie riem
9/2/25	199,999	Luchtfilter
9/2/25	199,999	Multiriem inclusief spanner
9/2/25	199,999	Onderhoudsbeurt
9/2/25	199,999	Remvloeistof
9/2/25	199,999	Waterpomp
8/13/25	192,320	APK
8/13/25	192,320	Onderhoudsbeurt
8/13/25	192,320	Remblokken voorzijde
6/20/25	184,716	Vervanging band
4/10/25	173,632	Aandrijfashoes
4/10/25	173,632	Onderhoudsbeurt
4/10/25	173,632	Remblokken achterzijde
4/10/25	173,632	Ruitenwisserblad(en) voorzijde
3/17/25	169,008	Vervanging band
10/28/24	144,838	Distributie riem
10/28/24	144,838	Onderhoudsbeurt
10/28/24	144,838	Remblokken voorzijde
10/28/24	144,838	Riem/ multiriem
10/28/24	144,838	Vervanging band
7/29/24	128,815	Brandstoftoevoeging
7/29/24	128,815	Onderhoudsbeurt
7/29/24	128,815	Ruitenwisserblad(en) voorzijde
6/17/24	121,864	Remschijf + blokken achter
6/17/24	121,864	Vervanging band

Datum reparatie	Kilometerstand	Reparatie omschrijving
1/29/24	93,258	Aandrijfashoes
1/29/24	93,258	Brandstoffilter
1/29/24	93,258	Brandstoftoevoeging
1/29/24	93,258	Distributie riem
1/29/24	93,258	Luchtfilter
1/29/24	93,258	Onderhoudsbeurt
1/29/24	93,258	Remschijf + blokken voor
1/29/24	93,258	Remvloeistof
1/29/24	93,258	Vervanging band
11/6/23	75,075	Vervanging band
9/5/23	63,311	Aandrijfashoes
9/5/23	63,311	Remblokken achterzijde
8/7/23	56,733	Distributie riem
8/7/23	56,733	Onderhoudsbeurt
5/8/23	41,112	Distributie riem
5/8/23	41,112	Onderhoudsbeurt
5/8/23	41,112	Remblokken voorzijde
2/9/23	26,516	Vervanging band
1/30/23	24,885	Onderhoudsbeurt