TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Hartmann Compound Professionals
Wachau 2
89584 Ehingen

Expertise

Protocol number: 48226247
Order No. / Reference: 27037152
Inspection date: 19 Oct 2026

Manufacturer: Audi	Model: A4 Avant 35 TDI S tronic
VIN: WAUZZZF48PA074411	





Vehicle details

Manufacturer / Type / Model / Equipment	
Audi A4 Avant 35 TDI S tronic	
Vehicle Identification number	WAUZZZF48PA074411
Mileage (Read)	106,125 km
First registration	17 Jul 2023
Number of holders	1
Next periodical technical inspection	12/2025
(Report on hand)	
Fuel type	Hybrid Diesel / E
Engine displacement / Cylinder	1,968 ccm / 4
Power	120 kW
Gearbox / Number of gears	Automatic / 7
Type of drive	Front drive
Type of vehicle	Station wagon
Colour / colour code	Mythosschwarz Metallic (Y9T)
Doors / Seats	5 / 5
Upholstery type	Leather
Colour of upholstery	Black-Anthracite

Vehicle details

Maintenance booklet / proof	digital evidence / incomplete	**Next maintenance in**	3,500 km
Last service on / at	01/2025 at 51,138 km		
Key is / should be	2 / 2	**FZG documents**	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	GV202550
Previous damage / Accident	Detectable	**Repainting**	Detectable
Inspection conditions	Conditional: Light/moisture/dirt	**Lifting equipment / pit**	yes
Test drive	Not performed	**Engine function test**	Performed
Manufacturer key number/ type code number	0588 / BPK 01147		
Emission standard	EURO6	**fine dust sticker**	
Permitted total weight	2,165 kg	**Empty weight**	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	225/50 R17 94Y	Summer tyres on Light alloy	Hankook	5mm / 4mm
2)	225/50 R17 94Y	Summer tyres on Light alloy	Fulda	6mm / 6mm

Additional tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	225/50 R17 98H	Winter tyres (Without wheel rim)	Fulda	7mm / 7mm

Replacement

Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
	Tirefit	Expiration date 05/2029		

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

Equipment

Standard equipment

- AdBlue tank (12 liters)
- Airbag: Front side airbags and head airbag system
- Anti-lock braking system (ABS)
- Audi connect emergency call & service with Audi connect Remote & Control
- Exterior mirror housings in body color
- third brake light, raised
- Black roof rails
- Diesel particulate filter (DPF)
- Parking assistance plus
- Electromechanical parking brake
- Electronic Stability Control (ESC)
- Chassis: Standard chassis
- Window channel strips in black (rubber)
- front and rear floor mats
- Transmission: S tronic 7-speed
- Top speed limited to 210 km/h
- Interior mirror dimming
- Child lock
- Automatic air conditioning
- boot floor mat
- Loading floor
- LED taillights
- Steering column, manually adjustable in height and axis
- Light/rain sensor
- front center armrest
- Wheel: Alloy wheels, 5-arm
- Radio: MMI Radio plus
- Tire repair kit
- Electromechanical power steering
- Seats: Standard front seats
- Seats: Front seats manually adjustable
- Start-stop system
- Glazing: Windscreen in heat-insulating and acoustic glazing
- Airbag for driver and front passenger
- Accent areas matte black
- Traction control (ASR)
- Audi pre sense city
- Electrically adjustable and heated exterior mirrors
- Vehicle tool kit
- Fabric headliner
- Decorative inlays diamond lacquer silver grey
- Tachometer
- Door sill trims with aluminum inlay at the front
- Electronic Differential Lock (EDS)
- Driver information system with color display
- electric window regulators
- Remote key, without SafeLock
- Cruise control system with speed limiter
- rear window wiper
- Interior lighting
- Camera-based traffic sign recognition
- ISOFIX child seat attachment and Top Tether for the outer rear seats
- Headrests (5)
- Manual cargo cover
- Steering wheel: Leather steering wheel in 3-spoke design with multifunction
- Mild hybrid
- Non-smoking version
- Wheel: Tires optimized for rolling resistance, speed-limited
- Tire pressure monitoring system
- Headlights using LED technology
- Fabric seat covers Index
- Seats: Rear seat backrest foldable
- Lane Departure Warning
- First aid kit with warning triangle
- Electronic immobilizer
- Central locking "Keyless-Go" without deadbolt

Extra equipment

- AdBlue tank (24 liters) (larger tank for AdBlue solution to reduce nitrogen oxides in the exhaust gas using an SCR system)
- Audi connect Navigation & Infotainment (Online Points of Interest - Online Traffic Information Plus - Hazard Information - Weather Information - Wi-Fi Hotspot - Online News - Navigation with Google Satellite Maps - Online Search for Navigation Destinations - Online Voice Input - Highly Detailed 3D City Display - On-Street Parking - Online Radio - Hybrid Radio - User Profiles - Amazon Alexa Integration - Online Media Streaming - myAudi Navi. - Online Traffic Sign Information. - HoloRide Interface)
- Electrically adjustable, heated and folding exterior mirrors, automatically dimming on both sides (including curb view function for passenger-side exterior mirror with integrated LED turn signal, including heated windshield washer nozzles; the curb view function folds the passenger-side mirror down when reverse gear is engaged, giving the driver a better view of the curb edge)
- Hold assist (holds the vehicle indefinitely after stopping on typical road inclines and declines. The system is activated by pressing a button and allows the driver to start off comfortably.)
- Comfort center armrest at the front (adjustable in tilt and longitudinally sliding or completely foldable)
- Fuel tank with increased filling volume (54 l)
- Paint finish: Metallic
- Business package (MMI Navigation plus with MMI touch - Audi phone box - 3-spoke leather steering wheel with multifunction plus - Heated front seats - Frameless, automatically dimming interior mirror - Electrically adjustable, heated and folding exterior mirrors, automatically dimming on both sides - High-beam assistant - Manual sunshade for rear door windows)
- Wheel: Deselect low rolling resistance tires, remove speed limiter (17 inch) (Tires 225/50 R 17 94Y)
- Wheel: Audi new car tire warranty (36-month term from vehicle handover to the first customer)
- Wheel: Alloy wheels, 10-spoke crystal (size 7.5J x 17 with tires 225/50 R17)
- Seat covers in leather/artificial leather mono.pur 550 combination in conjunction with sport seats (for sport seats: - center section of the front seats and outer rear seats, driver's side bolster in the entry area in leather - side bolsters, headrests, center armrest and middle rear seat in artificial leather mono.pur 550 for sport seats with seat ventilation: - center section of the front seats, non-ventilated center section of the outer rear seats in perforated leather and driver's entry bolster in leather - side bolsters, middle rear seat and headrests in artificial leather mono.pur 550)
- Glazing: Sun protection glazing, tinted (rear window, rear door and side windows tinted)
- Mechanically swiveling towbar (Conveniently locks and unlocks via a release mechanism. - Mechanically swiveling ball head with electric release, controlled by a button in the luggage compartment - Ball shaft and head made of forged steel - Trailer stabilization via the electronic stability control (ESC) - Swiveling system socket allows continuous operation of electrical devices in the trailer or caravan, even while driving)
- Audi virtual cockpit plus (Innovative, fully digital instrument cluster with 12.3-inch display, full HD resolution with additional graphic display options: Classic, Sport and Dynamic design - For flexible and needs-based display of the respective information according to the driver's needs: speed/RPM, map display, Audi connect services, radio/media information, etc. - VIEW button in the multifunction steering wheel)
- Deletion of model designation and performance/technology lettering
- Electrically operated tailgate (The tailgate can be opened electrically by pressing the button on the vehicle key, in the driver's door, or the soft-touch button on the tailgate handle. Closing the tailgate is just as easy and convenient: simply press the button on the inside of the tailgate, the button in the driver's door, or the button on the vehicle key. A soft-close mechanism makes manual closing easier when necessary.)
- Steering wheel: Sport contour leather steering wheel in 3-spoke design, flattened at the bottom with multifunction plus (with more contoured steering wheel rim; adjustable in height and distance; with 12 multifunction buttons for convenient operation of the available infotainment features with shift paddles for manual gear changes in automatic transmissions)
- Package: Ambient Lighting Package (in addition to the interior lighting: - approach lighting in the exterior door handles - entry lights on the underside of the front doors - illuminated front cupholders - front footwell lighting - illuminated interior door handles - ambient door lighting - ambient lighting in the front center console)
- Radio accessories: Audi sound system (10 speakers including center speaker and subwoofer - 6-channel amplifier - total output of 180 watts)
- Seats: 4-way lumbar support (electrically adjustable, horizontally and vertically)
- Front seat heating (heats seat and backrest center panels; with leather upholstery, sport seats and S sport seats also seat side bolsters - individually adjustable in multiple stages for driver and front passenger side via the climate control unit)
- Front sports seats (with manual adjustment of seat height, seat longitudinal position, seat tilt, backrest tilt, headrest and belt height; with pronounced seat side bolsters for better lateral support in curves, extendable thigh support)

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	A proper visual inspection of the paintwork and bodywork was only possible to a limited extent due to insufficient lighting conditions/dampness or dirt. Lifting equipment and/or a pit were available for examining the vehicle.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.

Value reducing factors

No.	Component group	Description
1	Vehicle glazing	Windscreen with lane departure assistant - Stone chips - Smart repair
2	Side panel - rear left side	Side panel (Kante sichtbar) - Unprofessionally repaired - Polishing / interior cleaning
3	Front bumper	Front bumper - Scratch(es) - Smart repair
4	Rear bumper	Rear bumper (schleifen + polieren) - Dent / paintcoat damage - Smart repair
5	Misc.	Main inspection - Due - Perform
6	Body	Underbody panelling - Holes - Replace
7	Sill - left side	Sill - Deformed - Repair and paint

Wear and tear

No.	Component group	Description
1	Bonnet	Bonnet - Stone chips - No deduction
2	Door - rear right side	Door - dent(s) - No deduction
3	Side panel - rear left side	Sill - dent(s) - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.

Previous damages

No.	Previous damage	Extent of damage (Net)
1	Rear, Side - left, Provided by user / customer, from 4 Oct 2025	1.996,43 €
2	Rear, Side right, Provided by user / customer, from 18 Feb 2024	7.035,65 €

Repainting

No.	Repainting
1	Boot lid / rear door, Mudguard - right side, Side panel - rear left side, Door - rear right side, Professionally carried out, Invoice of repair done Non-existent
2	Side panel - rear right side, Unprofessionally carried out, Invoice of repair done Non-existent

Paint coat thickness measurement

Roof	117 µm	Roof rail - left side	119 µm
Roof rail - right side	135 µm	Boot lid / rear door	206 µm
Mudguard - left side	110 µm	Mudguard - right side	157 µm
Bonnet	121 µm	Side panel - rear left side	161 µm
Side panel - rear right side	214 µm	Door - rear left side	114 µm
Door - rear right side	203 µm	Door - front left side	122 µm
Door - front right side	123 µm		

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
  (Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
  (Functional testing of driver assistance systems is not included in the scope of services!)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

According to available information previous damages were repaired at the vehicle. Traces of repairs, which allow conclusions about the area of repair, were not recognizable during the inspection.

Comments

- Winterreifen sind kein Bestandteil des Auslieferungsumfangs.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)




Figure 5: Interior - front




Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel



Figure 9: Cargo area




Figure 10: VIN



Figure 11: Mounted tyres




Figure 12: Documents




Figure 13: Documents




Figure 14: Documents




Figure 15: Navigation



Figure 16: Misc.




Figure 17: Misc.



Figure 18: Misc.



Figure 19: Misc.




Figure 20: Misc.



Figure 21: Misc.




Figure 22: Misc.



Figure 23: Misc.



Figure 24: Misc.




Figure 25: Misc.



Figure 26: Misc.



Figure 27: Misc.



Figure 28: Misc.



Figure 29: Misc.



Figure 30: Misc.



Figure 31: Misc.



Figure 32: Misc.



Figure 33: Misc.



Figure 34: Misc.



Figure 35: Misc.





Figure 36: Misc.




Figure 37: Misc.



Damage 1: Vehicle glazing: Windscreen with lane departure assistant - Stone chips - Smart repair




Damage 1: Vehicle glazing: Windscreen with lane departure assistant - Stone chips - Smart repair




Damage 2: Side panel - rear left side: Side panel (Kante sichtbar) - Unprofessionally repaired - Polishing / interior cleaning



Damage 2: Side panel - rear left side: Side panel (Kante sichtbar) - Unprofessionally repaired - Polishing / interior cleaning




Damage 2: Side panel - rear left side: Side panel (Kante sichtbar) - Unprofessionally repaired - Polishing / interior cleaning




Damage 3: Front bumper: Front bumper - Scratch(es) - Smart repair



Damage 3: Front bumper: Front bumper - Scratch(es) - Smart repair



Damage 4: Rear bumper: Rear bumper (schleifen + polieren) - Dent / paintcoat damage - Smart repair



Damage 4: Rear bumper: Rear bumper (schleifen + polieren) - Dent / paintcoat damage - Smart repair



Damage 4: Rear bumper: Rear bumper (schleifen + polieren) - Dent / paintcoat damage - Smart repair




Damage 4: Rear bumper: Rear bumper (schleifen + polieren) - Dent / paintcoat damage - Smart repair




Damage 4: Rear bumper: Rear bumper (schleifen + polieren) - Dent / paintcoat damage - Smart repair



Damage 4: Rear bumper: Rear bumper (schleifen + polieren) - Dent / paintcoat damage - Smart repair



Damage 4: Rear bumper: Rear bumper (schleifen + polieren) - Dent / paintcoat damage - Smart repair




Damage 5: Misc.: Main inspection - Due - Perform




Damage 6: Body: Underbody panelling - Holes - Replace




Damage 6: Body: Underbody panelling - Holes - Replace



Damage 7: Sill - left side: Sill - Deformed - Repair and paint



Damage 7: Sill - left side: Sill - Deformed - Repair and paint




Damage 7: Sill - left side: Sill - Deformed - Repair and paint



Repainting 1: Boot lid / rear door, Mudguard - right side, Side panel - rear left side, Door - rear right side



Repainting 1: Boot lid / rear door, Mudguard - right side, Side panel - rear left side, Door - rear right side



Repainting 1: Boot lid / rear door, Mudguard - right side, Side panel - rear left side, Door - rear right side




Repainting 1: Boot lid / rear door, Mudguard - right side, Side panel - rear left side, Door - rear right side



Repainting 1: Boot lid / rear door, Mudguard - right side, Side panel - rear left side, Door - rear right side



Repainting 1: Boot lid / rear door, Mudguard - right side, Side panel - rear left side, Door - rear right side



Repainting 1: Boot lid / rear door, Mudguard - right side, Side panel - rear left side, Door - rear right side



Repainting 1: Boot lid / rear door, Mudguard - right side, Side panel - rear left side, Door - rear right side



Repainting 2: Side panel - rear right side



Repainting 2: Side panel - rear right side