TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Hartmann Fleet Professionals GmbH
Leerenstraße 25
29683 Bad Fallingbostel

Expertise

Protocol number: 48562377
Order No. / Reference: 27234316
Inspection date: 6 Nov 2026

Manufacturer: Volkswagen	Model: Caddy 2.0 TDI BMT (7-Si.) Caddy Maxi
VIN: WV2ZZZSKZNX051602	





Vehicle details

Manufacturer / Type / Model / Equipment	
Volkswagen Caddy 2.0 TDI BMT (7-Si.) Caddy Maxi	
Vehicle Identification number	WV2ZZZSKZNX051602
Mileage (Read)	116,828 km
First registration	5 May 2022
Number of holders	1
Fuel type	Diesel
Engine displacement / Cylinder	1,968 ccm / 4
Power	90 kW
Gearbox / Number of gears	Manual / 6
Type of drive	Front drive
Type of vehicle	Station wagon
Colour / colour code	Candy White (B9A)
Doors / Seats	5 / 5
Upholstery type	Cloth
Colour of upholstery	Black-Grey

Vehicle details

Maintenance booklet / proof	Non-existent	**Next maintenance in**	2,800 km
Key is / should be	2 / 2	**FZG documents**	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	GJ136431
Previous damage / Accident	None detectable	**Repainting**	None detectable
Inspection conditions	sufficient	**Lifting equipment / pit**	No
Test drive	Not performed	**Engine function test**	Performed
Manufacturer key number/ type code number	0603 / CLI 00573		
Emission standard	EURO6	**fine dust sticker**	
Permitted total weight	2,450 kg	**Empty weight**	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	215/55 R17 98H	All-season tyres on Steel rim with wheel cover	Bridgestone	3mm / 3mm
2)	215/55 R17 98W	All-season tyres on Steel rim with wheel cover	Firestone	1mm / 0mm

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

Equipment

Standard equipment

- Storage compartments: Storage tray on the headliner with 2 roof grab handles in the driver's cab
- Airbag: Side and head airbags for driver and front passenger (head airbags for the outer rear seats - center airbag in the front)
- Reinforced battery (70 Ah/ 420 A)
- Operating voltage 12 V
- Brake booster
- third brake light
- Roof rail/roof rack preparation
- Electronic parking brake including auto-hold function
- Automatic headlight control with daytime running lights
- Windows: Heated rear window
- Window: Side window in the passenger/cargo compartment, rear left, permanently installed
- Window: Side window in the passenger/cargo compartment, front left, permanently installed
- Windows: Laminated glass front pane in heat-insulating glazing
- electric window regulators
- Cruise control system including speed limiter
- Halogen dual headlights-H7
- Tailgate with window cutout
- Interior lighting: in the passenger compartment (LED reading lights)
- Electric child safety lock for sliding doors
- Child seat anchorage (I-Size) and top tether (for seats in the passenger compartment (except the middle seat of the 2nd row))
- Paint protection/transport protection film (transport protection film (minimum protection) with additional transport protection measures)
- Center console with 2 universal cup holders
- Multifunctional camera
- Fatigue detection
- Emergency braking assistant "Front Assist" (with pedestrian and cyclist detection)
- Upholstery: Fabric, "Double Grid" design
- Radio "Composition Audio" with 16.51 cm (6.5 inch) touch color display (4 speakers - mobile phone interface - 1 USB (Type C) interface)
- Wheels: Tire Mobility Set (12-volt compressor and tire sealant)
- Windscreen wiper intermittent control with light sensor
- Sliding door, on the right in the passenger/cargo area
- Side paneling for comfort in the passenger compartment
- Speed-sensitive power steering (Servotronic)
- Seat belts: in the passenger compartment (with belt tensioners for the outer seats in the 2nd row)
- Driver's cab seats: Height adjustment for left seat, manual
- Seats: Seat left and right, in the 1st row
- Sun visors with mirrors, airbag label on passenger sun visor
- Lane keeping assistant “Lane Assist”
- Power outlets: 12-volt socket in the cargo area
- Telephone: Mobile phone interface
- Lashing points: 6 lashing points for securing cargo
- Towing eye front and rear, screw-in
- Airbag for driver and front passenger (with passenger airbag deactivation)
- Electrically adjustable and heated exterior mirrors
- Exterior mirror housings in black, door handles in body color and sliding door rail in silver
- Floor coverings, carpeting in the driver's cab and passenger compartment (carpeting in the driver's cab and passenger compartment)
- Three-phase generator 140 A
- Electronic Stability Program with Brake Assist (including Anti-lock Braking System (ABS), Traction Control System (ASR), (EDS and MSR) - Evasive Steering Assist and Turn Assist)
- Window: Side window in the passenger/cargo compartment, rear right, permanently installed
- Window: Side window in the passenger/cargo compartment, front right, permanently installed
- Windows: Green heat-insulating glass
- Luggage compartment cover, foldable and removable
- Transmission: 6-speed transmission
- Glove compartment with lid, illuminated
- Rear window wiper/washer system with intermittent function
- Instrument cluster (km/h) (displays for speed, total/trip distance, engine speed, fuel level and time)
- Air conditioning with manual control
- Headrests (2), height adjustable
- Paint finish: Solid (Candy White)
- Steering wheel: Multifunction steering wheel
- Steering column adjustable in height and tilt
- Headlight range control
- Multifunction display "Plus"
- Multi-collision brake
- Non-smoking version
- eCall emergency call system
- Particulate filter: Diesel particulate filter (incl. SCR and AdBlue tank)
- Radio accessories: Digital radio reception DAB+
- Wheels, tires: Wheel covers
- Wheels/Tires: Tire pressure monitoring system
- reversing light
- Gearshift lever in plastic
- Sliding door, left side in the passenger/cargo area
- Keys for locking system: 2 remote control flip keys
- Side indicator lights
- Seat belts: Three-point automatic seat belts (front with belt height adjustment and electric belt tensioners)
- dimmable interior safety mirror
- Seats in the passenger compartment: 3-seater bench in the 2nd row (foldable, rollable and removable) (ISOFIX and Top Tether on outer seats in the passenger compartment - 2 individual seats in the 3rd row)

- Electronic immobilizer
- Auxiliary heating: Electric auxiliary air heater
- Start-stop system (with brake energy recuperation)
- Bumper in grey
- First aid kit, warning triangle and high-visibility vest
- Warning tone and light for unfastened front seat belts
- Central locking with remote control and interior operation
- Additional dust protection seal on the outside

Extra equipment

- Air conditioning system "Air Care Climatronic" with 2-zone temperature control and air purification function
- Package: Light and Sight (Safety interior mirror, automatically dimming - Windscreen wiper interval control with light and rain sensor - Automatic headlight control, with daytime running lights and welcome and farewell lights)
- Wheels/Tires: All-season tires 215/55 R 17 98 H XL, optimized for low rolling resistance
- Seats in the driver's cab: Lumbar support manually adjustable, left and right
- Bumpers in body color
- Partition net: Luggage net in the cargo/passenger compartment
- Navigation system "Discover Media" (Caddy) (25.4 cm (10 inch) touch color display - streaming & internet - 2 USB interfaces (Type C) in the center console, front)
- Package: Winter package (Seat heating for seats in the driver's cab, left and right, separately adjustable - Washer fluid level indicator with enlarged washer fluid reservoir - Heated windshield washer nozzles at the front)
- Driver's cab seats: Height adjustment for both front seats, manual
- Seats: Deletion of the 3rd row of seats (3-seater bench in the 2nd row (foldable, rollable and removable), preparation for 2 seats in the 3rd row, ISOFIX and Top Tether on outer seats in the 2nd row)

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. No lifting equipment or pit was available for inspecting the vehicle. Therefore, inspection of the vehicle's underside was only possible to a limited extent.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.

Value reducing factors

No.	Component group	Description
1	Door - front right side	Door handle - outside - Scratch(es) - Smart repair
2	Wing mirror - right side	Cap - Scratch(es) - Smart repair
3	Bonnet	Bonnet - Stone chips - Smart repair
4	Tail light	Tail lamp - right side - Scratch(es) - Replace
5	Headlight	Headlight - left side - Scratch(es) - Replace
6	Headlight	Headlight - right side (Beschichtung löst sich) - Differs from the original configuration - Replace
7	Wheel / tyres	Tyres - complete set - Worn - Replace
8	Rear bumper	Rear bumper - Scratch(es) - Paint
9	Mudguard - right side	Mudguard - right side - Scratch(es) - Paint
10	Door - front right side	Door - Dent / paintcoat damage - Repair and paint
11	Front bumper	Front bumper - Dent / paintcoat damage - Paint
12	Boot lid / rear door	Boot lid - Deformed - Repair and paint
13	Vehicle glazing	Windscreen - Stone chips - Replace

Wear and tear

No.	Component group	Description
1	Trim / covers	Boot lid - interior trim - Scratch(es) - No deduction
2	Roof	Roof rail - left side - dent(s) - No deduction
3	Sliding door - left side	Sliding door - dent(s) - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.

Missing parts

Description
Equipment - Tirefit complete

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
  (Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
  (Functional testing of driver assistance systems is not included in the scope of services!)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

No apparent prior damage that had been repaired could be found on the vehicle.

TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Hartmann Fleet Professionals GmbH
Leerenstraße 25
29683 Bad Fallingbostel



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)



Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel

Figure 9: Interior 360° view (Online Link)



Figure 10: Cargo area




Figure 11: VIN



Figure 12: Mounted tyres



Figure 13: Documents



Figure 14: Navigation



Figure 15: Misc.



Figure 16: Misc.



Figure 17: Misc.



Figure 18: Misc.




Figure 19: Misc.



Figure 20: Misc.




Figure 21: Misc.



Figure 22: Misc.




Figure 23: Misc.



Figure 24: Misc.



Figure 25: Misc.



Figure 26: Misc.



Figure 27: Misc.



Figure 28: Misc.




Damage 1: Door - front right side: Door handle - outside - Scratch(es) - Smart repair




Damage 1: Door - front right side: Door handle - outside - Scratch(es) - Smart repair



Damage 2: Wing mirror - right side: Cap - Scratch(es) - Smart repair




Damage 2: Wing mirror - right side: Cap - Scratch(es) - Smart repair



Damage 3: Bonnet: Bonnet - Stone chips - Smart repair



Damage 3: Bonnet: Bonnet - Stone chips - Smart repair



Damage 4: Tail light: Tail lamp - right side - Scratch(es) - Replace



Damage 4: Tail light: Tail lamp - right side - Scratch(es) - Replace



Damage 5: Headlight: Headlight - left side - Scratch(es) - Replace



Damage 5: Headlight: Headlight - left side - Scratch(es) - Replace




Damage 6: Headlight: Headlight - right side (Beschichtung löst sich) - Differs from the original configuration - Replace




Damage 6: Headlight: Headlight - right side (Beschichtung löst sich) - Differs from the original configuration - Replace




Damage 7: Wheel / tyres: Tyres - complete set - Worn - Replace



Damage 7: Wheel / tyres: Tyres - complete set - Worn - Replace



Damage 7: Wheel / tyres: Tyres - complete set - Worn - Replace



Damage 7: Wheel / tyres: Tyres - complete set - Worn - Replace



Damage 8: Rear bumper: Rear bumper - Scratch(es) - Paint



Damage 8: Rear bumper: Rear bumper - Scratch(es) - Paint



Damage 8: Rear bumper: Rear bumper - Scratch(es) - Paint



Damage 9: Mudguard - right side: Mudguard - right side - Scratch(es) - Paint



Damage 9: Mudguard - right side: Mudguard - right side - Scratch(es) - Paint



Damage 10: Door - front right side: Door - Dent / paintcoat damage - Repair and paint



Damage 10: Door - front right side: Door - Dent / paintcoat damage - Repair and paint



Damage 11: Front bumper: Front bumper - Dent / paintcoat damage - Paint



Damage 11: Front bumper: Front bumper - Dent / paintcoat damage - Paint



Damage 11: Front bumper: Front bumper - Dent / paintcoat damage - Paint




Damage 11: Front bumper: Front bumper - Dent / paintcoat damage - Paint



Damage 11: Front bumper: Front bumper - Dent / paintcoat damage - Paint



Damage 12: Boot lid / rear door: Boot lid - Deformed - Repair and paint



Damage 12: Boot lid / rear door: Boot lid - Deformed - Repair and paint




Damage 13: Vehicle glazing: Windscreen - Stone chips - Replace




Damage 13: Vehicle glazing: Windscreen - Stone chips - Replace



Wear and tear 1: Trim / covers: Boot lid - interior trim - Scratch(es) - No deduction




Wear and tear 2: Roof: Roof rail - left side - dent(s) - No deduction



Wear and tear 2: Roof: Roof rail - left side - dent(s) - No deduction



Wear and tear 3: Sliding door - left side: Sliding door - dent(s) - No deduction



Wear and tear 3: Sliding door - left side: Sliding door - dent(s) - No deduction