TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Hartmann Compound Professionals
Arnoldschacht 9-11
44894 Bochum

# Expertise

Protocol number: 48104912
Order No. / Reference: 27074613
Inspection date: 14 Oct 2026

| Manufacturer: Volkswagen | Model: Passat Variant 2.0 TDI SCR DSG Business |
|---|---|
| VIN: WVWZZZ3CZME083254 | |







## Vehicle details

| | |
|---|---|
| **Manufacturer / Type / Model / Equipment** | |
| Volkswagen Passat Variant 2.0 TDI SCR DSG Business | |
| **Vehicle Identification number** | WVWZZZ3CZME083254 |
| **Mileage** (Read) | 124,963 km |
| **First registration** | 9 Apr 2021 |
| **Number of holders** | 1 |
| **Next periodical technical inspection** | 04/2028 |
| (Report on hand) | |
| **Fuel type** | Diesel |
| **Engine displacement / Cylinder** | 1,968 ccm / 4 |
| **Power** | 110 kW |
| **Gearbox / Number of gears** | Automatic / 7 |
| **Type of drive** | Front drive |
| **Type of vehicle** | Car station wagon |
| **Colour / colour code** | Reflexsilber Metallic |
| **Doors / Seats** | 5 / 5 |
| **Upholstery type** | Cloth |
| **Colour of upholstery** | Black-Dark grey |
| **Re-import** | no |
| **readiness to drive** | Roadworthy |

## Vehicle details

| | | | |
|---|---|---|---|
| **Maintenance booklet / proof** | digital proof / complete | **Next maintenance in** | 20,600 km |
| **Last service on / at** | 04/2026 at 115,543 km | | |
| **Key is / should be** | 2 / 2 | **FZG documents** | ZB#2 (B) was available (copy), ZB#1 (S) was not available. |
| | | **Letter No.** | GA764017 |
| **Previous damage / Accident** | None detectable | **Repainting** | None detectable |
| **Inspection conditions** | sufficient | **Lifting equipment / pit** | yes |
| **Test drive** | Not performed | **Engine function test** | Performed |
| **readiness to drive** | Roadworthy | | |
| **Manufacturer key number/ type code number** | 0603 / BQS 00799 | | |
| **Emission standard** | EURO6 | **fine dust sticker** | |
| **Permitted total weight** | 2,210 kg | **Empty weight** | |

## Tyres

### Mounted tyres

| # | Tyre size | Type of tyre | Manufacturer | Tread depth |
|---|---|---|---|---|
| 1) | 215/60 R16 99V | Summer tyres on Light alloy | Pirelli | 5mm / 5mm |
| 2) | 215/60 R16 95V | Summer tyres on Light alloy | Continental | 6mm / 6mm |

### Additional tyres

| # | Tyre size | Type of tyre | Manufacturer | Tread depth |
|---|---|---|---|---|
| 1) | 215/60 R16 99H | Winter tyres on Steel | Pirelli | 6mm / 6mm |
| 2) | 215/60 R16 99H | Winter tyres on Steel | Dunlop | 6mm / 6mm |

### Replacement

| Typ | Tyre size | Type of tyre | Manufacturer | Tread depth |
|---|---|---|---|---|
| | Tirefit | Expiration date 12/2029 | | |

**Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.**

## Equipment

### Standard equipment

- Airbag for driver and front passenger
- Anti-lock braking system (ABS)
- Adaptive Cruise Control (ACC) "stop & go", including speed limiter
- Hill start assist
- Chrome trim on the side windows
- black roof rails
- Parking aid - warning signals for obstacles in the front and rear area
- Automatic headlight control
- Remote release for luggage compartment lid
- Pedestrian detection
- Adjustable luggage compartment floor
- Interior lights front and rear with switch-off delay and dimming function
- Instrument cluster with electronic speedometer, odometer and trip odometer, tachometer
- LED fog lights and cornering lights
- LED headlights with daytime running lights
- Headlight range control
- "Premium" multifunction display with multicolor screen
- Mesh partition
- Emergency braking assistant "Front Assist" (for automatic distance control ACC up to 210 km/h)
- Upholstery: Fabric "Weave"
- Radio "Composition"
- Radio accessories: Digital radio reception DAB+
- Tire pressure monitoring system (passive)
- LED taillights
- Gearshift knob in leather
- Keyless start system without safe locking
- Seat belts: Three-point automatic seat belt
- Seats: Front seats are height-adjustable
- 12V power outlet on the rear of the center console
- Textile floor mats
- Warning tone and light for unfastened seat belts front and rear
- Airbag, head airbag system for front and rear passengers
- App-Connect
- Electrically adjustable and heated exterior mirrors
- Cup holders (2) front
- third brake light
- Headliner in Mistral Grey
- Diesel particulate filter
- Electronic parking brake including auto-hold function
- Electronic stability program and electromechanical brake booster
- Windscreen made of laminated safety glass, heat and sound insulating
- Transmission: 7-speed DSG
- ISOFIX mounting points
- Air conditioning
- Rear headrests (3)
- Front headrests
- LED taillights
- Steering wheel: Multifunction steering wheel in leather, with paddle shifters
- Fatigue detection
- Non-smoking version
- Emergency call service
- Package: Light and Sight Package "Plus"
- Proactive occupant protection system in conjunction with "Front Assist"
- Rain sensor
- Wheels: 4 light alloy wheels "Sepang" 6.5 J x 16
- Rear bench seat, undivided, backrest asymmetrically split and foldable, with center armrest
- Power steering
- Seats: Lumbar support in the front
- Start-stop system
- Telephone interface
- First aid kit, warning triangle and high-visibility vest
- Electronic immobilizer

### Extra equipment

- Anti-theft alarm system (interior monitoring, backup horn and tow-away protection - illuminated make-up mirror in the sun visors, extendable sun visors)
- Package: "Business Premium" package incl. navigation (from Business trim level) (2 USB-C ports in the front, 1 USB-C charging port in the rear, 230V socket, App-Connect incl. wireless, Apple CarPlay, Android Auto, "Travel Assist" driver assistance system and "Lane Assist" lane keeping system, Air Care Climatronic with 3-zone temperature control, allergen filter and rear controls, lumbar support in the front, electric on the driver's side, massage function on the driver's side, "Rear View" reversing camera, heated windshield washer nozzles, Comfort telephone interface, inductive charging function, heated front seats)
- Keyless start system with safe locking
- Voice control
- "Comfort" telephone interface with inductive charging function (hands-free system)
- Paint finish: Metallic
- Navigation system "Discover Media" incl. "Streaming & Internet" (4x20 watts, user interface with proximity sensor, dual tuner with phase diversity, vehicle menu, speed, volume adjustment, map, 2D display, tone control, 3-way TFT display with touchscreen operation, navigation "Discover Media" incl. "Streaming & Internet", MP3 radio, telephone contact addresses for navigation, telephone interface, 2 USB ports also for iPod/iPhone, traffic sign recognition "VW Media Control", We Connect Plus, 3 years, incl. We Connect route guidance, dynamic RDS, TMC tuner)
- Package: Winter (front windshield washer nozzles automatically heated - front seats heated)
- Rear side windows and rear window tinted
- Auxiliary heating and ventilation (with radio remote control and timer)

## Brief expert findings

| | |
|---|---|
| Documents submitted | At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy) |
| VIN comparison | The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection. |
| Inspection | The inspection conditions were sufficient for the assessment of the vehicle.<br>Lifting equipment and/or a pit were available for examining the vehicle. |
| Test drive | No test drive/shunting maneuver was carried out during the inspection of the vehicle. |
| Engine function test | An engine test run was performed. |
| readiness to drive | The vehicle was roadworthy at the time of inspection. |

## Value reducing factors

| No. | Component group | Description |
|---|---|---|
| 1 | Wing mirror - right side | Cap - Scratch(es) - Smart repair |
| 2 | Mudguard - right side | Mudguard - right side - Stone chips - Smart repair |
| 3 | Vehicle glazing | Windscreen (Mehrkosten möglich) - Stone chips - Smart repair |
| 4 | Rear bumper | Rear bumper - Scratch(es) - Paint |
| 5 | Side panel - rear left side | Side panel - Scratch(es) - Paint |
| 6 | Side panel - rear right side | Side panel - Dent / paintcoat damage - Repair and paint |
| 7 | Bonnet | Bonnet (+ Vogelkotverätzung) - Stone chips - Paint |

## Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
  *(Delivery by third-party service providers)*
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
  *(Functional testing of driver assistance systems is not included in the scope of services!)*
- a photographic documentation of the vehicle

## Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

## Previous damages

No apparent prior damage that had been repaired could be found on the vehicle.

## Comments

- Wartungshistorie gemäß Auftraggeber Informationen.

- Winterradsatz ist kein Bestandteil des Auslieferumfangs.




**Figure 1:** Diagonal front (left)




**Figure 2:** Diagonal front (right)




**Figure 3:** Diagonal rear (left)




**Figure 4:** Diagonal rear (right)



**Figure 5:** Interior - front



**Figure 6:** Interior - rear




**Figure 7:** Instrument cluster



**Figure 8:** Instrument panel

**Figure 9:** Interior 360° view (Online Link)



**Figure 10:** Cargo area




**Figure 11:** VIN



**Figure 12:** Mounted tyres



**Figure 13:** Documents





**Figure 14:** Documents



**Figure 15:** Additional tyres




**Figure 16:** Navigation



**Figure 17:** Misc.



**Figure 18:** Misc.



**Figure 19:** Misc.



**Figure 20:** Misc.




**Figure 21:** Misc.



**Figure 22:** Misc.




**Figure 23:** Misc.




**Figure 24:** Misc.




**Figure 25:** Misc.




**Figure 26:** Misc.




**Figure 27:** Misc.




**Figure 28:** Misc.



**Figure 29:** Misc.



**Figure 30:** Misc.



**Damage 1:** Wing mirror - right side: Cap - Scratch(es) - Smart repair



**Damage 1:** Wing mirror - right side: Cap - Scratch(es) - Smart repair



**Damage 2:** Mudguard - right side: Mudguard - right side - Stone chips - Smart repair




**Damage 2:** Mudguard - right side: Mudguard - right side - Stone chips - Smart repair



**Damage 3:** Vehicle glazing: Windscreen (Mehrkosten möglich) - Stone chips - Smart repair




**Damage 3:** Vehicle glazing: Windscreen (Mehrkosten möglich) - Stone chips - Smart repair



**Damage 4:** Rear bumper: Rear bumper - Scratch(es) - Paint



**Damage 4:** Rear bumper: Rear bumper - Scratch(es) - Paint



**Damage 4:** Rear bumper: Rear bumper - Scratch(es) - Paint



**Damage 5:** Side panel - rear left side: Side panel - Scratch(es) - Paint



**Damage 5:** Side panel - rear left side: Side panel - Scratch(es) - Paint



**Damage 5:** Side panel - rear left side: Side panel - Scratch(es) - Paint



**Damage 6:** Side panel - rear right side: Side panel - Dent / paintcoat damage - Repair and paint



**Damage 6:** Side panel - rear right side: Side panel - Dent / paintcoat damage - Repair and paint




**Damage 6:** Side panel - rear right side: Side panel - Dent / paintcoat damage - Repair and paint



**Damage 6:** Side panel - rear right side: Side panel - Dent / paintcoat damage - Repair and paint



**Damage 7:** Bonnet: Bonnet (+ Vogelkotverätzung) - Stone chips - Paint



**Damage 7:** Bonnet: Bonnet (+ Vogelkotverätzung) - Stone chips - Paint



**Damage 7:** Bonnet: Bonnet (+ Vogelkotverätzung) - Stone chips - Paint



**Damage 7:** Bonnet: Bonnet (+ Vogelkotverätzung) - Stone chips - Paint