# APPRAISAL REPORT



## IDENTIFICATION VEHICLE

| | |
|---|---|
| **Driver name:** | HM Tongeren |
| **Make:** | BMW |
| **Model / version:** | 5 SERIES TOURING |
| **Vin:** | WBA11BN040CH62560 |
| **Plate:** | 2AUK447 |
| **Mileage:** | 125835 |
| **First registration:** | 22/07/2021 |
| **Color:** | Bluestone (m |

## ADDITIONAL INFORMATION

| | |
|---|---|
| **Category:** | |
| **Transmission:** | |
| **Interior color:** | |
| **Metallic paint:** | ? |
| **Type of lining:** | |
| **Board computer reset:** | ? |


## DOCUMENTS

| | |
|---|---|
| **Certificate of conformity:** | ✓ |
| **Registration certificate:** | ✓ |
| **Registration certificate 2:** | ✓ |
| **Insurance certificate:** | ✗ |
| **Maintenance book:** | |
| **Number of keys:** | 2 |
| **Original key:** | ✓ |

## PICTURES










































## VIN INFORMATION

| | | |
|---|---|---|
| Téléphone | Transmission automatique | 8 rapports |
| Matière : alliage | Lettre repère (J) | Diamètre avant 17 |
| Diamètre arrière 17 | Largeur avant 7,5 | Largeur arrière 7,5 |
| Diamètre avant 17 | Diamètre arrière 17 | Hauteur avant 55 |
| Hauteur arrière 55 | Indice de vitesse avant Y | Indice de vitesse arrière Y |
| Largeur avant 225 | Largeur arrière 225 | Climatisation automatique 2 zones |
| Climatisation réfrigérant 1234YF | Diesel | 1995 cm3 |
| 2.00 litres | 110 kw | 150 ch |
| Métallisée vernissée | Rétroviseur gauche jour/nuit automatique | Rétroviseur droit jour/nuit automatique |
| Siège avant gauche chauffant | Sièges avant chauffants | Garnitures cuir |
| Aide au stationnement avant | Aide au stationnement arrière | Assistance au parking |
| Caméra avant | Caméra arrière de recul | Alarme |

| | | |
|---|---|---|
| Appel de secours | Toit ouvrant électrique | Toit ouvrant vitré panoramique |
| Attelage avec boule rétractable électrique | Fixotoit aluminium satiné | Protection piéton |
| Freinage d'urgence assistée autonome (urbain) | Avertisseur de collision avant | Contrôle pression des pneus |
| depuis 07.21 | éclairage d'ambiance | mesures CO2 étendues |
| Teleservices | tuner DAB | BMW Live Cockpit Professional |
| système de récupération d'énergie | spécifique Europe | |

## EQUIPMENT

| | | | |
|---|---|---|---|
| **Board computer:** | ? | **Central locking:** | ? |
| **Compressor:** | × | **Cruise control:** | ? |
| **Gps:** | ? | **Power steering:** | ? |
| **Rear parking sensor:** | ? | **Repair kit:** | × |
| **Front seats heated:** | ? | **Steering wheel:** | ? |
| **Electric windows:** | ? | **Climate control type:** | |
| **Headlighting type:** | | **Tow bar type:** | |
| **Charging cables:** | 0 | **Fast charging cables:** | 0 |

## TIRES

| Position | Depth | Brand | Dimensions | Type | Rims | Runflat |
|---|---|---|---|---|---|---|
| Front left | 5 mm | | 225/55R17 101Y | Summer | ? | |
| Front right | 5 mm | | 225/55R17 101Y | Summer | ? | |
| Rear left | 5 mm | | 225/55R17 101Y | Summer | ? | |
| Rear right | 5 mm | | 225/55R17 101Y | Summer | ? | |

## DAMAGES SUMMARY

**NOT ACCEPTABLE / TO BE INVOICED**

| # | Location | Damage type |
|---|---|---|
| 1 | Certificate of registration 2 | Teared |
| 2 | Bumper F | Dent(s) and scratch(es) |
| 4 | Door FL | Dent(s) and scratch(es) |
| 5 | Wing RL | Dent(s) |
| 6 | Bumper R | Scratch(es) |

**Total: 5**

**ACCEPTABLE / NOT TO BE INVOICED**

| # | Location | Damage type | Renta® | Repaired | Already invoiced |
|---|---|---|---|---|---|
| 3 | Bodywork | Dent(s) and scratch(es) | ✓ | × | × |

**Total: 1**

## DAMAGES DETAILS

### 1 - Certificate of registration 2 - Teared





### 2 - Bumper F - Dent(s) and scratch(es)







**4** - Door FL - Dent(s) and scratch(es)






**5** - Wing RL - Dent(s)





**6** - Bumper R - Scratch(es)






**3** - Bodywork - Dent(s) and scratch(es) - Renta®














## SIGNATURE - IN AGREEMENT WITH THE RECORDED DAMAGES

**Expert**

21/10/2026 12:05

