TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Hartmann Fleet Professionals GmbH
Industriestraße 11
36272 Niederaula

Expertise

Protocol number: 48550085
Order No. / Reference: 27204563
Inspection date: 2 Nov 2026

Manufacturer: Ford	Model: Transit 350 L4H3 Lkw HA Trend
VIN: WF0EXXTTRENJ39278	





Vehicle details

Manufacturer / Type / Model / Equipment	
Ford Transit 350 L4H3 Lkw HA Trend	
Vehicle Identification number	WF0EXXTTRENJ39278
Mileage (Read)	167,519 km
First registration	28 Jul 2022
Number of holders	1
Fuel type	Diesel
Engine displacement / Cylinder	1,995 ccm / 4
Power	96 kW
Gearbox / Number of gears	Manual / 6
Type of drive	Rear drive
Type of vehicle	Van
Colour / colour code	Frozen White
Doors / Seats	4 / 3
Upholstery type	Cloth
Colour of upholstery	Black-Anthracite

Vehicle details

Maintenance booklet / proof	Available / incomplete	**Next maintenance in**	0 km
Last service on / at	02/2024 at 79,541 km		
Key is / should be	1 / 2	**FZG documents**	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	GK830352
Previous damage / Accident	Detectable	**Repainting**	None detectable
Inspection conditions	sufficient	**Lifting equipment / pit**	yes
Test drive	Not performed	**Engine function test**	Performed
Manufacturer key number/ type code number	8566 / BNG 10379		
Emission standard	EURO6	**fine dust sticker**	
Permitted total weight	3,500 kg	**Empty weight**	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	235/65 R16 115R	All-season tyres on Steel	Sonstige	5mm / 5mm
2)	235/65 R16 115R	All-season tyres on Steel	Sonstige	5mm / 5mm

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

Equipment

Standard equipment

- 1 battery
- Anti-lock braking system with electronic brake force distribution (EBD) incl.
- On-board computer
- roof, high
- Tachometer
- Third brake light
- Ford Easy Fuel
- Generator, high-performance version
- Transmission: 6-speed transmission
- Interior lighting with delay circuit
- Fuel tank 70 l
- Cargo area lighting
- Steering column, adjustable in height and reach
- Fog light
- Package: Technology Package 9
- Radio: Ford audio system with radio and DAB+
- Wheels: Tire repair kit
- Headlight low beam: Halogen headlights with daytime running lights
- Sliding door: Sliding door, right
- Side protection strips
- Seat belts
- Start-stop system
- Partition wall (plastic) at the height of the B-pillar
- Lashing eyes
- Heat-insulating glazing, lightly tinted
- Second key with remote control
- Driver's side airbag
- Exterior mirrors, electrically adjustable and heated
- Battery: Battery life, programming of battery life to 10 minutes
- Double-leaf rear doors with a 256° opening angle (without windows)
- Front electric windows
- Warranty: 2-year Ford new car warranty including Ford Assistance mobility guarantee
- Lockable glove compartment with lid
- Front air conditioning
- Paint finish: Solid color paint
- Steering wheel: Faux leather steering wheel
- MyKey key system
- Emergency call assistant
- Particulate filter: diesel particulate filter
- Wheels: Wheel trims
- Wheels: Steel wheels 6.5 J x 16 with 235/65 R 16 tires
- Sliding door entry light automatically illuminates when the door is opened
- Rear mud flaps
- Power steering
- Seats: Seat package 13
- Rear bumper with integrated step
- recirculation mode
- Immobiliser
- Central locking with remote control
- Front overhead storage compartment

Extra equipment

- Deletion: Digital tachograph (including deletion of the second battery)
- Package: Technology Package 10 (Heated windscreen, rain-sensing wipers - Front and rear parking sensors, active emergency braking assist (camera-based) - Lane Keeping Assist with Driver Alert and High Beam Assist; additionally with Lane Departure Warning - Automatic Headlights with Day/Night Sensor - Cruise Control - Rearview Camera with image transmission of the rear view on the multifunction display - LED Downlights - Fog Lights - Ford Audio System with 4" multifunction display)
- Option Airline Rails
- Package: Cargo area protection package 2 (Cargo area floor "Easy Clean" - High side wall cladding - Cargo area lighting (LED) - Fuel tank 95 l)
- Wheels/Tires: Spare wheel, steel wheel
- Partition wall (metal)
- Central locking with remote control (also includes a second key, foldable, with remote control)

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. Lifting equipment and/or a pit were available for examining the vehicle.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.

Value reducing factors

No.	Component group	Description
1	Braking system	Braking system - Functional / admissibility - Perform diagnosis
2	Fuel system	Tank flap - Scratched - Smart repair
3	Electronic systems	Parking assistance - Functional / admissibility - Perform
4	Indicator - front	Mirror - left side - Broken / torn - Replace
5	Indicator - front	Mirror - right side (Materialabtrag) - Scratched - Replace
6	Wheel / tyres	Tyre - front left side (Flanke) - Damaged - Replace
7	Wheel / tyres	Tyre - front right side (Flanke glatt) - Damaged - Replace
8	Wheel / tyres	Tyre - rear right side (Flanke glatt) - Damaged - Replace
9	Interior	Interior (Sitze speckig) - Soiled - Clean
10	Rear axle	Rear axle (Anschlagpuffer) - Porous / cracked - Replace
11	Body	Firewall trim - Damage caused by marten / rodent - Replace
12	Misc.	Inspection / maintenance (Fällig) - Incomplete - Perform
13	Seat - front	Seat cover - left side (+ Polster) - Broken / torn - Replace
14	Front bumper	Front bumper (+ Nebelscheinwer Rahmen) - Scratched - Replace
15	Door - front right side	Door - Dent / paintcoat damage - Repair and paint
16	Door - front left side	Door - Dent / paintcoat damage - Repair and paint
17	Vehicle glazing	Windscreen - Broken / torn - Replace

Wear and tear

No.	Component group	Description
1	Misc.	Main inspection - No evidence - No deduction
2	Interior	Cargo area floor (Laderaum) - Scratched - No deduction
3	Door - front left side	Brightware - lower - Scratched - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.

Missing parts

Description
Wheel / tyres - Wheel cover set - complete
Equipment - Spare wheel
Equipment - Vehicle key with remote control

Accident damages

No.	Accident
1	Side - left
2	Roof, Rear, Side right

TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Hartmann Fleet Professionals GmbH
Industriestraße 11
36272 Niederaula

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
  (Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
  (Functional testing of driver assistance systems is not included in the scope of services!)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

Non-repaired previous damages were found at the vehicle. The necessary repair costs are listed in the expert report or if necessary, are listed in detail in a separately enclosed repair cost calculation.

Comments

Das Fahrzeug befand sich zum Besichtigungszeitpunkt in beschädigtem, nicht demontiertem Zustand. Schadenausweitung möglich, Zusatzkosten können entstehen.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)




Figure 5: Interior - front



Figure 6: Interior - rear




Figure 7: Instrument cluster




Figure 8: Instrument panel

Figure 9: Interior 360° view (Online Link)




Figure 10: Cargo area



Figure 11: VIN



Figure 12: Mounted tyres




Figure 13: Documents




Figure 14: Documents




Figure 15: Documents




Figure 16: Documents




Figure 17: Documents



Figure 18: Navigation



Figure 19: Misc.



Figure 20: Misc.



Figure 21: Misc.



Figure 22: Misc.




Figure 23: Misc.




Figure 24: Misc.



Figure 25: Misc.



Figure 26: Misc.



Figure 27: Misc.



Figure 28: Misc.



Figure 29: Misc.




Figure 30: Misc.



Figure 31: Misc.



Damage 1: Braking system: Braking system - Functional / admissibility - Perform diagnosis




Damage 2: Fuel system: Tank flap - Scratched - Smart repair



Damage 2: Fuel system: Tank flap - Scratched - Smart repair



Damage 3: Electronic systems: Parking assistance - Functional / admissibility - Perform



Damage 4: Indicator - front: Mirror - left side - Broken / torn - Replace



Damage 4: Indicator - front: Mirror - left side - Broken / torn - Replace



Damage 5: Indicator - front: Mirror - right side (Materialabtrag) - Scratched - Replace



Damage 5: Indicator - front: Mirror - right side (Materialabtrag) - Scratched - Replace



Damage 5: Indicator - front: Mirror - right side (Materialabtrag) - Scratched - Replace



Damage 6: Wheel / tyres: Tyre - front left side (Flanke) - Damaged - Replace




Damage 6: Wheel / tyres: Tyre - front left side (Flanke) - Damaged - Replace



Damage 7: Wheel / tyres: Tyre - front right side (Flanke glatt) - Damaged - Replace



Damage 7: Wheel / tyres: Tyre - front right side (Flanke glatt) - Damaged - Replace



Damage 7: Wheel / tyres: Tyre - front right side (Flanke glatt) - Damaged - Replace



Damage 7: Wheel / tyres: Tyre - front right side (Flanke glatt) - Damaged - Replace



Damage 8: Wheel / tyres: Tyre - rear right side (Flanke glatt) - Damaged - Replace



Damage 8: Wheel / tyres: Tyre - rear right side (Flanke glatt) - Damaged - Replace



Damage 8: Wheel / tyres: Tyre - rear right side (Flanke glatt) - Damaged - Replace




Damage 9: Interior: Interior (Sitze speckig) - Soiled - Clean



Damage 9: Interior: Interior (Sitze speckig) - Soiled - Clean




Damage 9: Interior: Interior (Sitze speckig) - Soiled - Clean




Damage 9: Interior: Interior (Sitze speckig) - Soiled - Clean




Damage 10: Rear axle: Rear axle (Anschlagpuffer) - Porous / cracked - Replace




Damage 10: Rear axle: Rear axle (Anschlagpuffer) - Porous / cracked - Replace



Damage 10: Rear axle: Rear axle (Anschlagpuffer) - Porous / cracked - Replace



Damage 10: Rear axle: Rear axle (Anschlagpuffer) - Porous / cracked - Replace



Damage 11: Body: Firewall trim - Damage caused by marten / rodent - Replace



Damage 11: Body: Firewall trim - Damage caused by marten / rodent - Replace



Damage 12: Misc.: Inspection / maintenance (Fällig) - Incomplete - Perform



Damage 13: Seat - front: Seat cover - left side (+ Polster) - Broken / torn - Replace



Damage 13: Seat - front: Seat cover - left side (+ Polster) - Broken / torn - Replace



Damage 14: Front bumper: Front bumper (+ Nebelscheinwer Rahmen) - Scratched - Replace



Damage 14: Front bumper: Front bumper (+ Nebelscheinwer Rahmen) - Scratched - Replace



Damage 14: Front bumper: Front bumper (+ Nebelscheinwer Rahmen) - Scratched - Replace



Damage 14: Front bumper: Front bumper (+ Nebelscheinwer Rahmen) - Scratched - Replace



Damage 14: Front bumper: Front bumper (+ Nebelscheinwer Rahmen) - Scratched - Replace



Damage 14: Front bumper: Front bumper (+ Nebelscheinwer Rahmen) - Scratched - Replace



Damage 15: Door - front right side: Door - Dent / paintcoat damage - Repair and paint



Damage 15: Door - front right side: Door - Dent / paintcoat damage - Repair and paint



Damage 15: Door - front right side: Door - Dent / paintcoat damage - Repair and paint



Damage 15: Door - front right side: Door - Dent / paintcoat damage - Repair and paint



Damage 16: Door - front left side: Door - Dent / paintcoat damage - Repair and paint




Damage 16: Door - front left side: Door - Dent / paintcoat damage - Repair and paint



Damage 16: Door - front left side: Door - Dent / paintcoat damage - Repair and paint



Damage 16: Door - front left side: Door - Dent / paintcoat damage - Repair and paint



Damage 16: Door - front left side: Door - Dent / paintcoat damage - Repair and paint




Damage 16: Door - front left side: Door - Dent / paintcoat damage - Repair and paint



Damage 17: Vehicle glazing: Windscreen - Broken / torn - Replace




Damage 17: Vehicle glazing: Windscreen - Broken / torn - Replace




Wear and tear 3: Door - front left side: Brightware - lower - Scratched - No deduction



Wear and tear 3: Door - front left side: Brightware - lower - Scratched - No deduction



Missing part 2: Equipment: Spare wheel - Missing - Replace



Missing part 3: Equipment: Vehicle key with remote control - Missing - Replace



Accident 1: Side - left



Accident 1: Side - left



Accident 1: Side - left



Accident 1: Side - left



Accident 1: Side - left



Accident 1: Side - left



Accident 1: Side - left



Accident 1: Side - left




Accident 1: Side - left



Accident 1: Side - left



Accident 1: Side - left



Accident 1: Side - left



Accident 1: Side - left



Accident 1: Side - left



Accident 1: Side - left



Accident 1: Side - left



Accident 1: Side - left



Accident 1: Side - left



Accident 1: Side - left



Accident 1: Side - left



Accident 1: Side - left



Accident 1: Side - left



Accident 1: Side - left




Accident 1: Side - left




Accident 1: Side - left



Accident 2: Roof, Rear, Side right




Accident 2: Roof, Rear, Side right



Accident 2: Roof, Rear, Side right



Accident 2: Roof, Rear, Side right



Accident 2: Roof, Rear, Side right



Accident 2: Roof, Rear, Side right



Accident 2: Roof, Rear, Side right



Accident 2: Roof, Rear, Side right




Accident 2: Roof, Rear, Side right



Accident 2: Roof, Rear, Side right



Accident 2: Roof, Rear, Side right




Accident 2: Roof, Rear, Side right



Accident 2: Roof, Rear, Side right



Accident 2: Roof, Rear, Side right



Accident 2: Roof, Rear, Side right




Accident 2: Roof, Rear, Side right



Accident 2: Roof, Rear, Side right




Accident 2: Roof, Rear, Side right



Accident 2: Roof, Rear, Side right



Accident 2: Roof, Rear, Side right



Accident 2: Roof, Rear, Side right




Accident 2: Roof, Rear, Side right



Accident 2: Roof, Rear, Side right



Accident 2: Roof, Rear, Side right



Accident 2: Roof, Rear, Side right



Accident 2: Roof, Rear, Side right



Accident 2: Roof, Rear, Side right



Accident 2: Roof, Rear, Side right



Accident 2: Roof, Rear, Side right



Accident 2: Roof, Rear, Side right



Accident 2: Roof, Rear, Side right



Accident 2: Roof, Rear, Side right



Accident 2: Roof, Rear, Side right



Accident 2: Roof, Rear, Side right



Accident 2: Roof, Rear, Side right



Accident 2: Roof, Rear, Side right



Accident 2: Roof, Rear, Side right



Accident 2: Roof, Rear, Side right



Accident 2: Roof, Rear, Side right




Accident 2: Roof, Rear, Side right



Accident 2: Roof, Rear, Side right



Accident 2: Roof, Rear, Side right



Accident 2: Roof, Rear, Side right



Accident 2: Roof, Rear, Side right



Accident 2: Roof, Rear, Side right



Accident 2: Roof, Rear, Side right



Accident 2: Roof, Rear, Side right



Accident 2: Roof, Rear, Side right



Accident 2: Roof, Rear, Side right



Accident 2: Roof, Rear, Side right