TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Mosolf SE & Co.KG
August-Horch-Straße 1
04519 Rackwitz

Expertise

Protocol number: 48573352
Order No. / Reference: 27253531
Inspection date: 9 Nov 2026

Manufacturer: Ford	Model: Transit Connect 220 L1 S&S Trend
VIN: WF0RXXWPGRLL48130	





Vehicle details

Manufacturer / Type / Model / Equipment	
Ford Transit Connect 220 L1 S&S Trend	
Vehicle Identification number	WF0RXXWPGRLL48130
Mileage (Read)	92,024 km
First registration	20 Nov 2020
Number of holders	1
Next periodical technical inspection	11/2026
(Report on hand)	
Fuel type	Diesel
Engine displacement / Cylinder	1,499 ccm / 4
Power	88 kW
Gearbox / Number of gears	Manual / 6
Type of drive	Front drive
Type of vehicle	Van
Colour / colour code	Frost-Weiß
Doors / Seats	4 / 2
Upholstery type	Cloth
Colour of upholstery	Black

Vehicle details

Maintenance booklet / proof	digital proof / complete	**Next maintenance in**	23 %
Last service on / at	11/2025 at 69,657 km		
Key is / should be	2 / 3	**FZG documents**	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	FY016112
Previous damage / Accident	Detectable	**Repainting**	None detectable
Inspection conditions	sufficient	**Lifting equipment / pit**	yes
Test drive	Not performed	**Engine function test**	Performed
Manufacturer key number/ type code number	8566 / BMN 01413		
Emission standard	EURO6	**fine dust sticker**	
Permitted total weight	2,390 kg	**Empty weight**	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	205/60 R16 96H	Winter tyres on Steel rim with wheel cover	Pirelli	7mm / 7mm
2)	205/60 R16 96H	Winter tyres on Steel rim with wheel cover	Pirelli	8mm / 8mm

Additional tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	205/60 R16 96H	Summer tyres on Steel	Continental	4mm / 4mm
2)	205/60 R16 96H	Summer tyres on Steel	Continental	5mm / 5mm

Replacement

Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
E	205/60 R16 96H	Summer tyres on Steel	Continental	7 mm

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

Equipment

Standard equipment

- ABS with EBD
- Exterior mirrors, narrow mirror format
- Hill start assist
- On-board computer including outside temperature display
- Double-leaf rear doors without windows
- Third brake light
- Front electric windows
- FordPass Connect
- FRNK: Seat covers
- Warranty: 2-year Ford new car warranty including Ford Assistance mobility guarantee
- Interior lighting in the passenger/cargo area with delay function
- Paint finish: Solid
- Cargo area floor protection, plastic, molded
- Steering column, adjustable in height and reach
- Fog light
- Radio: Ford Audio System 2
- Wheels: Steel wheels 6.5 J x 16 with 205/60 R 16 tires and wheel trims
- Electro-mechanical power steering
- Front seat belts are height-adjustable
- Seats: Seat package 4
- Start-stop system
- Concealed storage compartment on dashboard
- Power outlet: 12-volt connection in storage compartment on dashboard (driver's side)
- Daytime running light
- Child safety lock on sliding doors
- Electronic immobilizer (EPATS)
- Central locking with remote control
- Driver's side airbag
- Battery, reinforced
- Rubberized flooring, front
- Diesel particulate filter (DPF)
- Tachometer
- Electronic Safety and Stability Program (ESP)
- Ford Easy Fuel
- FRNK: Third key
- Heated windshield
- Transmission: 6-speed transmission
- Glove compartment with lid
- Front interior lighting with delay function
- Front air conditioning including semi-electronic recirculation system
- Cargo area lining, side, half-height
- Center console, front
- Emergency brake light
- Wheels: Tire repair kit
- Sliding door at rear, right
- Side protection strips, plastic
- Safety brake assist
- Automatic door locking mechanism (45 sec.)
- Front spoiler lip
- Dust and pollen filter
- Power outlet: 12-volt connection on the front center console
- Front bumper and rear bumper end caps painted in body color
- Partition to the cargo area without window
- Lashing eyes
- Heat-insulating glazing, lightly tinted
- Auxiliary electric heater (PTC), front

Extra equipment

- Electrically adjustable and heated exterior mirrors with blind spot assist
- Adaptive cruise control
- Air conditioning with automatic temperature control (2 zones)
- Parking assistant (active) with parking and exiting function
- Tire pressure monitoring system
- Headlight assistant with day/night sensor
- Seats: Seat package 42
- Partition wall to the cargo area with pass-through opening and window
- DPF regenerator, manual
- Remote control: 2nd remote control key for central locking
- Rear swing door with heated rear window
- Inductive charging station for mobile devices
- Fog lights with static cornering lights
- Radio: Ford Audio System 9
- Spare wheel: Steel wheel
- Crosswind Assist and Roll Stability Control (RSC)
- Fuel-operated auxiliary heater, programmable via on-board computer
- Xenon: Bi-xenon headlights with LED daytime running lights

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. Lifting equipment and/or a pit were available for examining the vehicle.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.

Value reducing factors

No.	Component group	Description
1	Misc.	Main inspection (11/2026) - Due - Perform
2	Wheel / tyres	Wheel cover - front right side - Broken / torn - Replace
3	Sill - right side	Trim (Hinten) - Broken / torn - Replace
4	Front bumper	Front bumper - Scratch(es) - Smart repair
5	Side panel - rear right side	Side panel - dent(s) - Smart repair
6	Rear bumper	Rear bumper (unpainted) - Scratched - Replace
7	Vehicle glazing	Windscreen - Stone chips - Replace

Missing parts

Description
Equipment - Vehicle key with remote control

Previous damages

No.	Previous damage	Extent of damage (Net)
1	Rear, Provided by user / customer, from 3 Mar 2025	877,41 €

Paint coat thickness measurement

Boot lid / rear door	107 µm

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
  (Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
  (Functional testing of driver assistance systems is not included in the scope of services!)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

According to available information previous damages were repaired at the vehicle. Traces of repairs, which allow conclusions about the area of repair, were not recognizable during the inspection.

Comments

- Winterradsatz ist kein Bestandteil des Auslieferungsumfangs.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)




Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel

Figure 9: Interior 360° view (Online Link)




Figure 10: Cargo area



Figure 11: VIN



Figure 12: Mounted tyres




Figure 13: Documents




Figure 14: Documents



Figure 15: Documents



Figure 16: Additional tyres



Figure 17: Navigation



Figure 18: Misc.




Figure 19: Misc.




Figure 20: Misc.



Figure 21: Misc.




Figure 22: Misc.



Figure 23: Misc.




Figure 24: Misc.



Figure 25: Misc.



Figure 26: Misc.



Figure 27: Misc.




Figure 28: Misc.



Figure 29: Misc.



Figure 30: Misc.



Damage 1: Misc.: Main inspection (11/2026) - Due - Perform



Damage 2: Wheel / tyres: Wheel cover - front right side - Broken / torn - Replace



Damage 2: Wheel / tyres: Wheel cover - front right side - Broken / torn - Replace



Damage 3: Sill - right side: Trim (Hinten) - Broken / torn - Replace



Damage 3: Sill - right side: Trim (Hinten) - Broken / torn - Replace




Damage 3: Sill - right side: Trim (Hinten) - Broken / torn - Replace



Damage 4: Front bumper: Front bumper - Scratch(es) - Smart repair



Damage 4: Front bumper: Front bumper - Scratch(es) - Smart repair



Damage 5: Side panel - rear right side: Side panel - dent(s) - Smart repair



Damage 5: Side panel - rear right side: Side panel - dent(s) - Smart repair



Damage 5: Side panel - rear right side: Side panel - dent(s) - Smart repair



Damage 6: Rear bumper: Rear bumper (unpainted) - Scratched - Replace




Damage 6: Rear bumper: Rear bumper (unpainted) - Scratched - Replace



Damage 6: Rear bumper: Rear bumper (unpainted) - Scratched - Replace



Damage 7: Vehicle glazing: Windscreen - Stone chips - Replace



Damage 7: Vehicle glazing: Windscreen - Stone chips - Replace



Missing part 1: Equipment: Vehicle key with remote control - Missing - Replace



Boot lid / rear door: 107 µm