TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Mosolf SE & Co.KG
August-Horch-Straße 1
04519 Rackwitz

# Expertise

Protocol number: 48437868
Order No. / Reference: 27076616
Inspection date: 2 Nov 2026

| Manufacturer: Volkswagen | Model: Tiguan Allspace 2.0 TDI SCR DSG Life |
|---|---|
| VIN: WVGZZZ5N3PM021574 | |







## Vehicle details

| | |
|---|---|
| **Manufacturer / Type / Model / Equipment** | |
| Volkswagen Tiguan Allspace 2.0 TDI SCR DSG Life | |
| **Vehicle Identification number** | WVGZZZ5N3PM021574 |
| **Mileage** (Read) | 190,712 km |
| **First registration** | 2 Feb 2023 |
| **Number of holders** | 1 |
| **Next periodical technical inspection** (Report on hand) | 02/2028 |
| **Fuel type** | Diesel |
| **Engine displacement / Cylinder** | 1,968 ccm / 4 |
| **Power** | 110 kW |
| **Gearbox / Number of gears** | Automatic / 7 |
| **Type of drive** | Front drive |
| **Type of vehicle** | Car station wagon |
| **Colour / colour code** | Deep Black Perleffekt |
| **Doors / Seats** | 5 / 5 |
| **Upholstery type** | Cloth |
| **Colour of upholstery** | Black |
| **readiness to drive** | Not roadworthy / moveable |

TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Mosolf SE & Co.KG
August-Horch-Straße 1
04519 Rackwitz

## Vehicle details

| | | | |
|---|---|---|---|
| **Maintenance booklet / proof** | digital proof / complete | **Next maintenance in** | 14,800 km |
| **Last service on / at** | 10/2026 at 190,483 km | | |
| **Key is / should be** | 2 / 2 | **FZG documents** | ZB#2 (B) was available (copy), ZB#1 (S) was not available. |
| | | **Letter No.** | GP794552 |
| **Previous damage / Accident** | Detectable | **Repainting** | Detectable |
| **Inspection conditions** | sufficient | **Lifting equipment / pit** | yes |
| **Test drive** | Not performed | **Engine function test** | With complaint |
| **readiness to drive** | Not roadworthy / moveable | | |
| **Manufacturer key number/ type code number** | 0603 / BZG 23496 | | |
| **Emission standard** | EURO6 | **fine dust sticker** | |
| **Permitted total weight** | 2,270 kg | **Empty weight** | |

## Tyres

### Mounted tyres

| # | Tyre size | Type of tyre | Manufacturer | Tread depth |
|---|---|---|---|---|
| 1) | 215/65 R17 103H | Winter tyres on Light alloy | Pirelli | 5mm / 5mm |
| 2) | 215/65 R17 103H | Winter tyres on Light alloy | Pirelli | 7mm / 7mm |

### Additional tyres

| # | Tyre size | Type of tyre | Manufacturer | Tread depth |
|---|---|---|---|---|
| 1) | 235/55 R18 100V | Summer tyres on Light alloy | Continental | 1mm / 2mm |
| 2) | 235/55 R18 100V | Summer tyres on Light alloy | Continental | 4mm / 4mm |

**Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.**

## Equipment

### Standard equipment

- Storage compartments in the overhead console
- Airbag, head airbag system including front side airbags
- Adaptive Cruise Control (ACC) "stop & go" with speed limiter
- third brake light
- Chrome trim on the side windows
- Silver anodized roof rails
- Diesel particulate filter
- Parking assistance
- Electronic parking brake including auto-hold function
- Automatic headlight control, with daytime running lights
- High beam control Light Assist
- Pedestrian detection
- Luggage compartment lighting
- Transmission: 7-speed DSG
- Rear window heated
- Rear window wiper with intermittent function
- ISOFIX mounting points, also for i-Size child car seats
- Air conditioning system "Air Care Climatronic"
- Front headrests
- Steering wheel: Multifunction steering wheel in leather, with paddle shifters
- Illuminated makeup mirrors in the sun visors
- Fatigue detection
- Emergency braking assistant "Front Assist"
- Upholstery: Cloth
- Radio
- Radio accessories: 8 speakers
- Rain sensor
- Wheels: AirStop tires 235/55 R 18, optimized for low rolling resistance
- Gearshift knob in leather
- electromechanical power steering
- Seats: Front passenger seat backrest folds down completely
- Seats: Lumbar support in the front
- Lane keeping assistant “Lane Assist”
- 12-volt socket
- Bumpers in body color
- Textile floor mats front and rear
- Prepared for later activation: Navigation function "Discover Media" incl. "Streaming & Internet"
- Central locking without safe locking, with remote control and 2 remote keys
- Airbag for driver and front passenger including knee airbag on the driver's side
- Electrically adjustable and heated exterior mirrors
- Exterior mirror housings painted silver
- Chrome applications on mirror adjustment switches, window regulator switches, door pull handles
- Decorative inlays "Horizon Black"
- Display: Digital Cockpit Pro, multicolor, various selectable info profiles
- Electronic Stability Program with counter-steering support
- Electric windows front and rear
- Windscreen made of laminated safety glass, heat and sound insulating
- Luggage compartment floor height adjustable in 2 stages
- Tailgate with electric opening and closing, adjustable opening angle
- Interior mirror automatically dimming
- LED license plate lighting
- Rear headrests (3)
- LED headlights
- Reading lights: 2 front and 2 rear
- Light in the front footwell
- front center armrest
- Non-smoking version
- Emergency call service
- Proactive occupant protection system in conjunction with "Front Assist"
- Radio accessories: Digital radio reception DAB+
- Tire pressure monitoring system
- Wheels: Tire Mobility Set omitted
- Wheels: Light alloy (4) "Frankfurt" 7 J x 18
- Drawers under the front seats
- Seat belts: Three-point automatic seat belts at the front with height adjustment and belt tensioner
- Seats: Comfort seats in the front
- Seats: Front seats with height adjustment
- Start-stop system with brake energy recuperation
- Power outlet: 2 USB-C ports on the front
- Telephone interface
- First aid kit, warning triangle and high-visibility vest
- Electronic immobilizer
- Green thermal insulation glazing, sides and rear

### Extra equipment

- Electrically adjustable, folding and heated exterior mirrors (with passenger-side mirror lowering function)
- Display: Head-up display
- Paint finish: Pearl effect
- Steering wheel: Multifunction steering wheel in leather, with paddle shifters, heated
- Mesh partition
- Package: "Easy Open & Close" with safe locking mechanism ("Easy Open & Close" - tailgate with sensor-controlled opening and closing, with remote unlocking - keyless locking and starting system "Keyless Access" with safe locking mechanism)
- Seats: ergoActive front seats (front passenger seat backrest not foldable - ergoActive front seats height-adjustable, seat and backrest tilt adjustable, thigh support longitudinally adjustable - front lumbar support electrically adjustable and with massage function - seat center panels of the front seats and the outer rear seats in microfleece "ArtVelours" - top comfort seats in front)
- Surround view "Area View" (incl. reversing camera "Rear View")
- Anti-theft alarm system with safe locking (anti-theft alarm system with interior monitoring, backup horn and tow-away protection, central locking with safe locking, remote control and 2 remote folding keys)
- Navigation system "Discover Pro" incl. "Streaming & Internet" (8 speakers - App-Connect incl. App-Connect Wireless for Apple CarPlay and Android Auto - Digital radio reception DAB+ - Navigation system "Discover Pro" incl. "Streaming & Internet" - Radio - Voice control - Traffic sign recognition)
- Park Assist system including parking aid
- Windows: Rear side windows and rear window tinted
- 230 volt socket
- "Comfort" telephone interface with inductive charging function (operation and display via multifunction display and touchscreen of the radio or radio navigation system as well as via multifunction steering wheel - hands-free system - Bluetooth audio - external antenna connection with LTE support - 2 USB interfaces, also for iPod/iPhone; 1 USB charging socket and multimedia socket AUX-IN)

## Brief expert findings

| | |
|---|---|
| Documents submitted | At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy) |
| VIN comparison | The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection. |
| Inspection | The inspection conditions were sufficient for the assessment of the vehicle.<br>Lifting equipment and/or a pit were available for examining the vehicle. |
| Test drive | No test drive/shunting maneuver was carried out during the inspection of the vehicle. |
| Engine function test | An engine test run was performed, problem has been detected<br>This is due to the following reason.:<br>Motorkontrolle Leuchtet |
| readiness to drive | The vehicle was not capable of driving under its own power at the time of inspection, but can be moved on its own axle with the aid of assistance. |

## Value reducing factors

| No. | Component group | Description |
|---|---|---|
| 1 | Door - rear left side | Door - Soiled - Conditioning |
| 2 | Instrument panel | Indicator light (Ad Blue prüfen) - on - Diagnosed and repair if necessary |
| 3 | Seat - front | Seat cover - right side - Soiled - Clean |
| 4 | Bonnet | Insulation lining - Broken / torn - Replace |
| 5 | Interior | Interior - Scratch(es) - Loss in value |
| 6 | Instrument panel | Indicator light (Motorkontrolle) - on - Perform diagnosis |
| 7 | 2nd wheel set | 2 tyres (Reifen außen Kante abgefahren) - Does not meet the leasing specifications - Replace |
| 8 | Trim / covers | Boot lining (Rechts) - Scratched - Replace |
| 9 | Boot lid / rear door | Boot lid (Teillackierung) - Scratch(es) - Paint |

## Wear and tear

| No. | Component group | Description |
|---|---|---|
| 1 | Rear bumper | Rear bumper - Scratch(es) - No deduction |
| 2 | Trim / covers | Carpet - front left side - Scratch(es) - No deduction |
| 3 | Boot lid / rear door | Trim - standard - lower - Scratch(es) - No deduction |
| 4 | Trim / covers | Boot lining (Links) - Scratch(es) - No deduction |
| 5 | 2nd wheel set | Wheel cover set - complete (Sind auf den Winterräder montiert) - Missing - No deduction |

The vehicle shows signs of wear and tear commensurate with its age and use.

## Previous damages

| No. | Previous damage | Extent of damage (Net) |
|---|---|---|
| 1 | Front, Provided by user / customer, from 6 Nov 2024 | 740,87 € |
| 2 | Rear, Provided by user / customer, from 6 Nov 2024 | 1.005,35 € |
| 3 | Side right, Provided by user / customer, from 6 Nov 2024 | 3.565,17 € |

## Repainting

| No. | Repainting |
|---|---|
| 1 | Boot lid / rear door, Bonnet, Side panel - rear right side, Door - rear right side, Professionally carried out, Invoice of repair done Non-existent |

## Paint coat thickness measurement

| | | | |
|---|---|---|---|
| Boot lid / rear door | 359 µm | Bonnet | 293 µm |
| Side panel - rear right side | 686 µm | Door - rear right side | 322 µm |

## Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
  *(Delivery by third-party service providers)*
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
  *(Functional testing of driver assistance systems is not included in the scope of services!)*
- a photographic documentation of the vehicle

## Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

## Previous damages

According to available information previous damages were repaired at the vehicle. Traces of repairs, which allow conclusions about the area of repair, were not recognizable during the inspection.

## Comments

-Der montierte Winterradsatz ist kein Bestandteil des
Auslieferungsumfangs.
- Nabendeckel der Winterräder gehören zu den Sommerräder




**Figure 1:** Diagonal front (left)




**Figure 2:** Diagonal front (right)




**Figure 3:** Diagonal rear (left)




**Figure 4:** Diagonal rear (right)



**Figure 5:** Interior - front



**Figure 6:** Interior - rear




**Figure 7:** Instrument cluster



**Figure 8:** Instrument panel

**Figure 9:** Interior 360° view (Online Link)



**Figure 10:** Cargo area





**Figure 11:** VIN




**Figure 12:** Mounted tyres





**Figure 13:** Documents



**Figure 14:** Documents





**Figure 15:** Documents




**Figure 16:** Documents



**Figure 17:** Documents



**Figure 18:** Additional tyres





**Figure 19:** Navigation



**Figure 20:** Misc.



**Figure 21:** Misc.




**Figure 22:** Misc.



**Figure 23:** Misc.



**Figure 24:** Misc.




**Figure 25:** Misc.




**Figure 26:** Misc.




**Figure 27:** Misc.




**Figure 28:** Misc.




**Figure 29:** Misc.



**Figure 30:** Misc.



**Figure 31:** Misc.



**Figure 32:** Misc.



**Damage 1:** Door - rear left side: Door - Soiled - Conditioning




**Damage 1:** Door - rear left side: Door - Soiled - Conditioning




**Damage 2:** Instrument panel: Indicator light (Ad Blue prüfen) - on - Diagnosed and repair if necessary



**Damage 3:** Seat - front: Seat cover - right side - Soiled - Clean



**Damage 3:** Seat - front: Seat cover - right side - Soiled - Clean



**Damage 3:** Seat - front: Seat cover - right side - Soiled - Clean



**Damage 3:** Seat - front: Seat cover - right side - Soiled - Clean



**Damage 4:** Bonnet: Insulation lining - Broken / torn - Replace



**Damage 4:** Bonnet: Insulation lining - Broken / torn - Replace



**Damage 5:** Interior: Interior - Scratch(es) - Loss in value



**Damage 5:** Interior: Interior - Scratch(es) - Loss in value




**Damage 5:** Interior: Interior - Scratch(es) - Loss in value



**Damage 5:** Interior: Interior - Scratch(es) - Loss in value



**Damage 5:** Interior: Interior - Scratch(es) - Loss in value



**Damage 5:** Interior: Interior - Scratch(es) - Loss in value



**Damage 5:** Interior: Interior - Scratch(es) - Loss in value



**Damage 5:** Interior: Interior - Scratch(es) - Loss in value



**Damage 5:** Interior: Interior - Scratch(es) - Loss in value




**Damage 6:** Instrument panel: Indicator light (Motorkontrolle) - on - Perform diagnosis




**Damage 6:** Instrument panel: Indicator light (Motorkontrolle) - on - Perform diagnosis



**Damage 7:** 2nd wheel set: 2 tyres (Reifen außen Kante abgefahren) - Does not meet the leasing specifications - Replace



**Damage 7:** 2nd wheel set: 2 tyres (Reifen außen Kante abgefahren) - Does not meet the leasing specifications - Replace



**Damage 7:** 2nd wheel set: 2 tyres (Reifen außen Kante abgefahren) - Does not meet the leasing specifications - Replace



**Damage 7:** 2nd wheel set: 2 tyres (Reifen außen Kante abgefahren) - Does not meet the leasing specifications - Replace



**Damage 7:** 2nd wheel set: 2 tyres (Reifen außen Kante abgefahren) - Does not meet the leasing specifications - Replace



**Damage 8:** Trim / covers: Boot lining (Rechts) - Scratched - Replace



**Damage 8:** Trim / covers: Boot lining (Rechts) - Scratched - Replace



**Damage 8:** Trim / covers: Boot lining (Rechts) - Scratched - Replace



**Damage 9:** Boot lid / rear door: Boot lid (Teillackierung) - Scratch(es) - Paint





**Damage 9:** Boot lid / rear door: Boot lid (Teillackierung) - Scratch(es) - Paint




**Wear and tear 1:** Rear bumper: Rear bumper - Scratch(es) - No deduction



**Wear and tear 1:** Rear bumper: Rear bumper - Scratch(es) - No deduction



**Wear and tear 1:** Rear bumper: Rear bumper - Scratch(es) - No deduction



**Wear and tear 2:** Trim / covers: Carpet - front left side - Scratch(es) - No deduction



**Wear and tear 2:** Trim / covers: Carpet - front left side - Scratch(es) - No deduction




**Wear and tear 2:** Trim / covers: Carpet - front left side - Scratch(es) - No deduction



**Wear and tear 3:** Boot lid / rear door: Trim - standard - lower - Scratch(es) - No deduction



**Wear and tear 3:** Boot lid / rear door: Trim - standard - lower - Scratch(es) - No deduction



**Wear and tear 4:** Trim / covers: Boot lining (Links) - Scratch(es) - No deduction



**Wear and tear 4:** Trim / covers: Boot lining (Links) - Scratch(es) - No deduction



**Wear and tear 4:** Trim / covers: Boot lining (Links) - Scratch(es) - No deduction



**Wear and tear 5:** 2nd wheel set: Wheel cover set - complete (Sind auf den Winterräder montiert) - Missing - No deduction



**Wear and tear 5:** 2nd wheel set: Wheel cover set - complete (Sind auf den Winterräder montiert) - Missing - No deduction



**Wear and tear 5:** 2nd wheel set: Wheel cover set - complete (Sind auf den Winterräder montiert) - Missing - No deduction




**Repainting 1:** Boot lid / rear door, Bonnet, Side panel - rear right side, Door - rear right side




**Repainting 1:** Boot lid / rear door, Bonnet, Side panel - rear right side, Door - rear right side




**Repainting 1:** Boot lid / rear door, Bonnet, Side panel - rear right side, Door - rear right side




**Repainting 1:** Boot lid / rear door, Bonnet, Side panel - rear right side, Door - rear right side




**Repainting 1:** Boot lid / rear door, Bonnet, Side panel - rear right side, Door - rear right side




**Repainting 1:** Boot lid / rear door, Bonnet, Side panel - rear right side, Door - rear right side




**Boot lid / rear door:** 359 µm




**Boot lid / rear door:** 359 µm




**Bonnet:** 293 µm




**Side panel - rear right side:** 686 µm




**Side panel - rear right side:** 686 µm




**Door - rear right side:** 322 µm