TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Hartmann Fleet Professionals GmbH
Industriestraße 11
36272 Niederaula

Expertise

Protocol number: 48563161
Order No. / Reference: 27204855
Inspection date: 4 Nov 2026

Manufacturer: Kia	Model: EV6 58-kWh
VIN: KNAC481AFP5120570	





Vehicle details

Manufacturer / Type / Model / Equipment	
Kia EV6 58-kWh	
Vehicle Identification number	KNAC481AFP5120570
Mileage (Read)	105,290 km
First registration	10 Aug 2023
Number of holders	1
Next periodical technical inspection	08/2028
(Report on hand)	
Fuel type	Electric
Power	56 kW
Gearbox / Number of gears	Direct drive / 1
Type of drive	Rear drive
Type of vehicle	Multipurpose vehicle
Colour / colour code	Aurora Schwarz Metallic
Doors / Seats	5 / 5
Upholstery type	Artificial leather
Colour of upholstery	Black-Light grey
Vehicle with smoke odor	no

Vehicle details

Maintenance booklet / proof	digital proof / complete	**Next maintenance in**	650 Tag(e)
Last service on / at	08/2026 at 98,667 km		
Key is / should be	2 / 2	**FZG documents**	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	GV863305
Previous damage / Accident	None detectable	**Repainting**	Detectable
Inspection conditions	sufficient	**Lifting equipment / pit**	yes
Test drive	Not performed	**Engine function test**	Performed
Manufacturer key number/ type code number	2233 / ABA 00011		
Emission standard	2017/1151	**fine dust sticker**	
Permitted total weight	2,425 kg	**Empty weight**	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	235/55 R19 105H	Winter tyres on Light alloy	Goodyear	3mm / 3mm
2)	235/55 R19 105H	Winter tyres on Light alloy	Goodyear	5mm / 5mm

Additional tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	235/55 R19 105V	Summer tyres on Light alloy	Nexen	3mm / 3mm
2)	235/55 R19 105V	Summer tyres on Light alloy	Nexen	5mm / 5mm

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

Equipment

Standard equipment

- ABS (Anti-lock Braking System)
- Airbag: Front center airbag
- Alternator Management System (AMS)
- Highway Driving Assist (HDA)
- Heated and electrically folding exterior mirrors
- Battery: Battery preheating system
- Bluetooth hands-free system
- Roof spoiler
- Drive Mode Select
- twilight sensor
- Electric windows front and rear
- Forward Collision Avoidance Assist (FCA-JX)
- Forward Collision Avoidance Assist (FCA)
- Countersteering support
- Adaptive cruise control including Stop&Go function
- Transmission: Direct drive
- Back window, heater
- Auto-dimming interior rearview mirror
- Rear Occupant Alert (ROA), sensor-controlled
- Child safety lock on the rear doors (manual)
- Automatic climate control with dual-zone control
- Paint finish: Runway Red Metallic
- Type 2 to Type 2 charging cable
- LED headlights
- LED spotlights on the C-pillar
- Steering wheel: Heated leather steering wheel
- Armrest - centre, rear
- Navigation: Kia map navigation (12.3 inch)
- On-board charger (3-phase, AC)
- Parking brake, electronic (EPB)
- Front and rear parking sensors (PDW fr/rr)
- Upholstery: Suede-look vegan cover in "Dark" (Black)
- Radio accessories: USB port
- Tire Pressure Monitoring System (TPMS)
- Wheels: 19-inch alloy wheels
- Fast charging system (400 V, 800 V, DC)
- Front seat belts are height-adjustable
- Seats: Driver's seat height adjustable
- Seats: Lumbar support for driver, electrically adjustable
- Seats: Premium Relaxation Seat (Passenger)
- Seats: Premium Relaxation Seat (Driver)
- Seats: Rear seat heating
- Seats: Front seat ventilation
- Smart Key and Start Button
- Sport pedals
- Traffic jam assistant (Lane Follow Assist, LFA)
- Door handles with automatic flush function
- USB port at the rear, on the backrest of the front seats
- V2L (Vehicle-to-Load): Charging of external devices with a maximum of 3.6 kW
- Airbag: 2 front airbags
- Airbag: Front side airbags and full-length curtain airbags
- Ambient lighting
- Highway Assistant II (Highway Driving Assist, HDA II)
- Exterior mirrors in piano black
- Hill Start Assist Control (HAC)
- Brake light: Third with LED
- Display: Integrated digital display with a 31.2 cm (12.3 inch) screen diagonal, curved
- ESC (Electronic Stability Program)
- High beam assist
- Front Collision Warning (Forward Collision Avoidance Assist - turning function and cross traffic)
- Intelligent Speed Limit Assist (ISLA)
- Cruise control, navigation-based
- Electric tailgate (including sensor control)
- Inductive charging station for smartphones
- Rear Occupant Alert (ROA)
- ISOFIX mounts on outer rear seats
- Child safety lock in the rear doors (sensor-controlled)
- Active front headrests
- Charging port: Adapter for V2L use
- LED taillights
- LED headlights, dual adaptive
- Steering wheel adjustable for height and reach
- Steering wheel: Multifunction steering wheel
- Multiple Collision Braking (MCB)
- Emergency call service eCall
- Online services Kia Connect with Kia Live
- Rear parking sensors (PDW)
- Upholstery: Fabric/faux leather
- Privacy glass (from the B-pillar back)
- Rain sensor
- Regenerative braking paddles on the steering wheel
- Rear View Monitor (RVM) camera
- Power steering
- Seats: Passenger seat height adjustable
- Seats: Lumbar support, passenger, electrically adjustable
- Seats: Memory function for driver's seat, driver and passenger seats electrically adjustable
- Seats: Rear seat backrest split 60:40, foldable
- Seats: Heated front seats
- Seats: Ski pass-through
- Solar glass windshield and front side windows
- Lane keeping assist including drowsiness warning
- Blind spot assist active
- Door handles with manual flush function
- USB port, front tunnel console (2 pieces)
- Immobiliser
- Central locking with remote control

Extra equipment

- 77.4 kWh battery
- Glass sunroof, hinged, electric
- Paint finish: Metallic paint
- GT-line package
- Detachable towbar
- Glass sunroof, hinged, electric JATO007
- Charging adapter Schuko plug to Type 2 (10A)
- Heat pump to improve real-world range at low outside temperatures

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. Lifting equipment and/or a pit were available for examining the vehicle.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.

Value reducing factors

No.	Component group	Description
1	Door - rear left side	Door edge - Scratch(es) - Smart repair
2	Door - front left side	Door edge - Scratch(es) - Smart repair
3	Side panel - rear left side	Sill - Scratch(es) - Smart repair
4	Front bumper	Front bumper (Plus Steinschläge) - Scratched - Paint
5	Bonnet	Bonnet - Stone chips - Paint

Repainting

No.	Repainting
1	Mudguard - right side, Professionally carried out, Invoice of repair done Non-existent
2	Side panel - rear right side, Professionally carried out, Invoice of repair done Non-existent
3	Door - rear right side, Professionally carried out, Invoice of repair done Non-existent
4	Door - front right side, Professionally carried out, Invoice of repair done Non-existent

Paint coat thickness measurement

Mudguard - right side	199 µm	Side panel - rear right side	190 µm
Door - rear right side	195 µm	Door - front right side	198 µm

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
  (Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
  (Functional testing of driver assistance systems is not included in the scope of services!)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

No apparent prior damage that had been repaired could be found on the vehicle.

Comments

- Winterradsatz ist kein Bestandteil des Auslieferungsumfangs.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)



Figure 5: Interior - front



Figure 6: Interior - rear

TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Hartmann Fleet Professionals GmbH
Industriestraße 11
36272 Niederaula



Figure 7: Instrument cluster



Figure 8: Instrument panel

Figure 9: Interior 360° view (Online Link)



Figure 10: Cargo area



Figure 11: VIN



Figure 12: Mounted tyres




Figure 13: Documents




Figure 14: Documents



Figure 15: Additional tyres




Figure 16: Navigation




Figure 17: Misc.



Figure 18: Misc.



Figure 19: Misc.




Figure 20: Misc.



Figure 21: Misc.



Figure 22: Misc.



Figure 23: Misc.



Figure 24: Misc.




Figure 25: Misc.




Figure 26: Misc.




Figure 27: Misc.




Figure 28: Misc.




Figure 29: Misc.



Figure 30: Misc.




Figure 31: Misc.



Figure 32: Misc.



Figure 33: Misc.




Figure 34: Misc.



Figure 35: Misc.




Damage 1: Door - rear left side: Door edge - Scratch(es) - Smart repair




Damage 1: Door - rear left side: Door edge - Scratch(es) - Smart repair



Damage 1: Door - rear left side: Door edge - Scratch(es) - Smart repair




Damage 2: Door - front left side: Door edge - Scratch(es) - Smart repair



Damage 2: Door - front left side: Door edge - Scratch(es) - Smart repair



Damage 2: Door - front left side: Door edge - Scratch(es) - Smart repair




Damage 3: Side panel - rear left side: Sill - Scratch(es) - Smart repair



Damage 3: Side panel - rear left side: Sill - Scratch(es) - Smart repair



Damage 4: Front bumper: Front bumper (Plus Steinschläge) - Scratched - Paint



Damage 4: Front bumper: Front bumper (Plus Steinschläge) - Scratched - Paint



Damage 4: Front bumper: Front bumper (Plus Steinschläge) - Scratched - Paint



Damage 4: Front bumper: Front bumper (Plus Steinschläge) - Scratched - Paint




Damage 4: Front bumper: Front bumper (Plus Steinschläge) - Scratched - Paint



Damage 4: Front bumper: Front bumper (Plus Steinschläge) - Scratched - Paint



Damage 4: Front bumper: Front bumper (Plus Steinschläge) - Scratched - Paint



Damage 4: Front bumper: Front bumper (Plus Steinschläge) - Scratched - Paint




Damage 4: Front bumper: Front bumper (Plus Steinschläge) - Scratched - Paint




Damage 5: Bonnet: Bonnet - Stone chips - Paint




Damage 5: Bonnet: Bonnet - Stone chips - Paint



Damage 5: Bonnet: Bonnet - Stone chips - Paint



Damage 5: Bonnet: Bonnet - Stone chips - Paint



Damage 5: Bonnet: Bonnet - Stone chips - Paint



Damage 5: Bonnet: Bonnet - Stone chips - Paint



Damage 5: Bonnet: Bonnet - Stone chips - Paint



Repainting 1: Mudguard - right side



Repainting 1: Mudguard - right side



Repainting 2: Side panel - rear right side



Repainting 2: Side panel - rear right side



Repainting 3: Door - rear right side



Repainting 3: Door - rear right side



Repainting 4: Door - front right side

TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Hartmann Fleet Professionals GmbH
Industriestraße 11
36272 Niederaula



Repainting 4: Door - front right side