VOLKSWAGEN ID.5

Vehicle information


Brand:	**VOLKSWAGEN**	License plate:	**2DMW565**
Gearbox:		Body color:	
Model:	**ID.5**	LEVEL:	**WVGZZZE2ZPP514983**
Fuel type:		Power:	**128 kW**
Version:	**BEV 82KWH 128 KW PRO AUTO**	First registration	**28/04/2023**
Mileage:	**145987 km**	Number of doors:	

Summary of damages


Back	2
RIGHT	1
Interior	3
Roof & other	2

Commercial photos































Options according to the inspector

GPS	**Yes**

Damages

Bodywork


Damaged -


Acceptable.

Roof & other



















Trunk/
Hatchback Dent(s)
LI - Repair and Paint (Complete)
Rear








Damaged **Interior**
- Acceptable
Interior











Interior
Odor
Treatment: Ozone Treatment

Rear bumper molding, Smart repair
claw(s), rear










Front **Right Door -**
Dent(s) and Scratch(es)
- Repair and Paint (Complete)






AVG Burnt
Smart Repair
Interior **Floor Mats**





Fuel filler flap
deformed/forced
- Replace and paint
roof & other





Tires

Front Left
4 Seasons
Aluminum
235/55/19/105/W
Bridgestone
6.0 mm
Front Right
4 Seasons
Aluminum
235/55/19/105/W
Bridgestone
6.0 mm
Left Back
4 Seasons
Aluminum
255/50/19/107/W
Bridgestone
7.0 mm
Rear Right
4 Seasons
Aluminum
255/50/19/107/W
Bridgestone
7.0 mm

Controls

Category	**Private vehicle**	Registration certificate - home address section	**No**
Vehicle registration certificate	**Yes**	Certificate of Conformity	**Yes**
Compressor	**Yes**	Interview	**OK**
Repair kit	**Yes**	Number of charging cables (220V)	**1**
Number of charging cables (fast charging)	**1**	Total number of keys	**2**
Charge level	**80**	Factory reset	**Yes, the vehicle has been reset to factory settings.**
SOH	**95.0**	Type of maintenance log	**Digital interview**

Information on the content and scope of the inspection report:

- The evaluation is based on the sales standards specified by the client.
- Acceptable wear and tear according to sales standards is not always documented in this condition report.
- The specified repair methods and/or resulting repair times were determined taking into account modern industrial repair methods.
- The reseller must assess individual repair costs.
- The inspection was carried out without dismantling. Macadam cannot be held responsible for any missing information. For further information, please contact the seller.