MACADAM

BYD Atto 3 '22 BEV

Vehicle information

Make:**BYD**
License:**S887BK**
Gearbox:**Automatic**
Body color:
Model:**Atto 3 '22 BEV**
VIN:**LGXCE4CB0N2082782**
Fuel type:**Electric**
Power:**150 kW**
Version:**Atto 3 60kWh FWD Design**
First registration**29/12/2022**
Mileage:**163037 km**
N° of doors:

Damage summary

Front	1
Interior	4
Left	2
Right	2

Commercial pictures











S-887-BK











13:10
km/h
0
kW
273
km
65%
Standard OK ECO
P
ODO 163037 km




LGXCE4CB0N2082782
















Settings
P


Search for...
Nijkerk, Gelderland







Options according to the inspector

Central consol F**Yes**
GPS**Yes**
Headlights Xenon/LED/Laser**Yes**
Panoramic roof**Yes**
Radio multimedia**Yes**
Rear view camera**Yes**
Sun Roof electric**Yes**
Telephone equipment**Yes**

Damages

Alloy rim FL
Scratch(es)
Repair and paint (complete)
Left





Alloy rim RR
Rust
Repair and paint (complete)
Right





Bumper F
Scratch(es)
Repair and paint (complete)
Front






Door FL
Scratch(es)
Repair and paint (complete)
Left






Door RR
Dent(s) and scratch(es)
Repair and paint (complete)
Right









Gear shift lever knob
Worn
Replace
Interior






Seat cover FL
Worn
Replace
Interior





Shutter / cover
Scratch(es)
Replace
Interior





User's manual
Missing
Replace
Interior

Tyres

Location	Type	Rim	Measures	Make	Depth
Front Left					
Summer	235/50/18/101/Y			Vredestein	4.5 mm
Front Right					
Summer	235/50/18/101/Y			Vredestein	4.4 mm
Rear Left					
Summer	235/50/18/101/Y			Vredestein	4.7 mm
Rear Right					
Summer	235/50/18/101/Y			Vredestein	4.4 mm

Checks

CO2 Emission	**0**
Digital maintenance	**Yes**
Luggage cover	**Yes**
Number head rests	**5**
Number of charging cables (rapid charge)	**1**
Number of keys total	**2**
Reset to factory settings	**Yes, vehicle is reset to factory settings**
Service book	**No**
User's manual	**No**

Information on the content and the scope of the inspection report:

- The assessment is based on the sales standards specified by the customer.
- Acceptable usage damages according to the sales standards are not always documented in this status report.
- The specified repair methods and/or resulting repair times have been determined, taking into account modern industrial repair methods.
- The purchasing dealer should assess individual repair costs.
- The inspection was carried out in a non-disassembly condition. Macadam cannot be held responsible for any missing information. For further information, please contact the seller.