TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Mosolf SE & Co.KG
Faberweg 25
73230 Kirchheim unter Teck

Expertise

Protocol number: 48463748
Order No. / Reference: 27205060
Inspection date: 30 Oct 2026

Manufacturer: Opel	Model: Combo Cargo XL 1.5 D EHZ Autm.
VIN: W0VEFYHZ3NJ807696	





Vehicle details

Manufacturer / Type / Model / Equipment	
Opel Combo Cargo XL 1.5 D EHZ Autm.	
Vehicle Identification number	W0VEFYHZ3NJ807696
Mileage (Read)	45,593 km
First registration	29 Mar 2023
Number of holders	1
Next periodical technical inspection	09/2027
(Report on hand)	
Fuel type	Diesel
Engine displacement / Cylinder	1,499 ccm / 4
Power	96 kW
Gearbox / Number of gears	Automatic / 8
Type of drive	Front drive
Type of vehicle	Van
Colour / colour code	jadeweiss
Doors / Seats	4 / 2
Upholstery type	Cloth
Colour of upholstery	Grey-Black
Vehicle with smoke odor	no

TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Mosolf SE & Co.KG
Faberweg 25
73230 Kirchheim unter Teck

Vehicle details

Maintenance booklet / proof	digital proof / complete	**Next maintenance in**	23 Monat(e)
Last service on / at	10/2024 at 30,468 km		
Key is / should be	2 / 2	**FZG documents**	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	GQ357210
Previous damage / Accident	None detectable	**Repainting**	None detectable
Inspection conditions	sufficient	**Lifting equipment / pit**	yes
Test drive	Not performed	**Engine function test**	Performed
Manufacturer key number/ type code number	1844 / AGY 01495		
Emission standard	EURO6	**fine dust sticker**	
Permitted total weight	2,380 kg	**Empty weight**	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	205/60 R16 96H	Winter tyres on Steel	Goodyear	5mm / 5mm
2)	205/60 R16 96H	Winter tyres on Steel	Goodyear	5mm / 5mm

Additional tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	205/60 R16 96H	Summer tyres on Steel	Michelin	5mm / 5mm
2)	205/60 R16 96H	Summer tyres on Steel	Michelin	5mm / 5mm

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

Equipment

Standard equipment

- Cover strip for sliding door track (in black)
- ABS including brake assist and adaptive brake light
- Driver's side airbag
- Anti-lock braking system (ABS) with cornering brake control and brake assist
- Exterior mirrors, electrically adjustable, heated and manually folding
- Exterior mirror housings in black
- Hill Start Assist
- On-board computer
- Tachometer
- Third brake light
- Deletion: Interior rearview mirror
- Electric front windows
- Cruise control (steering wheel remote control)
- Seat belts: 3-point safety belts in the front
- Air conditioning, front, with particle and odor filter (recirculation mode, manual - glove compartment, split)
- Leather steering wheel, flattened at the bottom with steering wheel remote control (with paddle shifters)
- Upholstery: Cloth
- Radio accessories: Digital radio reception DAB+ (Digital Audio Broadcasting) (Offers a wider selection of radio programs. Digitally broadcast radio stations and traffic information can be received.)
- Tire pressure monitoring system
- Wheels: Tire repair kit (with tire sealant and 12-volt compressor (without jack))
- Visibility equipment (rain sensor - high beam assist - 2 folding ignition keys)
- Start/Stop System
- 12-volt power outlet in the center console
- Traction control with engine and brake intervention (TC Plus)
- Doors: Sliding door, passenger side, sheet metal
- Immobiliser
- Central locking with remote control
- Storage compartments (storage compartment in the instrument panel, driver's side, closed - storage compartment in the center console, front - storage shelf above the windshield, open - storage compartment in the front doors, suitable for 1.5-liter beverage bottles - glove compartment, closed - storage compartment on the dashboard, passenger side, closed)
- Battery discharge protection
- Floor covering: Cargo area floor, painted
- Diesel particulate filter, maintenance-free (incl. SCR catalyst with AdBlue)
- Electronic Stability Program (ESP Plus)
- Driver information display - LCD, black surround
- Speed limiter
- Transmission: 8-speed automatic
- Rear wing doors, asymmetrically split, sheet metal, 180° opening angle
- Headrests (2), front, height adjustable
- Steering wheel remote control
- Steering column, adjustable for reach and height
- Radio BT (Audio: - Bluetooth audio streaming Phone: - Hands-free calling via Bluetooth interface - Display of phonebook and call lists - Up to 5 mobile phones can be paired General: - Use of the voice control of the paired smartphone possible (e.g. Siri, Google voice control) - USB interface - 4 speakers)
- Side protection strips (in black)
- Speed-sensitive power steering
- Seats: Single passenger seat, fixed
- Seats: Driver's seat manually adjustable in 4 ways (length and backrest angle)
- Daytime running light
- Partition wall, closed
- Doors: Sheet metal insert, driver's side in the 2nd row
- Lashing eyes (6) in the cargo area
- Heat-insulating glazing, tinted
- Central locking: Ignition keys (2), one of which is foldable

Extra equipment

- Cool & Sound Package 2
- Load securing
- Front seat heating
- Sortimo installations
- electric front windows
- Package: Design (side protection strip in body color - front apron in body color - door handles in body color - exterior mirror housings in black - steel wheels, 6½ J x 16 - wheel cover, full surface - LED daytime running lights)

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. Lifting equipment and/or a pit were available for examining the vehicle.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.

Value reducing factors

No.	Component group	Description
1	Wheel / tyres	Wheel cover - rear left side - Scratched - Replace
2	Side panel - rear right side	Interior trim - Glued / labelled - De-glue / neutralise
3	Rear bumper	Rear bumper - Scratch(es) - Smart repair
4	Roof	Roof - dent(s) - Repair and paint

Wear and tear

No.	Component group	Description
1	Misc.	Inspection / maintenance (Letzeter Eintrag fehlt.) - No evidence - Loss in value
2	Bonnet	Bonnet (Lack ausgeblichen) - Paint defect - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
  (Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
  (Functional testing of driver assistance systems is not included in the scope of services!)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

No apparent prior damage that had been repaired could be found on the vehicle.

Comments

- Winterradsatz ist kein Bestandteil des Auslieferungsumfangs.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)



Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel

Figure 9: Interior 360° view (Online Link)



Figure 10: Cargo area




Figure 11: VIN



Figure 12: Mounted tyres




Figure 13: Documents



Figure 14: Documents



Figure 15: Documents



Figure 16: Additional tyres




Figure 17: Navigation




Figure 18: Misc.



Figure 19: Misc.



Figure 20: Misc.



Figure 21: Misc.



Figure 22: Misc.




Figure 23: Misc.



Figure 24: Misc.



Damage 1: Wheel / tyres: Wheel cover - rear left side - Scratched - Replace



Damage 2: Side panel - rear right side: Interior trim - Glued / labelled - De-glue / neutralise



Damage 2: Side panel - rear right side: Interior trim - Glued / labelled - De-glue / neutralise



Damage 3: Rear bumper: Rear bumper - Scratch(es) - Smart repair



Damage 3: Rear bumper: Rear bumper - Scratch(es) - Smart repair



Damage 3: Rear bumper: Rear bumper - Scratch(es) - Smart repair

TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Mosolf SE & Co.KG
Faberweg 25
73230 Kirchheim unter Teck



Damage 4: Roof: Roof - dent(s) - Repair and paint



Damage 4: Roof: Roof - dent(s) - Repair and paint