TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Hartmann Fleet Professionals GmbH
Leerenstraße 25
29683 Bad Fallingbostel

Expertise

Protocol number: 48136636
Order No. / Reference: 27110798
Inspection date: 14 Oct 2026

Manufacturer: Volkswagen	Model: Caddy Cargo 2.0 TDI BMT
VIN: WV1ZZZSK4RX014882	





Vehicle details

Manufacturer / Type / Model / Equipment	
Volkswagen Caddy Cargo 2.0 TDI BMT	
Vehicle Identification number	WV1ZZZSK4RX014882
Mileage (Read)	147,181 km
First registration	18 Sept 2023
Number of holders	1
Fuel type	Diesel
Engine displacement / Cylinder	1,968 ccm / 4
Power	75 kW
Gearbox / Number of gears	Manual / 6
Type of drive	Front drive
Type of vehicle	Van
Colour / colour code	Candy White (B9A)
Doors / Seats	4 / 2
Upholstery type	Cloth
Colour of upholstery	Black-Grey

Vehicle details

Maintenance booklet / proof	digital proof / complete	**Next maintenance in**	9,000 km
Last service on / at	08/2026 at 145,016 km		
Key is / should be	2 / 2	**FZG documents**	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	GV392864
Previous damage / Accident	None detectable	**Repainting**	None detectable
Inspection conditions	sufficient	**Lifting equipment / pit**	yes
Test drive	Not performed	**Engine function test**	Performed
Manufacturer key number/ type code number	0603 / CMF 00481		
Emission standard	EURO6	**fine dust sticker**	
Permitted total weight	2,220 kg	**Empty weight**	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	205/65 R15 94H	Summer tyres on Steel rim with wheel cover	Continental	6mm / 6mm
2)	205/65 R15 94H	Summer tyres on Steel rim with wheel cover	Continental	4mm / 4mm

Additional tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	205/65 R15 94H	Winter tyres on Light alloy	Continental	5mm / 5mm
2)	205/65 R15 94H	Winter tyres on Light alloy	Continental	6mm / 6mm

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

Equipment

Standard equipment

- Storage compartments: Glove compartment open
- Exterior mirrors: electrically adjustable
- Exterior mirror housings and door handles in black, sliding door track in silver
- Floor coverings: Carpet in the driver's cab
- third brake light
- Roof rail/roof rack preparation
- Three-point automatic seat belts (with front belt height adjustment and electric belt tensioners)
- Omission: Without additional child seat anchorage
- Automatic headlight control with daytime running lights
- Windows: Laminated glass front pane in heat-insulating glazing
- Cruise control system including speed limiter
- Halogen dual headlights-H7
- Heating and ventilation system in the driver's cab
- Interior lighting in the cargo area (1 light)
- Fuel fill quantity, standard fuel initial fill
- Diesel fuel system
- Headlight range control
- Center console with 2 universal cup holders
- Multifunctional camera
- Multimedia systems: 2 USB ports (Type C) in the center console, front
- eCall emergency call system
- Particulate filter: Diesel particulate filter (incl. SCR and AdBlue tank)
- Radio accessories: Digital radio reception DAB+
- Wheels/Tires: 205/65 R 15 99 H XL, optimized for low rolling resistance
- taillights
- Windscreen wiper intermittent control with light sensor
- Keys for locking system: 2 remote control flip keys
- Side indicator lights
- dimmable interior safety mirror
- Seats: Left and right seats in the 1st row (including headrests)
- Lane keeping assistant “Lane Assist”
- Bumper in grey
- Tire Mobility Set (12-volt compressor and tire sealant)
- Door trim and armrest in plastic
- Lashing points: 6 lashing points for securing cargo
- Warning tone and light for unfastened front seat belts
- Green thermal insulation glazing
- Additional dust protection seal on the outside
- Airbag for driver and front passenger (with passenger airbag deactivation)
- Reinforced battery (70 Ah/ 420 A)
- Operating voltage 12 V
- Brake booster
- Cockpit panel, matte
- Three-phase generator 140 A
- Electronic parking brake including auto-hold function
- Deletion: Without rear window (sheet metal)
- ESP Electronic Stability Program with Brake Assist (incl. Anti-lock Braking System (ABS), Traction Control (ASR), (EDS and MSR))
- Electric windows, front
- Transmission: 6-speed transmission
- Rear wing door (asymmetrically divided) without window cutout
- Instrument cluster (km/h) (displays for speed, total/trip distance, engine speed, fuel level and time)
- Steering wheel: Multifunction steering wheel
- Air vents, front, in matte black
- Multifunction display "Plus"
- Multi-collision brake
- Fatigue detection
- Emergency braking assistant "Front Assist" (with pedestrian and cyclist detection)
- Upholstery: Fabric, "Double Grid" design
- Radio accessories: 4 speakers
- Wheels, tires: Wheel covers
- Wheels/Tires: Tire pressure monitoring system
- Wheels/Tires: Steel wheels 6J x 15, in black
- Gearshift lever in plastic
- Sliding door, on the right in the passenger/cargo area
- Standard side panels in the cargo area
- Speed-sensitive power steering (Servotronic)
- Seats: Height adjustment for left seat, manual
- Sun visors without mirrors, with ticket pocket on the driver's side, plus airbag label on the sun visor
- Start-stop system (with brake energy recuperation)
- Telephone: Mobile phone interface
- Partition wall (tall) without window
- First aid kit, warning triangle and high-visibility vest
- Prepared for "We Connect" and "We Connect Plus"
- Electronic immobilizer
- Central locking with remote control and interior operation

Extra equipment

- Storage compartments: Glove compartment with lockable, illuminated flap
- Floor coverings, rubber floor covering in the cargo area
- Parking assistance
- Air conditioning
- Paint finish: Solid
- Package: Window package (Caddy Cargo with rear wing doors) (Rear wing doors with asymmetrically divided window cutouts - Fixed side window in the load/passenger compartment, front left - Fixed side window in the load/passenger compartment, front right - Fixed side window in the load/passenger compartment, rear left - Heated rear window - Fixed side window in the load/passenger compartment, rear right - Rear window wiper/washer system with intermittent function)
- Airbag: Side and head airbags for driver and front passenger, as well as a center airbag in the front.
- Floor coverings: Rubber floor covering in the driver's cab
- Deletion: Lettering on the rear (excluding lettering for type/model designation - excluding promotional lettering and decals)
- Radio "Composition Audio" 2 speakers
- Smoker's version
- Wheels/Tires: Spare wheel in driving tire size, steel (spare wheel in driving tire size, steel - on-board tools and jack)
- Sliding door, left side in the passenger/cargo area
- Power outlets: 12V socket (with cigarette lighter and ashtray)
- Partition wall (high) with grilles

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. Lifting equipment and/or a pit were available for examining the vehicle.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.

Value reducing factors

No.	Component group	Description
1	Misc.	Main inspection - No evidence - No deduction
2	Wheel / tyres	Wheel cover - front right side - Missing - Replace
3	Wheel / tyres	Wheel cover - rear right side - Broken / torn - Replace
4	Vehicle glazing	Door glass - front right side (Öffnet sich nicht vollständig) - Functional / admissibility - Perform diagnosis
5	Rear bumper	Rear bumper (unpainted) - Scratch(es) - Loss in value
6	Sill - right side	Sill - Scratch(es) - Smart repair
7	Sill - left side	Sill - Scratch(es) - Smart repair
8	Interior	Interior - Odour - Ozone treatment
9	Body	Body (Flugrost-Mehrkosten möglich) - Conditioning
10	Door - front left side	Door - Dent / paintcoat damage - Smart repair
11	Instrument panel	Centre console - front - Scratch(es) - Smart repair
12	Interior	Interior - Dent / paintcoat damage - Loss in value
13	Body	Body - Glued / labelled - De-glue / neutralise
14	Boot lid / rear door	Rear door - right side (unterhalb) - Corrosion - Repair and paint
15	Front bumper	Front bumper - Broken / torn - Replace
16	Sliding door - left side	Sliding door - Dent / paintcoat damage - Repair and paint
17	Sliding door, right	Sliding door - Dent / paintcoat damage - Repair and paint

Wear and tear

No.	Component group	Description
1	Multimedia system	Navigation data storage - Missing - No deduction
2	Bonnet	Bonnet - dent(s) - Smooth repair work
3	Door - front right side	Door - Dent / paintcoat damage - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
  (Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
  (Functional testing of driver assistance systems is not included in the scope of services!)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

No apparent prior damage that had been repaired could be found on the vehicle.

TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Hartmann Fleet Professionals GmbH
Leerenstraße 25
29683 Bad Fallingbostel



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)



Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel

Figure 9: Interior 360° view (Online Link)



Figure 10: Cargo area




Figure 11: VIN



Figure 12: Mounted tyres



Figure 13: Documents



Figure 14: Additional tyres



Figure 15: Additional tyres



Figure 16: Misc.



Figure 17: Misc.



Figure 18: Misc.



Figure 19: Misc.



Figure 20: Misc.




Figure 21: Misc.



Figure 22: Misc.



Figure 23: Misc.



Figure 24: Misc.



Figure 25: Misc.



Figure 26: Misc.



Figure 27: Misc.




Figure 28: Misc.




Damage 2: Wheel / tyres: Wheel cover - front right side - Missing - Replace



Damage 3: Wheel / tyres: Wheel cover - rear right side - Broken / torn - Replace



Damage 3: Wheel / tyres: Wheel cover - rear right side - Broken / torn - Replace



Damage 4: Vehicle glazing: Door glass - front right side (Öffnet sich nicht vollständig) - Functional / admissibility - Perform diagnosis



Damage 5: Rear bumper: Rear bumper (unpainted) - Scratch(es) - Loss in value



Damage 5: Rear bumper: Rear bumper (unpainted) - Scratch(es) - Loss in value



Damage 5: Rear bumper: Rear bumper (unpainted) - Scratch(es) - Loss in value



Damage 5: Rear bumper: Rear bumper (unpainted) - Scratch(es) - Loss in value



Damage 6: Sill - right side: Sill - Scratch(es) - Smart repair



Damage 6: Sill - right side: Sill - Scratch(es) - Smart repair



Damage 7: Sill - left side: Sill - Scratch(es) - Smart repair



Damage 7: Sill - left side: Sill - Scratch(es) - Smart repair



Damage 9: Body: Body (Flugrost-Mehrkosten möglich) - Conditioning



Damage 10: Door - front left side: Door - Dent / paintcoat damage - Smart repair



Damage 10: Door - front left side: Door - Dent / paintcoat damage - Smart repair



Damage 10: Door - front left side: Door - Dent / paintcoat damage - Smart repair



Damage 11: Instrument panel: Centre console - front - Scratch(es) - Smart repair



Damage 11: Instrument panel: Centre console - front - Scratch(es) - Smart repair



Damage 12: Interior: Interior - Dent / paintcoat damage - Loss in value



Damage 12: Interior: Interior - Dent / paintcoat damage - Loss in value



Damage 13: Body: Body - Glued / labelled - De-glue / neutralise




Damage 13: Body: Body - Glued / labelled - De-glue / neutralise



Damage 14: Boot lid / rear door: Rear door - right side (unterhalb) - Corrosion - Repair and paint



Damage 14: Boot lid / rear door: Rear door - right side (unterhalb) - Corrosion - Repair and paint



Damage 14: Boot lid / rear door: Rear door - right side (unterhalb) - Corrosion - Repair and paint



Damage 15: Front bumper: Front bumper - Broken / torn - Replace




Damage 15: Front bumper: Front bumper - Broken / torn - Replace




Damage 15: Front bumper: Front bumper - Broken / torn - Replace



Damage 16: Sliding door - left side: Sliding door - Dent / paintcoat damage - Repair and paint



Damage 16: Sliding door - left side: Sliding door - Dent / paintcoat damage - Repair and paint



Damage 16: Sliding door - left side: Sliding door - Dent / paintcoat damage - Repair and paint



Damage 16: Sliding door - left side: Sliding door - Dent / paintcoat damage - Repair and paint



Damage 16: Sliding door - left side: Sliding door - Dent / paintcoat damage - Repair and paint



Damage 17: Sliding door, right: Sliding door - Dent / paintcoat damage - Repair and paint



Damage 17: Sliding door, right: Sliding door - Dent / paintcoat damage - Repair and paint



Damage 17: Sliding door, right: Sliding door - Dent / paintcoat damage - Repair and paint



Damage 17: Sliding door, right: Sliding door - Dent / paintcoat damage - Repair and paint