DEKRA

DEKRA Automotive Solutions

Appraisal Report

Vehicle details

VIN	ZAC5JAC59 PJK08799	Registration date	10/07/2023	Exterior Color	Unknown
Brand	JEEP	Licence Plate	LB-GB 46E	Odometer	43 549 km
Model	AVENGER 54 kWh 115 kW Summit				

Inspection Details

Arrival Date	31/08/2026	Inspection ID	7159282	Inspection date	14/09/2026
Assign Date	31/08/2026	Fleet owner	Leasys Privat Leasing	Inspection loc.	Leasys AKB Buch
























Generic equipment

Removable element

Spare wheel kit	✓
Toolkit	✓
Rear parcel shelf	✓
Radio user manual	✓

Technical Document

User manual	✓
Warranty booklet	✓
Log books	✓
Spare key	✓
Key	✓
Remote key	✓
Service	✓

Tyres

Goodyear 215/55/18 V Summer 4.0 mm

Goodyear 215/55/18 V Summer 4.0 mm



Goodyear 215/55/18 V Summer 5.0 mm

Goodyear 215/55/18 V Summer 5.0 mm

Exception / Damage

DEKRA

DEKRA Automotive Solutions

Appraisal Report

1		Part	Alloy wheel 18"	Repair Time	0.50	Part Cost	242.26€
		Position	Back right	Repair Cost	70.00€	Gross Cost	312.26€
		Damages	Scratched	Paint Time	-	Depreciation %	20.00%
		Severity	-	Paint cost	-	Depreciation	- 62.45
		Repair mode	Replace	Flat Rate	-	**Net Cost**	**249.81€**
2		Part	Tyre	Repair Time	-	Part Cost	130.00€
		Position	Front right	Repair Cost	-	Gross Cost	130.00€
		Damages	Cut	Paint Time	-	Depreciation %	-
		Severity	-	Paint cost	-	Depreciation	-
		Repair mode	Replace	Flat Rate	-	**Net Cost**	**130.00€**
3		Part	Service 2	Repair Time	-	Part Cost	200.00€
		Position	-	Repair Cost	-	Gross Cost	200.00€
		Damages	Missing	Paint Time	-	Depreciation %	-
		Severity	-	Paint cost	-	Depreciation	-
		Repair mode	Replace	Flat Rate	-	**Net Cost**	**200.00€**
4		Part	Service 3	Repair Time	-	Part Cost	200.00€
		Position	-	Repair Cost	-	Gross Cost	200.00€
		Damages	Missing	Paint Time	-	Depreciation %	-
		Severity	-	Paint cost	-	Depreciation	-
		Repair mode	Replace	Flat Rate	-	**Net Cost**	**200.00€**
5		Part	Spoiler	Repair Time	1.30	Part Cost	-
		Position	Front	Repair Cost	182.00€	Gross Cost	332.00€
		Damages	Dented	Paint Time	1.00	Depreciation %	20.00%
		Severity	-	Paint cost	150.00€	Depreciation	- 66.40
		Repair mode	Repair	Flat Rate	-	**Net Cost**	**265.60€**
6		Part	Door	Repair Time	1.00	Part Cost	-
		Position	Front left	Repair Cost	140.00€	Gross Cost	140.00€
		Damages	Dented	Paint Time	-	Depreciation %	-
		Severity	-	Paint cost	-	Depreciation	-
		Repair mode	Smart Repair	Flat Rate	140.00€	**Net Cost**	**140.00€**
7		Part	Paint preparation	Repair Time	-	Part Cost	-
		Position	-	Repair Cost	-	Gross Cost	120.00€
		Damages	-	Paint Time	0.80	Depreciation %	20.00%
		Severity	-	Paint cost	120.00€	Depreciation	- 24.00
		Repair mode	Plastic paint	Flat Rate	-	**Net Cost**	**96.00€**

Summary Inspection

Gross Price	1,434.26€	Depreciation	-152.85€	Net Price	1,281.41€

DEKRA Automotive Solutions

Labor cost summary

	Hourly Rate	Time	Gross Price	Depreciation %	Depreciation	Net Price
Bodywork	140.00€	2.80	392.00€	12.86 %	-50.40€	341.60€
Paintwork	150.00€	1.00	150.00€	20.00 %	-30.00€	120.00€
Paint preparation	150.00€	0.80	120.00€	20.00 %	-24.00€	96.00€

Miscellaneous

	Gross Price	Depreciation %	Depreciation	Net Price
Small parts / disposal charge	0.00€	-	-	0.00€
Part Cost	772.26€	6.27 %	-48.45€	723.81€
Flat Rate	-400.00€	-	-	-400.00€