

MACDAM

Peugeot 5008 FL'21


Vehicle information



Make:	Peugeot	License:	
Gearbox:	MAN 6 VIT	Body color:	
Model:	5008 FL'21	VIN:	VF3MRHNSMLS319660
Fuel type:	Petrol	Power:	96 kW
Version:	5008 1.2PT 130 BL Active	First registration	25/01/2021
Mileage:	233711 km	N° of doors:	

Damage summary

Front	1
Interior	1
Left	3
Rear	6
Right	6

Commercial pictures





Options according to the inspector

Central consol F	Yes	GPS	Yes	Headlights Xenon/LED/Laser	Yes
Hook	Yes	Radio multimedia	Yes	Rear view camera	Yes
Telephone equipment	Yes				

Damages

Alloy rim FR
Scratch(es)
Repair and paint (complete)
Right



Bonnet
Stone chip(s)
Repair and paint (complete)
Front




Boot lid covering R
Scratch(es)
Smart repair
Rear



Bumper corner RL
Scratch(es)
Repair and paint (complete)
Rear



Bumper corner RR
Scratch(es)
Repair and paint (complete)
Rear



Bumper R
Scratch(es)
Smart repair
Rear



Door FL
Dent(s) and scratch(es)
Repair and paint (complete)
Left



Door RL
Dent(s) and scratch(es)
Repair and paint (complete)
Left



Door RR
Deformed / Strained
Repair and paint (complete)
Right




Door trim RR
Deformed / Strained
Replace
Right




Interior
Stain
Cleaning
Interior



Mirror side repeater R
Scratch(es)
Replace
Right



Rear window
Scratch(es)
Replace
Rear




Tailgate / Boot
Scratch(es)
Repair and paint (complete)
Rear



Wing RL
Dent(s) and scratch(es)
Repair and paint (complete)
Left



Wing RR
Dent(s) and scratch(es)
Repair and paint (complete)
Right



Wing trim RR
Scratch(es)
Replace
Right



Tyres	
	Front Left
	Winter
	215/65/17/99/H
	Michelin
	5.2 mm
	Front Right
	Winter
	215/65/17/99/H
	Michelin
	5.9 mm
	Rear Left
	Winter
	215/65/17/99/H
	Michelin
	7.0 mm
	Rear Right
	Winter
	215/65/17/99/H
	Michelin
	6.3 mm

Checks			
CO2 Emission	144	Digital maintenance	N/A
GPS storage	Yes	Luggage cover	Yes
Number head rests	5	Number of keys total	2
Reset to factory settings	Yes, vehicle is reset to factory settings	Service book	Yes
User's manual	Yes		

Information on the content and the scope of the inspection report:

- The assessment is based on the sales standards specified by the customer.
- Acceptable usage damages according to the sales standards are not always documented in this status report.
- The specified repair methods and/or resulting repair times have been determined, taking into account modern industrial repair methods.
- The purchasing dealer should assess individual repair costs.
- The inspection was carried out in a non-disassembly condition. Macadam cannot be held responsible for any missing information. For further information, please contact the seller.