TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Mosolf SE & Co.KG
August-Horch-Straße 1
04519 Rackwitz

Expertise

Protocol number: 48437725
Order No. / Reference: 27048971
Inspection date: 2 Nov 2026

Manufacturer: Opel	Model: Insignia Sports Tourer 2.0 Diesel Aut. Ultimate
VIN: W0VZS8GP3N1047825	





Vehicle details

Manufacturer / Type / Model / Equipment	
Opel Insignia Sports Tourer 2.0 Diesel Aut. Ultimate	
Vehicle Identification number	W0VZS8GP3N1047825
Mileage (Read)	151,472 km
First registration	15 Aug 2023
Number of holders	1
Next periodical technical inspection (Report on hand)	08/2028
Fuel type	Diesel
Engine displacement / Cylinder	1,995 ccm / 4
Power	128 kW
Gearbox / Number of gears	Automatic / 8
Type of drive	Front drive
Type of vehicle	Car station wagon
Colour / colour code	Jade Weiß
Doors / Seats	5 / 5
Upholstery type	Alcantara / cloth
Colour of upholstery	Black
readiness to drive	Not roadworthy / moveable

Vehicle details

Maintenance booklet / proof	digital proof / complete	**Next maintenance in**	69 %
Last service on / at	08/2026 at 142,210 km		
Key is / should be	2 / 2	**FZG documents**	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	GQ362001
Previous damage / Accident	Detectable	**Repainting**	None detectable
Inspection conditions	sufficient	**Lifting equipment / pit**	yes
Test drive	Not performed	**Engine function test**	Performed
readiness to drive	Not roadworthy / moveable		
Manufacturer key number/ type code number	1844 / AMC 00298		
Emission standard	EURO6	**fine dust sticker**	
Permitted total weight	2,215 kg	**Empty weight**	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	245/35 R20 95W	Summer tyres on Light alloy	Continental	5mm / 5mm
2)	245/35 R20 95W	Summer tyres on Light alloy	Continental	5mm / 5mm

Additional tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	245/45 R18 100V	Winter tyres on Light alloy	Bridgestone	4mm / 4mm
2)	245/45 R18 100V	Winter tyres on Light alloy	unterschiedliche Hersteller	4mm / 5mm

Replacement

Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
	Tirefit	Expiration date 10/2026		

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

Equipment

Standard equipment

- Storage compartments
- Airbag: Front airbags and side airbags, driver and front passenger
- Anti-lock braking system (ABS)
- Hill Start Assist
- third brake light
- Roof rails, silver anodized
- Diesel particulate filter
- Electronic brake force distribution (EBD)
- Electric windows front and rear
- Pedestrian protection including active hood
- luggage compartment cover
- Speed controller
- GS Line interior equipment
- rear window wiper
- Child safety lock in the rear doors, manual
- Front headrests
- Paint finish: Solid
- LED fog lights
- Steering column adjustable in height and length
- Illuminated makeup mirrors in both sun visors
- Package: Easy-Access
- Electric parking brake
- Upholstery: Alcantara trim, black
- Radio: Digital radio reception DAB+
- Radio accessories: 2 USB ports
- Tire repair kit
- Wheels: Alloy wheels 8.5 J x 20 in 5-twin-spoke design (BiColor with tires 245/35 R 20)
- Visibility equipment
- Lane Keeping Assist
- 12-volt power outlet in the trunk
- Traction Control (TC) Plus
- Immobiliser
- Central locking with remote control
- Adaptive brake light
- Airbag: Front and rear outer head airbags
- Ambient lighting
- Electrically adjustable and heated exterior mirrors for driver and passenger side
- Glasses compartment in the headliner
- Decorative strip hexagon
- Tachometer
- Electronic Stability Program (ESP Plus)
- Front collision warning system with pedestrian detection and automatic emergency braking
- Noise-reducing, laminated front side windows
- Transmission: 8-speed automatic transmission
- Back window, heater
- High Gloss Black Exterior Trim (Sports Tourer)
- Automatic climate control, two zones
- Rear headrests (3 pieces)
- LED headlights
- LED daytime running lights including LED indicators, front and LED taillights
- Center armrest, front
- Package: Innovations 1
- Parkpilot, front and rear parking aid
- Quickheat rapid heating system
- Radio: Multimedia Navi Pro with 8" color touchscreen display
- Tire pressure gauge
- Power steering
- Seat belts: Three-point seat belts in all seats
- Solar Protect thermal insulation glazing
- Start/Stop System
- Bumpers painted in body color
- Pre-installation for child seat mounting system "ISOFIX"
- Wireless Charging

Extra equipment

- Swiveling trailer hitch (including trailer stability program)
- Package: Winter 3 (Seat Comfort Equipment 1: Driver's seat 8-way electrically adjustable, memory function for driver's seat and exterior mirrors, electro-pneumatic adjustment of side bolsters, driver's seat massage function, driver's seat heating, multi-stage, driver and front passenger exterior mirrors with ambient lighting, electrically adjustable, heated and folding, 40:20:40 split-folding rear seat, charging package with wireless charging, 2 USB ports in the rear center console, heated ThermaTec windshield, heated rear seats (on the outer seats))
- Package: Innovations 2 (automatic transmission) (Head-up display - Adaptive cruise control (Generation 3), Stop & Go function - Forward collision warning with pedestrian detection and automatic emergency braking, active from 4 km/h, range 150 m. In case of risk of collision, the braking system is prepared and, if necessary, emergency braking / automatic emergency braking is initiated - Traffic sign recognition)
- Park & Go with digital reversing camera (digital reversing camera - reversing assistant - lane change assistant - blind spot warning in both exterior mirrors)

Retrofitted equipment

- Set of complete winter wheels on alloy wheels (OV39243613)

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. Lifting equipment and/or a pit were available for examining the vehicle.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.
readiness to drive	The vehicle was not capable of driving under its own power at the time of inspection, but can be moved on its own axle with the aid of assistance.

Value reducing factors

No.	Component group	Description
1	Equipment	Tirefit filler - Due - Replace
2	Wing mirror - left side	Cap - Scratch(es) - Smart repair
3	2nd wheel set	1 alloy rim - Scratched - Loss in value
4	Sill - right side	Trim - Scratch(es) - Smart repair
5	2nd wheel set	1 tyre (Hinten links) - Does not meet the leasing specifications - Replace
6	Wheel / tyres	Tyre - front right side - Broken / torn - Replace
7	2nd wheel set	2 tyres - Does not meet the leasing specifications - Replace
8	Body	Body - Glued / labelled - De-glue / neutralise
9	Wheel / tyres	Alloy rim - rear left side - Scratched - Replace
10	Wheel / tyres	Alloy rim - rear right side - Scratched - Replace
11	Wheel / tyres	Alloy rim - front left side - Scratched - Replace
12	Wheel / tyres	Alloy rim - front right side - Scratched - Replace

Missing parts

Description
2nd wheel set - Wheel cover set - complete

Previous damages

No.	Previous damage	Extent of damage (Net)
1	Rear, Provided by user / customer, from 27 Jun 2024	2.611,74 €

Paint coat thickness measurement

Roof	203 µm	Roof rail - left side	179 µm
Roof rail - right side	197 µm	Boot lid / rear door	179 µm
Mudguard - left side	195 µm	Mudguard - right side	192 µm
Bonnet	178 µm	Side panel - rear left side	184 µm
Side panel - rear right side	193 µm	Door - rear right side	183 µm
Door - front left side	203 µm	Door - front right side	200 µm

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
  (Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
  (Functional testing of driver assistance systems is not included in the scope of services!)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

According to available information previous damages were repaired at the vehicle. Traces of repairs, which allow conclusions about the area of repair, were not recognizable during the inspection.

Comments

Erhöhte Lackwerte am gesamten Fahrzeug.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)



Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel

Figure 9: Interior 360° view (Online Link)



Figure 10: Cargo area



Figure 11: VIN



Figure 12: Mounted tyres




Figure 13: Documents



Figure 14: Documents




Figure 15: Documents



Figure 16: Additional tyres



Figure 17: Navigation



Figure 18: Misc.




Figure 19: Misc.



Figure 20: Misc.



Figure 21: Misc.



Figure 22: Misc.



Figure 23: Misc.



Figure 24: Misc.




Figure 25: Misc.




Figure 26: Misc.




Figure 27: Misc.



Figure 28: Misc.



Figure 29: Misc.



Damage 1: Equipment: Tirefit filler - Due - Replace



Damage 2: Wing mirror - left side: Cap - Scratch(es) - Smart repair



Damage 2: Wing mirror - left side: Cap - Scratch(es) - Smart repair



Damage 3: 2nd wheel set: 1 alloy rim - Scratched - Loss in value



Damage 3: 2nd wheel set: 1 alloy rim - Scratched - Loss in value



Damage 4: Sill - right side: Trim - Scratch(es) - Smart repair



Damage 4: Sill - right side: Trim - Scratch(es) - Smart repair



Damage 5: 2nd wheel set: 1 tyre (Hinten links) - Does not meet the leasing specifications - Replace



Damage 5: 2nd wheel set: 1 tyre (Hinten links) - Does not meet the leasing specifications - Replace



Damage 5: 2nd wheel set: 1 tyre (Hinten links) - Does not meet the leasing specifications - Replace



Damage 5: 2nd wheel set: 1 tyre (Hinten links) - Does not meet the leasing specifications - Replace



Damage 6: Wheel / tyres: Tyre - front right side - Broken / torn - Replace



Damage 6: Wheel / tyres: Tyre - front right side - Broken / torn - Replace



Damage 6: Wheel / tyres: Tyre - front right side - Broken / torn - Replace




Damage 6: Wheel / tyres: Tyre - front right side - Broken / torn - Replace



Damage 7: 2nd wheel set: 2 tyres - Does not meet the leasing specifications - Replace



Damage 7: 2nd wheel set: 2 tyres - Does not meet the leasing specifications - Replace



Damage 7: 2nd wheel set: 2 tyres - Does not meet the leasing specifications - Replace



Damage 7: 2nd wheel set: 2 tyres - Does not meet the leasing specifications - Replace



Damage 8: Body: Body - Glued / labelled - De-glue / neutralise



Damage 8: Body: Body - Glued / labelled - De-glue / neutralise



Damage 8: Body: Body - Glued / labelled - De-glue / neutralise



Damage 9: Wheel / tyres: Alloy rim - rear left side - Scratched - Replace



Damage 9: Wheel / tyres: Alloy rim - rear left side - Scratched - Replace



Damage 9: Wheel / tyres: Alloy rim - rear left side - Scratched - Replace



Damage 10: Wheel / tyres: Alloy rim - rear right side - Scratched - Replace



Damage 10: Wheel / tyres: Alloy rim - rear right side - Scratched - Replace



Damage 10: Wheel / tyres: Alloy rim - rear right side - Scratched - Replace



Damage 10: Wheel / tyres: Alloy rim - rear right side - Scratched - Replace



Damage 11: Wheel / tyres: Alloy rim - front left side - Scratched - Replace



Damage 11: Wheel / tyres: Alloy rim - front left side - Scratched - Replace



Damage 12: Wheel / tyres: Alloy rim - front right side - Scratched - Replace



Damage 12: Wheel / tyres: Alloy rim - front right side - Scratched - Replace



Damage 12: Wheel / tyres: Alloy rim - front right side - Scratched - Replace



Damage 12: Wheel / tyres: Alloy rim - front right side - Scratched - Replace



Missing part 1: 2nd wheel set: Wheel cover set - complete - Missing - Replace



Missing part 1: 2nd wheel set: Wheel cover set - complete - Missing - Replace



Boot lid / rear door: 179 µm



Mudguard - left side: 195 µm



Mudguard - right side: 192 µm



Bonnet: 178 µm



Side panel - rear left side: 184 µm



Side panel - rear right side: 193 µm



Door - front left side: 203 µm



Door - front right side: 200 µm