TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Hartmann Fleet Professionals GmbH
Leerenstraße 25
29683 Bad Fallingbostel

Expertise

Protocol number: 48435133
Order No. / Reference: 27224368
Inspection date: 29 Oct 2026

Manufacturer: Seat	Model: CUPRA Formentor 1.4 e-Hybrid DSG
VIN: VSSZZZKM3RR022308	





Vehicle details

Manufacturer / Type / Model / Equipment	
Seat CUPRA Formentor 1.4 e-Hybrid DSG	
Vehicle Identification number	VSSZZZKM3RR022308
Mileage (Read)	117,313 km
First registration	24 Oct 2023
Number of holders	1
Next periodical technical inspection	10/2026
(Report not on hand)	
Fuel type	Hybr.B/E ext.aufl
Engine displacement / Cylinder	1,395 ccm / 4
Power	110 kW
Gearbox / Number of gears	Automatic / 6
Type of drive	Front drive
Type of vehicle	Car station wagon
Colour / colour code	Grey metallic (S7H)
Doors / Seats	5 / 5
Upholstery type	Cloth / leather combination
Colour of upholstery	Black
Re-import	no
readiness to drive	Roadworthy

TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Hartmann Fleet Professionals GmbH
Leerenstraße 25
29683 Bad Fallingbostel

Vehicle details

Maintenance booklet / proof	digital proof / complete	**Next maintenance in**	5,100 km
Last service on / at	03/2026 at 107,826 km		
Key is / should be	2 / 2	**FZG documents**	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	GT084330
Previous damage / Accident	Detectable	**Repainting**	None detectable
Inspection conditions	sufficient	**Lifting equipment / pit**	No
Test drive	Not performed	**Engine function test**	Performed
readiness to drive	Roadworthy		
Manufacturer key number/ type code number	7593 / ARB 00057		
Emission standard	EURO6	**fine dust sticker**	
Permitted total weight	2,110 kg	**Empty weight**	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	245/45 R18 100V	Winter tyres on Light alloy	Pirelli	4mm / 4mm
2)	245/45 R18 100V	Winter tyres on Light alloy	Pirelli	4mm / 4mm

Additional tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	245/45 R18 100Y	Summer tyres on Light alloy	Continental	4mm / 4mm
2)	245/45 R18 100Y	Summer tyres on Light alloy	Continental	4mm / 4mm

Replacement

Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
	Tirefit	Expiration date 06/2027		

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

Equipment

Standard equipment

- Storage compartment in the doors
- Acoustic pedestrian warning system (AVAS)
- Adaptive Cruise Control (ACC) up to 210 km/h (DSG)
- Electrically adjustable, folding and heated exterior mirrors (including passenger-side mirror lowering function)
- Climatronic with 3-zone temperature control
- CUPRA Drive Profile (Driving profiles can be individually selected - Selected driving profile influences steering assistance and throttle response, chassis control (with DCC), and shift characteristics (with DSG))
- Parking aid - ultrasonic, rear
- Electronic parking brake including auto-hold function
- Electric window regulator with anti-pinch protection and one-touch function
- luggage compartment cover
- Speed limiter
- Illuminated glove compartment
- rear window wiper
- Headrests, 2 front, 3 rear
- Trim strips on the side windows (outside) in Glossy Black
- Steering wheel: Heated steering wheel
- Reading lights front and rear
- front center armrest
- Emergency call service (no registration required, service is activated upon delivery)
- PreCrash Assist (Proactive occupant protection system)
- Radio: Digital radio reception DAB+
- Radio: Media System Plus (audio system with 10" color touchscreen - voice control - navigation system)
- Radio accessories: Bluetooth interface (with integrated hands-free system and audio streaming)
- Radio accessories: 2 USB-C ports front / 2 rear (charging function)
- Wheels: Tyre fit
- Servotronic
- Seats: Passenger seat with height adjustment
- Seats: Driver's seat with height adjustment
- Seats: ISOFIX child seat restraint system, in the 2nd row left and right (incl. top tether anchor points)
- Sun visor on driver and passenger side with make-up mirror and lighting
- Start-stop system
- Illuminated door sill trims, front
- Front Assist area monitoring system with City Emergency Braking function
- Electronic immobilizer
- thermal insulation glazing
- Airbag: Airbags (7) (Driver and front passenger airbag (passenger airbag deactivation) - Center airbag - Side airbag for driver and front passenger - Head airbag system, front and rear)
- Third brake light (integrated into the tailgate)
- Connectivity box in the center console storage compartment including wireless charger
- Roof rails in Glossy Black
- Electronic differential lock (XDS) for front axle
- Three-point automatic seat belts, front and rear (warning tone for unfastened seat belts)
- Electronic Stability Control (ESC) (including Anti-lock Braking System (ABS) and Traction Control System (ASR))
- High beam assist
- Luggage compartment lighting
- Transmission: 6-speed dual-clutch transmission (DSG)
- Heated rear window
- Kessy Advanced and Keyless GO ((Engine Start/Stop Button) - Keyless locking and opening system)
- Steering wheel: CUPRA sports multifunction steering wheel
- Rear center armrest with pass-through option
- Fatigue detection
- Otto particulate filter
- Package: Light and Sight (Rain sensor - Interior mirror automatically dimming - Light sensor with automatic headlight control - Automatic coming home and leaving home function)
- Radio accessories: 7 speakers
- Radio accessories: CUPRA CONNECT (prepared for activation of the security/assistance and remote access service packages)
- Tire pressure monitoring system
- Side windows from the 2nd row of seats and rear window are dark tinted.
- Seats: CUPRA sports seats in the front, upholstered in "Sharp Textile"
- Seats: Lumbar support for driver and front passenger
- Seats: Rear seat backrest asymmetrically split and foldable
- Lane departure warning system
- Power outlets: 12V socket in the front, 230V socket in the trunk
- Lashing eyes in the luggage compartment
- Virtual Cockpit (Fully digital instrument cluster with 10.25" TFT display)
- Central locking including tailgate with remote control

Extra equipment

- Airbag: Rear side airbags and driver's knee airbag
- Black headliner
- Electrically operated tailgate (opening & closing including sensor-controlled opening & closing (virtual pedal) - remote release for folding down the rear seat backrest in the boot)
- Navigation: 12" navigation system (Navigation system prepared for activation of the CUPRA CONNECT online infotainment service package - Navigation system with 12" display - 3D navigation - Voice control - MAPCARE with integrated map for Europe)
- Package: Winter (heated front seats)
- Park Assist (with front parking aid)
- Smart Ambient Light (Room-wide ambient lighting - Welcome ceremony - Interaction with driver assistance systems and Drive Profile)
- Swiveling towbar with electric release
- Chassis: Adaptive chassis control DCC
- Paint finish: Metallic
- Mode 3 Type 2 charging cable, 16 A
- Matrix LED headlights (camera-based detection of vehicles ahead and oncoming vehicles and targeted masking of individual segments of the permanent high beam cone)
- Package: Driving Assistance Package XL (Side Assist incl. Blind Spot Assist - Exit Assist - Travel Assist - Emergency Assist - Lane Assist Plus)
- Panoramic glass sliding roof (electric with sunshade blind)
- Wheels: 18" "Performance III Black/Silver" alloy wheels, diamond-turned finish (8J x 18", tires 245/45 R 18)
- Top View Camera

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. No lifting equipment or pit was available for inspecting the vehicle. Therefore, inspection of the vehicle's underside was only possible to a limited extent.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.
readiness to drive	The vehicle was roadworthy at the time of inspection.

Value reducing factors

No.	Component group	Description
1	Trim / covers	Trim / covers - Damage caused by marten / rodent - Replace
2	Boot lid / rear door	Boot lid - dent(s) - Smooth repair work
3	Side panel - rear right side	Sill - Scratch(es) - Smart repair
4	Roof	Roof - Stone chips - Smart repair
5	Misc.	Main inspection - Due - Perform
6	2nd wheel set	1 alloy rim - Scratch(es) - Loss in value
7	Door - front right side	Door - Scratch(es) - Paint
8	Front bumper	Spoiler - Scratch(es) - Paint
9	Bonnet	Bonnet - Corrosion - Repair and paint

Wear and tear

No.	Component group	Description
1	Door - rear left side	Door - dent(s) - No deduction
2	Vehicle glazing	Rear window - Scratch(es) - No deduction
3	Vehicle glazing	Windscreen - Stone chips - No deduction
4	Front bumper	Front bumper - Stone chips - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.

Previous damages

No.	Previous damage	Extent of damage (Net)
1	Front, Provided by user / customer, from 9 Feb 2024	4.326,96 €

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
  (Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
  (Functional testing of driver assistance systems is not included in the scope of services!)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

According to available information previous damages were repaired at the vehicle. Traces of repairs, which allow conclusions about the area of repair, were not recognizable during the inspection.

Comments

- Für den montierten Radsatz wurde kein Nachweis erbracht.

- Winterradsatz ist kein Bestandteil des Auslieferumfangs.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)



Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel

Figure 9: Interior 360° view (Online Link)



Figure 10: Cargo area



Figure 11: VIN



Figure 12: Mounted tyres



Figure 13: Documents



Figure 14: Additional tyres




Figure 15: Additional tyres



Figure 16: Navigation



Figure 17: Misc.



Figure 18: Misc.




Figure 19: Misc.



Figure 20: Misc.



Figure 21: Misc.




Figure 22: Misc.



Figure 23: Misc.



Figure 24: Misc.



Figure 25: Misc.




Figure 26: Misc.



Figure 27: Misc.



Figure 28: Misc.



Figure 29: Misc.



Damage 1: Trim / covers: Trim / covers - Damage caused by marten / rodent - Replace




Damage 1: Trim / covers: Trim / covers - Damage caused by marten / rodent - Replace



Damage 2: Boot lid / rear door: Boot lid - dent(s) - Smooth repair work



Damage 2: Boot lid / rear door: Boot lid - dent(s) - Smooth repair work



Damage 3: Side panel - rear right side: Sill - Scratch(es) - Smart repair



Damage 3: Side panel - rear right side: Sill - Scratch(es) - Smart repair



Damage 4: Roof: Roof - Stone chips - Smart repair



Damage 4: Roof: Roof - Stone chips - Smart repair




Damage 6: 2nd wheel set: 1 alloy rim - Scratch(es) - Loss in value



Damage 6: 2nd wheel set: 1 alloy rim - Scratch(es) - Loss in value



Damage 7: Door - front right side: Door - Scratch(es) - Paint



Damage 7: Door - front right side: Door - Scratch(es) - Paint




Damage 8: Front bumper: Spoiler - Scratch(es) - Paint




Damage 8: Front bumper: Spoiler - Scratch(es) - Paint



Damage 8: Front bumper: Spoiler - Scratch(es) - Paint



Damage 9: Bonnet: Bonnet - Corrosion - Repair and paint



Damage 9: Bonnet: Bonnet - Corrosion - Repair and paint



Damage 9: Bonnet: Bonnet - Corrosion - Repair and paint



Wear and tear 1: Door - rear left side: Door - dent(s) - No deduction