TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Hartmann Compound Professionals
Wachau 2
89584 Ehingen

Expertise

Protocol number: 48504342
Order No. / Reference: 27167602
Inspection date: 5 Nov 2026

Manufacturer: Skoda	Model: Superb Combi 2.0 TDI 4x4 DSG Sportline
VIN: TMBLR9NP1P7007537	





Vehicle details

Manufacturer / Type / Model / Equipment	
Skoda Superb Combi 2.0 TDI 4x4 DSG Sportline	
Vehicle Identification number	TMBLR9NP1P7007537
Mileage (Read)	124,956 km
First registration	17 Aug 2022
Number of holders	1
Next periodical technical inspection	10/2027
(Report on hand)	
Fuel type	Diesel
Engine displacement / Cylinder	1,968 ccm / 4
Power	147 kW
Gearbox / Number of gears	Automatic / 7
Type of drive	All-wheel drive
Type of vehicle	Station wagon
Colour / colour code	Moon-Weiß Perleffekt
Doors / Seats	5 / 5
Upholstery type	Alcantara / cloth
Colour of upholstery	Black-Anthracite

Vehicle details

Maintenance booklet / proof	digital proof / complete	**Next maintenance in**	4,100 km
Last service on / at	10/2025 at 98,987 km		
Key is / should be	3 / 3	**FZG documents**	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	GJ949436
Previous damage / Accident	Detectable	**Repainting**	Detectable
Inspection conditions	sufficient	**Lifting equipment / pit**	yes
Test drive	Not performed	**Engine function test**	Performed
Manufacturer key number/ type code number	8004 / AWC 00496		
Emission standard	EURO6	**fine dust sticker**	
Permitted total weight	2,280 kg	**Empty weight**	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	235/40 R19 96Y	Summer tyres on Light alloy	Bridgestone	6mm / 6mm
2)	235/40 R19 96Y	Summer tyres on Light alloy	Bridgestone	6mm / 5mm

Additional tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	215/55 R17 98V	Winter tyres on Light alloy	Goodyear	5mm / 5mm
2)	215/55 R17 98V	Winter tyres on Light alloy	Goodyear	7mm / 8mm

Replacement

Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
	Tirefit	Expiration date 06/2026		

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

Equipment

Standard equipment

- Storage compartments
- Airbag, driver's knee airbag
- Airbag, front side airbags
- Anti-lock braking system (ABS)
- Electrically adjustable and heated exterior mirrors
- Illuminated glove compartment
- Hydraulic brake assist (HBA)
- Roof rails, painted in glossy black
- Diesel particulate filter and SCR catalyst
- Third brake light
- stainless steel pedals
- Electronic parking brake including auto-hold function
- Electronic Stability Control (ESC)
- Driving profile selection including customizable key (Normal, Eco, Sport, Individual)
- Electric windows front and rear, including anti-pinch protection and child safety lock
- Front and rear footwell lighting
- Transmission: 7-speed dual-clutch transmission (DSG)
- Tinted windows
- Rear window wiper including windshield washer system
- ISOFIX preparation on the outer rear seats, including top tether
- Boot cover, roll-up and removable, semi-automatic
- Radiator grille slats, frame, side moldings, exterior mirror caps, window surrounds in black
- Metal loading sill protector
- Remote release of the rear seat backrests in the trunk
- Steering wheel: Heated steering wheel (2 spokes)
- Steering wheel: height and reach adjustable
- Matrix LED headlights
- Front center armrest with storage compartment
- Engine drag torque control (MSR)
- Multi-collision brake
- Rear parking sensors
- Radio: Bolero infotainment system
- Radio accessories: Digital radio reception DAB+
- Radio accessories: SmartLink+
- Tire pressure monitoring
- Wheels: 19" Vega alloy wheels, diamond-cut/anthracite
- Electromechanical power steering
- Seats: Heated front seats
- Seats: Electrically adjustable front seats with memory function
- Seats: Front sports seats
- Sun visor on driver and passenger side with illuminated make-up mirror
- 12V socket in the center console, front and rear
- Telephone: Convenient Bluetooth hands-free phone system
- Lashing eyes in the trunk
- Central locking with remote control
- Airbag, driver and switchable passenger airbag
- Airbag, head airbags
- All-wheel drive 4x4
- Traction control (ASR)
- Electrically folding exterior mirrors
- Hill start assist
- black headliner
- Sportline decorative inlay
- Tachometer
- Dynamic Light Assistant (Masked Continuous High Beam)
- Electric tailgate opening
- Electronic transverse differential lock (XDS+)
- Driving light assistant and rain sensor
- Chassis: Adaptive chassis DCC (10 mm lowering, adjustable damper setting)
- Front radar assistant including city emergency braking function
- Cruise control system (cruise control) including speed limiter
- Heated rear window
- Rear spoiler
- Kessy, keyless entry and start-stop system
- Air Care Climatronic air conditioning system (3 zones)
- Headrests integrated into front seats, rear headrests height-adjustable
- Paintwork: Special paintwork
- LED ambient lighting
- Steering wheel: 3-spoke leather steering wheel in sport design with multifunction buttons
- Reading lights at the front and rear of the headliner
- Rear center armrest with cup holders and pass-through option
- Color multifunction display in the instrument cluster
- LED fog lights with integrated cornering lights
- Upholstery: Alcantara trim in sport black
- Radio accessories: 2 USB-A ports in the center console
- Radio accessories: In-car communication
- Radio accessories: Wireless SmartLink for Apple CarPlay
- Tire mobility kit
- Heated windshield washer nozzles
- Superb seat belts
- Seats: Adjustable lumbar support in the front seats
- Seats: Height-adjustable front seats
- Seats: Rear seat backrest split 60:40, foldable
- SKODA Care Connect
- Start/stop system including brake energy recuperation
- 12V socket in the trunk
- Sunset (rear window and rear side windows tinted dark)
- Textile floor mats
- Chrome-plated elements
- Immobiliser

Extra equipment

- 360° surround view camera (area view)
- Airbag, proactive occupant protection including rear side airbags
- Paint finish: Pearl effect
- Front and rear parking sensors
- Wheels: 19" Supernova alloy wheels, black/gloss-turned (8J x 19" ET 44 with 235/40 R19 tires)
- Seats: Manual seat length adjustment for the electric front seats
- Sunshade roller blind for the rear side windows
- Lane Assist, Blind Spot Detection, Parking Assist, Emergency Assist and Traffic Jam Assist (Lane Assist with adaptive lane guidance)
- Auxiliary heater with radio remote control
- Adaptive Cruise Control (ACC) (control range up to 210 km/h) (replaces cruise control)
- Digital instrument cluster (Virtual Cockpit) 10.2"
- Package: Business Columbus (Combi) (dynamic Columbus radio navigation system, capacitive 9.2" touchscreen, color Maxi-Dot display, Wi-Fi hotspot, voice control, phone box with inductive charging function (connection via external antenna), driver fatigue detection, 230V socket and USB ports, tablet holder in the rear, Sunset (dark tinted rear window and rear side windows), Infotainment Online (3-year subscription), heated rear seats and heated steering wheel, cargo net in the trunk, luggage net partition)
- Traffic sign recognition for navigation systems

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. Lifting equipment and/or a pit were available for examining the vehicle.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.

Value reducing factors

No.	Component group	Description
1	Body	Underbody panelling - Scratch(es) - No deduction
2	Equipment	Tirefit filler - Expired - Replace
3	Braking system	Brake fluid - Due - Replace
4	Wheel / tyres	Alloy rim - front left side - Scratch(es) - Loss in value
5	Instrument panel	Air nozzle - centre (Hinten) - Broken / torn - Replace
6	Braking system	Brake discs and pads - rear - Worn - Replace
7	Front bumper	Front bumper (Unterhalb) - Scratched - Repair and paint
8	Rear bumper	Rear bumper - Scratched - Repair and paint

Wear and tear

No.	Component group	Description
1	Wheel / tyres	Alloy rim - front right side - Scratch(es) - No deduction
2	Vehicle glazing	Windscreen (Kleinere Steinschläge) - No deduction
3	Wheel / tyres	Alloy rim - front right side (Winterradsatz) - Scratch(es) - No deduction
4	Misc.	Misc. (Fußmatte v.l.) - Damaged - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.

Previous damages

No.	Previous damage	Extent of damage (Net)
1	Side right, Provided by user / customer, from 13 Dec 2023	3.517,10 €
2	Side right, Provided by user / customer, from 16 Jun 2024	4.367,48 €

Accident damages

No.	Accident
1	Side right

Repainting

No.	Repainting
1	Roof rail - right side, Mudguard - right side, Side panel - rear right side, Door - rear right side, Door - front right side, Professionally carried out

Paint coat thickness measurement

Roof	99 µm	Roof rail - left side	103 µm
Roof rail - right side	169 µm	Boot lid / rear door	95 µm
Mudguard - left side	98 µm	Mudguard - right side	177 µm
Bonnet	111 µm	Side panel - rear left side	102 µm
Side panel - rear right side	548 µm	Door - rear left side	108 µm
Door - rear right side	181 µm	Door - front left side	106 µm
Door - front right side	156 µm		

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
  (Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
  (Functional testing of driver assistance systems is not included in the scope of services!)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

Non-repaired previous damages were found at the vehicle. The necessary repair costs are listed in the expert report or if necessary, are listed in detail in a separately enclosed repair cost calculation.

Comments

- Winterradsatz ist kein Bestandteil des Auslieferumfangs.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)



Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel



Figure 9: Cargo area



Figure 10: VIN



Figure 11: Mounted tyres




Figure 12: Documents



Figure 13: Additional tyres



Figure 14: Navigation




Figure 15: Misc.



Figure 16: Misc.



Figure 17: Misc.



Figure 18: Misc.



Figure 19: Misc.



Figure 20: Misc.




Figure 21: Misc.



Figure 22: Misc.



Figure 23: Misc.




Figure 24: Misc.



Figure 25: Misc.



Figure 26: Misc.



Figure 27: Misc.




Figure 28: Misc.



Figure 29: Misc.



Figure 30: Misc.



Figure 31: Misc.




Figure 32: Misc.



Figure 33: Misc.




Figure 34: Misc.



Damage 2: Equipment: Tirefit filler - Expired - Replace



Damage 4: Wheel / tyres: Alloy rim - front left side - Scratch(es) - Loss in value



Damage 4: Wheel / tyres: Alloy rim - front left side - Scratch(es) - Loss in value



Damage 5: Instrument panel: Air nozzle - centre (Hinten) - Broken / torn - Replace




Damage 5: Instrument panel: Air nozzle - centre (Hinten) - Broken / torn - Replace



Damage 6: Braking system: Brake discs and pads - rear - Worn - Replace



Damage 6: Braking system: Brake discs and pads - rear - Worn - Replace



Damage 6: Braking system: Brake discs and pads - rear - Worn - Replace



Damage 6: Braking system: Brake discs and pads - rear - Worn - Replace



Damage 7: Front bumper: Front bumper (Unterhalb) - Scratched - Repair and paint



Damage 7: Front bumper: Front bumper (Unterhalb) - Scratched - Repair and paint



Damage 7: Front bumper: Front bumper (Unterhalb) - Scratched - Repair and paint



Damage 7: Front bumper: Front bumper (Unterhalb) - Scratched - Repair and paint



Damage 7: Front bumper: Front bumper (Unterhalb) - Scratched - Repair and paint



Damage 7: Front bumper: Front bumper (Unterhalb) - Scratched - Repair and paint



Damage 8: Rear bumper: Rear bumper - Scratched - Repair and paint



Damage 8: Rear bumper: Rear bumper - Scratched - Repair and paint



Damage 8: Rear bumper: Rear bumper - Scratched - Repair and paint



Wear and tear 1: Wheel / tyres: Alloy rim - front right side - Scratch(es) - No deduction



Wear and tear 1: Wheel / tyres: Alloy rim - front right side - Scratch(es) - No deduction



Wear and tear 3: Wheel / tyres: Alloy rim - front right side (Winterradsatz) - Scratch(es) - No deduction



Wear and tear 3: Wheel / tyres: Alloy rim - front right side (Winterradsatz) - Scratch(es) - No deduction



Wear and tear 4: Misc.: Misc. (Fußmatte v.l.) - Damaged - No deduction



Wear and tear 4: Misc.: Misc. (Fußmatte v.l.) - Damaged - No deduction



Accident 1: Side right



Accident 1: Side right



Accident 1: Side right



Accident 1: Side right



Accident 1: Side right



Accident 1: Side right



Accident 1: Side right



Accident 1: Side right



Accident 1: Side right



Previous damage 2: Side right



Previous damage 2: Side right



Previous damage 2: Side right



Previous damage 2: Side right



Previous damage 2: Side right

TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Hartmann Compound Professionals
Wachau 2
89584 Ehingen



Roof rail - right side: 169 µm



Mudguard - right side: 177 µm



Side panel - rear right side: 548 µm



Door - rear right side: 181 µm



Door - front right side: 156 µm