TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Hartmann Compound Professionals
Arnoldschacht 9-11
44894 Bochum

Expertise

Protocol number: 48509343
Order No. / Reference: 27198709
Inspection date: 28 Oct 2026

Manufacturer: Opel	Model: Mokka 1.2 DI Turbo Automatik Elegance
VIN: VXKUSHNSSNW046241	





Vehicle details

Manufacturer / Type / Model / Equipment	
Opel Mokka 1.2 DI Turbo Automatik Elegance	
Vehicle Identification number	VXKUSHNSSNW046241
Mileage (Read)	135,543 km
First registration	5 Jul 2022
Number of holders	1
Fuel type	Petrol
Engine displacement / Cylinder	1,199 ccm / 3
Power	96 kW
Gearbox / Number of gears	Automatic / 8
Type of drive	Front drive
Type of vehicle	Multipurpose vehicle
Colour / colour code	Jade Weiß
Doors / Seats	5 / 5
Upholstery type	Cloth / leather combination
Colour of upholstery	Grey-Black
Re-import	no
readiness to drive	Not roadworthy / moveable

TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Hartmann Compound Professionals
Arnoldschacht 9-11
44894 Bochum

Vehicle details

Maintenance booklet / proof	digital proof / complete	**Next maintenance in**	13,700 km
Last service on / at	03/2026 at 113,075 km		
Key is / should be	2 / 2	**FZG documents**	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	GJ692863
Previous damage / Accident	Detectable	**Repainting**	None detectable
Inspection conditions	sufficient	**Lifting equipment / pit**	yes
Test drive	Not performed	**Engine function test**	Performed
readiness to drive	Not roadworthy / moveable		
Manufacturer key number/ type code number	1889 / ADB 00027		
Emission standard	EURO6	**fine dust sticker**	
Permitted total weight	1,740 kg	**Empty weight**	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	215/60 R17 76H	Winter tyres on Light alloy	Maxxis	5mm / 5mm
2)	215/60 R17 76H	Winter tyres on Light alloy	Maxxis	6mm / 6mm

Replacement

Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
	Tirefit	Expiration date 08/2026		

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

Equipment

Standard equipment

- 2 ignition keys, both foldable
- Adaptive brake light
- Airbag: Front and side airbags
- Actively controlled air intakes (Active Aero Shutter)
- Electrically adjustable and heated exterior mirrors
- Exterior mirrors in black
- Roof design line in chrome
- Roof spoiler, black
- Double boot floor
- Third brake light
- Electronic Stability Program Plus (ESP Plus)
- Front collision warning with automatic city emergency braking and pedestrian detection
- Transmission: 8-speed automatic
- Child safety lock in the rear doors, manual
- Headrests (2)
- Rear headrests (3), height adjustable
- LED fog lights
- Steering wheel: Heated leather steering wheel
- Steering wheel: Leather steering wheel, flattened at the bottom with paddle shifters
- Steering column, height and tilt adjustable
- Makeup mirror in sun visor, driver and front passenger
- Multi-collision brake
- Otto particulate filter
- Upholstery: Fabric/Premium leather look
- Radio accessories: Digital radio reception DAB+
- Wheels: Tire repair kit (with tire sealant and 12-volt compressor (without jack))
- Speed-sensitive power steering
- Visibility equipment
- Seats: Driver's seat 6-way manually adjustable
- Seats: Rear seat backrest foldable in a 60:40 ratio
- Lane Keeping Assist
- Start/Stop System
- Traction control with engine and brake intervention TC Plus
- Underride protection look, front and rear, in silver
- Tinted heat-insulating glazing
- Storage compartments
- Driver and passenger side airbags
- Airbag: Head airbags, front and rear outer
- Anti-lock braking system (ABS) with cornering brake control and brake assist
- Hill Start Assist
- Headliner, Grey
- Decorative strips, silver
- Tachometer
- Electronic brake force distribution (EBD)
- Electric windows front and rear
- Pedestrian protection
- Cruise control with intelligent speed limiter
- Rear shelf
- Automatic climate control (with activated carbon filter, manual recirculation, automatic air distribution - footwell heating, rear - sun position sensor)
- LED headlights (LED ambient lighting in door storage compartments, front - LED turn signals, front and rear - LED taillights - LED daytime running lights - LED headlights - High beam assist)
- Reading lights, front
- Center armrest, front
- Fatigue detection
- Parkpilot, rear parking aid, with acoustic warning signal when reversing.
- Wheels: Light alloy (4) 5 double spokes 6.5 J x 17 in BiColor Black (with tires 215/60 R 17)
- Side impact protection
- Seat belts
- Seats: Passenger seat 6-way manually adjustable
- Seats: Comfort seats, front
- Seats: Pre-installation for ISOFIX child seat mounting system, rear outer
- 12-volt power outlet
- Ambient lighting
- Traffic sign recognition
- Central locking with remote control

Extra equipment

- All-weather tires
- Paint finish: Uni Jade White
- Radio: Multimedia Navi (with 7" color touchscreen display and fully digital 7" driver information display - Navigation with integrated memory - European road map - 3D map display - Dynamic route guidance via map and/or arrow display - Display of points of interest - Trip plan. - OpelConnect GPS module, including LIVE navigation services: - Map updates. - Voice control for audio, telephone and navigation. - Radio, Bluetooth, DAB+, USB, hands-free.)
- Paint finish: Roof and A-pillar in Diamond Black
- Park & Go (Park Pilot, front and rear parking aid with audiovisual warning - 180-degree panoramic reversing camera - blind spot warning and side protection - electrically folding exterior mirrors - ambient lighting)
- Keyless locking and starting system "Keyless Open & Start" (keyless unlocking for driver and passenger doors as well as the luggage compartment - engine start button)
- Seats: Heated seats, multi-stage, driver and front passenger
- Solar Protect heat-insulating glazing (heavily tinted, in the rear)

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. Lifting equipment and/or a pit were available for examining the vehicle.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.
readiness to drive	The vehicle was not capable of driving under its own power at the time of inspection, but can be moved on its own axle with the aid of assistance.

Value reducing factors

No.	Component group	Description
1	Equipment	Tirefit filler - Expired - Replace
2	Side panel - rear left side	Brightware (Dachholm links) - Scratched - Loss in value
3	Engine	Engine cover - Damage caused by marten / rodent - Replace
4	Bonnet	Insulation lining - Damage caused by marten / rodent - Replace
5	Wheel / tyres	Tyre - front right side (215 60 17 w) - Worn - Replace
6	Wheel / tyres	Alloy rim - rear left side - Scratch(es) - Loss in value
7	Steering system	Steering wheel sheath - Scratched - Loss in value
8	Wheel / tyres	Alloy rim - front left side (Materialabtrag) - Scratched - Replace
9	Wheel / tyres	Alloy rim - front right side - Scratched - Replace
10	Roof	Roof rail - left side - Scratch(es) - Paint
11	Door - rear left side	Door - Scratch(es) - Paint
12	Boot lid / rear door	Boot lid - Dent / paintcoat damage - Repair and paint
13	Door - front left side	Door - Dent / paintcoat damage - Repair and paint
14	Roof	Roof - Scratched - Paint

Wear and tear

No.	Component group	Description
1	Trim / covers	Door trim - rear left side - Scratch(es) - No deduction
2	Misc.	Main inspection - No evidence - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.

Accident damages

No.	Accident
1	Rear, Side right

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
  (Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
  (Functional testing of driver assistance systems is not included in the scope of services!)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

Non-repaired previous damages were found at the vehicle. The necessary repair costs are listed in the expert report or if necessary, are listed in detail in a separately enclosed repair cost calculation.

Comments

Das Fahrzeug befand sich zum Besichtigungszeitpunkt in beschädigtem, nicht demontiertem Zustand.
Schadenausweitung möglich, Zusatzkosten können entstehen.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)



Figure 5: Interior - front




Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel

Figure 9: Interior 360° view (Online Link)



Figure 10: Cargo area




Figure 11: VIN



Figure 12: Mounted tyres



Figure 13: Documents




Figure 14: Documents




Figure 15: Documents



Figure 16: Documents



Figure 17: Documents



Figure 18: Navigation



Figure 19: Misc.



Figure 20: Misc.



Figure 21: Misc.




Figure 22: Misc.



Figure 23: Misc.




Figure 24: Misc.



Figure 25: Misc.



Figure 26: Misc.



Figure 27: Misc.



Figure 28: Misc.



Figure 29: Misc.



Figure 30: Misc.



Figure 31: Misc.





Figure 32: Misc.




Damage 1: Equipment: Tirefit filler - Expired - Replace



Damage 2: Side panel - rear left side: Brightware (Dachholm links) - Scratched - Loss in value



Damage 2: Side panel - rear left side: Brightware (Dachholm links) - Scratched - Loss in value



Damage 2: Side panel - rear left side: Brightware (Dachholm links) - Scratched - Loss in value



Damage 3: Engine: Engine cover - Damage caused by marten / rodent - Replace



Damage 3: Engine: Engine cover - Damage caused by marten / rodent - Replace



Damage 4: Bonnet: Insulation lining - Damage caused by marten / rodent - Replace



Damage 4: Bonnet: Insulation lining - Damage caused by marten / rodent - Replace



Damage 4: Bonnet: Insulation lining - Damage caused by marten / rodent - Replace



Damage 5: Wheel / tyres: Tyre - front right side (215 60 17 w) - Worn - Replace



Damage 5: Wheel / tyres: Tyre - front right side (215 60 17 w) - Worn - Replace



Damage 5: Wheel / tyres: Tyre - front right side (215 60 17 w) - Worn - Replace



Damage 6: Wheel / tyres: Alloy rim - rear left side - Scratch(es) - Loss in value




Damage 6: Wheel / tyres: Alloy rim - rear left side - Scratch(es) - Loss in value




Damage 6: Wheel / tyres: Alloy rim - rear left side - Scratch(es) - Loss in value



Damage 7: Steering system: Steering wheel sheath - Scratched - Loss in value



Damage 7: Steering system: Steering wheel sheath - Scratched - Loss in value



Damage 7: Steering system: Steering wheel sheath - Scratched - Loss in value



Damage 7: Steering system: Steering wheel sheath - Scratched - Loss in value



Damage 8: Wheel / tyres: Alloy rim - front left side (Materialabtrag) - Scratched - Replace



Damage 8: Wheel / tyres: Alloy rim - front left side (Materialabtrag) - Scratched - Replace



Damage 8: Wheel / tyres: Alloy rim - front left side (Materialabtrag) - Scratched - Replace



Damage 8: Wheel / tyres: Alloy rim - front left side (Materialabtrag) - Scratched - Replace



Damage 9: Wheel / tyres: Alloy rim - front right side - Scratched - Replace




Damage 9: Wheel / tyres: Alloy rim - front right side - Scratched - Replace



Damage 9: Wheel / tyres: Alloy rim - front right side - Scratched - Replace




Damage 9: Wheel / tyres: Alloy rim - front right side - Scratched - Replace



Damage 10: Roof: Roof rail - left side - Scratch(es) - Paint



Damage 10: Roof: Roof rail - left side - Scratch(es) - Paint



Damage 10: Roof: Roof rail - left side - Scratch(es) - Paint



Damage 10: Roof: Roof rail - left side - Scratch(es) - Paint



Damage 11: Door - rear left side: Door - Scratch(es) - Paint




Damage 11: Door - rear left side: Door - Scratch(es) - Paint



Damage 11: Door - rear left side: Door - Scratch(es) - Paint



Damage 11: Door - rear left side: Door - Scratch(es) - Paint



Damage 12: Boot lid / rear door: Boot lid - Dent / paintcoat damage - Repair and paint



Damage 12: Boot lid / rear door: Boot lid - Dent / paintcoat damage - Repair and paint



Damage 12: Boot lid / rear door: Boot lid - Dent / paintcoat damage - Repair and paint



Damage 12: Boot lid / rear door: Boot lid - Dent / paintcoat damage - Repair and paint



Damage 13: Door - front left side: Door - Dent / paintcoat damage - Repair and paint



Damage 13: Door - front left side: Door - Dent / paintcoat damage - Repair and paint



Damage 13: Door - front left side: Door - Dent / paintcoat damage - Repair and paint




Damage 13: Door - front left side: Door - Dent / paintcoat damage - Repair and paint



Damage 13: Door - front left side: Door - Dent / paintcoat damage - Repair and paint



Damage 14: Roof: Roof - Scratched - Paint



Damage 14: Roof: Roof - Scratched - Paint



Damage 14: Roof: Roof - Scratched - Paint



Wear and tear 1: Trim / covers: Door trim - rear left side - Scratch(es) - No deduction



Accident 1: Rear, Side right



Accident 1: Rear, Side right



Accident 1: Rear, Side right



Accident 1: Rear, Side right



Accident 1: Rear, Side right



Accident 1: Rear, Side right



Accident 1: Rear, Side right



Accident 1: Rear, Side right



Accident 1: Rear, Side right




Accident 1: Rear, Side right



Accident 1: Rear, Side right



Accident 1: Rear, Side right



Accident 1: Rear, Side right



Accident 1: Rear, Side right



Accident 1: Rear, Side right



Accident 1: Rear, Side right



Accident 1: Rear, Side right




Accident 1: Rear, Side right



Accident 1: Rear, Side right



Accident 1: Rear, Side right



Accident 1: Rear, Side right



Accident 1: Rear, Side right



Accident 1: Rear, Side right



Accident 1: Rear, Side right



Accident 1: Rear, Side right



Accident 1: Rear, Side right



Accident 1: Rear, Side right



Accident 1: Rear, Side right

TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Hartmann Compound Professionals
Arnoldschacht 9-11
44894 Bochum



Accident 1: Rear, Side right



Accident 1: Rear, Side right



Accident 1: Rear, Side right