TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Hartmann Compound Professionals
Arnoldschacht 9-11
44894 Bochum

Expertise

Protocol number: 48605297
Order No. / Reference: 27251671
Inspection date: 4 Nov 2026

Manufacturer: Ford	Model: Transit Custom 300 L2H1 LKW VA Trend
VIN: WF0YXXTTGYKM34930	





Vehicle details

Manufacturer / Type / Model / Equipment	
Ford Transit Custom 300 L2H1 LKW VA Trend	
Vehicle Identification number	WF0YXXTTGYKM34930
Mileage (Read)	56,913 km
First registration	8 Apr 2020
Number of holders	1
Next periodical technical inspection	09/2028
(Report on hand)	
Fuel type	Diesel
Engine displacement / Cylinder	1,995 ccm / 4
Power	79 kW
Gearbox / Number of gears	Manual / 6
Type of drive	Front drive
Type of vehicle	Van
Colour / colour code	Polar-Silber Metallic
Doors / Seats	4 / 3
Upholstery type	Cloth
Colour of upholstery	Black

TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Hartmann Compound Professionals
Arnoldschacht 9-11
44894 Bochum

Vehicle details

Maintenance booklet / proof	digital evidence / incomplete	**Next maintenance in**	0 km
Key is / should be	2 / 4	**FZG documents**	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	FR767806
Previous damage / Accident	Detectable	**Repainting**	Detectable
Inspection conditions	sufficient	**Lifting equipment / pit**	yes
Test drive	Not performed	**Engine function test**	Performed
Manufacturer key number/ type code number	8566 / BSF 00187		
Emission standard	EURO6	**fine dust sticker**	
Permitted total weight	3,000 kg	**Empty weight**	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	215/65 R16 109S	Winter tyres on Steel	Continental	7mm / 7mm
2)	215/65 R16 109S	Winter tyres on Steel	Continental	8mm / 8mm

Replacement

Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
E	215/65 R16 109S	All-season tyres on Steel	Continental	7 mm

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

Equipment

Standard equipment

- 1 battery
- Anti-lock braking system with electronic brake force distribution (EBD)
- roof, flat
- Tachometer
- Front electric windows
- Ford Easy Fuel
- Warranty: 2-year Ford new car warranty including Ford Assistance mobility guarantee
- Transmission: 6-speed transmission
- Interior lighting with delay circuit
- Cargo area lighting with activatable switch-off delay
- Steering column, adjustable in height and reach
- Package: Style-Color Package
- Particulate filter: diesel particulate filter
- Wheels/Tires: Spare wheel, steel wheel
- Headlights: Halogen projector headlights
- Sliding door: Sliding door, right
- Mud flaps front and rear
- Low side paneling
- Seat belts
- Power outlet: 12-volt connection
- Lashing eyes 8
- Heat-insulating glazing, lightly tinted
- Auxiliary heater, electric
- Driver's side airbag
- Exterior mirrors, electrically adjustable and heated
- On-board computer
- Headliner in driver's cab
- Electronic Stability Program (ESP) with Traction Control System (TCS)
- FordPass Connect
- Generator, 240 A
- Cruise control including leather steering wheel
- Lockable glove compartment with lid
- Front air conditioning
- Cargo area floor: Vinyl floor covering, sealed, "Easy Clean"
- Emergency brake assist including emergency brake light
- Front and rear parking pilot system including fog lights
- Wheel trims
- Wheels: Steel wheels 6.5 J x 15 with 215/65 R 15 tires
- Sliding door entry light automatically illuminates when the door is opened
- Side protection strips
- Power steering
- Start-stop system
- Front bumper in body color
- Immobiliser
- Central locking with remote control
- Second key with remote control

Extra equipment

- 3rd and 4th keys
- Double-leaf rear door with 90° opening angle (without window)
- Seats: Seat Package 15 - Partition (load-through hatch), without window (Custom Truck Trend) (Driver's seat, 4-way adjustable (forward/backward, backrest, seat cushion tilt, height) - Double passenger seat with storage compartment under individually foldable seat cushions - Height-adjustable headrests - Integrated tray in the double passenger seat (fold-out) - Heated driver's seat - Heated passenger seat (outer seat) - Inner armrest for driver - Manual lumbar support (driver's seat) - TREND seat cover: fabric - Partition without window with load-through hatch)
- Parking heater, programmable, with remote control
- BOTT
- Paint finish: Metallic
- Radio: Audio System 24: Ford audio system including Ford SYNC 3 with AppLink, DAB/DAB+, navigation system. (Radio (FM/AM) 8" touchscreen multifunction display (20.32 cm), 4 speakers, FordPass Connect Wi-Fi hotspot, integrated control panel and audio remote control on the steering wheel, Ford SYNC 3 with touchscreen (hands-free system with voice control, SMS readout/sending function, Bluetooth, Emergency Assistance...), AppLink (advanced voice control, privacy mode, Android Auto and Apple CarPlay support, capacitive touchscreen technology,...), dynamic navigation, lane guidance, road map for Western Europe)

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. Lifting equipment and/or a pit were available for examining the vehicle.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.

Value reducing factors

No.	Component group	Description
1	Trim / covers	Floor mats - Broken / torn - Replace
2	Sliding door, right	Door seal - Malposition - Set / adjust
3	Wing mirror - left side	Cap - Scratch(es) - Smart repair
4	Rear of vehicle	Foot plate - Deformed - Loss in value
5	Boot lid / rear door	Trim rear door - hard fibre - centre - Deformed - Replace
6	Side panel - rear left side	Sill - Scratch(es) - Smart repair
7	Fuel system	Tank flap - Scratch(es) - Paint
8	Misc.	Inspection / maintenance - Due - Replace
9	Rear bumper	Bumper - rear left side - Scratch(es) - Paint
10	Bonnet	Bonnet - Scratch(es) - Paint
11	Sill - right side	Sill - Dent / paintcoat damage - Repair and paint
12	Front bumper	Front bumper - Broken / torn - Replace
13	Door - front left side	Door - Dent / paintcoat damage - Repair and paint
14	Boot lid / rear door	Rear door - right side - Dent / paintcoat damage - Repair and paint
15	Side panel - rear left side	Side panel - Dent / paintcoat damage - Repair and paint
16	Boot lid / rear door	Rear door - left side - Deformed - Replace

Wear and tear

No.	Component group	Description
1	Body	Partition wall - Scratch(es) - No deduction
2	Boot lid / rear door	Rear door - right side (Innen) - Dent / paintcoat damage - No deduction
3	Roof	Roof - dent(s) - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.

Missing parts

Description
Equipment - Vehicle key (2)

Accident damages

No.	Accident
1	Rear, Side right

Repainting

No.	Repainting
1	Door - rear right side

Paint coat thickness measurement

Door - rear right side	213 µm

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
  (Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
  (Functional testing of driver assistance systems is not included in the scope of services!)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations of light commercial vehicles published by Alphabet Fleet Management GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

Non-repaired previous damages were found at the vehicle. The necessary repair costs are listed in the expert report or if necessary, are listed in detail in a separately enclosed repair cost calculation.

Comments

Das Fahrzeug befand sich zum Besichtigungszeitpunkt in beschädigtem, nicht demontiertem Zustand.
Schadenausweitung möglich, Zusatzkosten können entstehen.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)



Figure 5: Interior - front



Figure 6: Instrument cluster



Figure 7: Instrument panel

Figure 8: Interior 360° view (Online Link)



Figure 9: Cargo area




Figure 10: VIN



Figure 11: Mounted tyres




Figure 12: Documents




Figure 13: Documents




Figure 14: Documents



Figure 15: Documents



Figure 16: Documents



Figure 17: Navigation




Figure 18: Misc.



Figure 19: Misc.



Figure 20: Misc.



Figure 21: Misc.



Figure 22: Misc.



Figure 23: Misc.



Figure 24: Misc.



Figure 25: Misc.



Figure 26: Misc.




Figure 27: Misc.



Figure 28: Misc.



Figure 29: Misc.



Figure 30: Misc.



Figure 31: Misc.



Figure 32: Misc.



Figure 33: Misc.



Figure 34: Misc.



Figure 35: Misc.



Damage 1: Trim / covers: Floor mats - Broken / torn - Replace



Damage 1: Trim / covers: Floor mats - Broken / torn - Replace



Damage 2: Sliding door, right: Door seal - Malposition - Set / adjust



Damage 3: Wing mirror - left side: Cap - Scratch(es) - Smart repair



Damage 3: Wing mirror - left side: Cap - Scratch(es) - Smart repair



Damage 4: Rear of vehicle: Foot plate - Deformed - Loss in value




Damage 4: Rear of vehicle: Foot plate - Deformed - Loss in value




Damage 4: Rear of vehicle: Foot plate - Deformed - Loss in value



Damage 5: Boot lid / rear door: Trim rear door - hard fibre - centre - Deformed - Replace



Damage 5: Boot lid / rear door: Trim rear door - hard fibre - centre - Deformed - Replace



Damage 6: Side panel - rear left side: Sill - Scratch(es) - Smart repair



Damage 6: Side panel - rear left side: Sill - Scratch(es) - Smart repair



Damage 6: Side panel - rear left side: Sill - Scratch(es) - Smart repair



Damage 7: Fuel system: Tank flap - Scratch(es) - Paint



Damage 7: Fuel system: Tank flap - Scratch(es) - Paint



Damage 8: Misc.: Inspection / maintenance - Due - Replace



Damage 9: Rear bumper: Bumper - rear left side - Scratch(es) - Paint




Damage 9: Rear bumper: Bumper - rear left side - Scratch(es) - Paint




Damage 9: Rear bumper: Bumper - rear left side - Scratch(es) - Paint



Damage 10: Bonnet: Bonnet - Scratch(es) - Paint



Damage 10: Bonnet: Bonnet - Scratch(es) - Paint



Damage 10: Bonnet: Bonnet - Scratch(es) - Paint



Damage 11: Sill - right side: Sill - Dent / paintcoat damage - Repair and paint



Damage 11: Sill - right side: Sill - Dent / paintcoat damage - Repair and paint



Damage 11: Sill - right side: Sill - Dent / paintcoat damage - Repair and paint



Damage 12: Front bumper: Front bumper - Broken / torn - Replace



Damage 12: Front bumper: Front bumper - Broken / torn - Replace



Damage 12: Front bumper: Front bumper - Broken / torn - Replace



Damage 12: Front bumper: Front bumper - Broken / torn - Replace



Damage 12: Front bumper: Front bumper - Broken / torn - Replace



Damage 13: Door - front left side: Door - Dent / paintcoat damage - Repair and paint




Damage 13: Door - front left side: Door - Dent / paintcoat damage - Repair and paint



Damage 13: Door - front left side: Door - Dent / paintcoat damage - Repair and paint



Damage 13: Door - front left side: Door - Dent / paintcoat damage - Repair and paint



Damage 13: Door - front left side: Door - Dent / paintcoat damage - Repair and paint




Damage 13: Door - front left side: Door - Dent / paintcoat damage - Repair and paint



Damage 14: Boot lid / rear door: Rear door - right side - Dent / paintcoat damage - Repair and paint



Damage 14: Boot lid / rear door: Rear door - right side - Dent / paintcoat damage - Repair and paint



Damage 14: Boot lid / rear door: Rear door - right side - Dent / paintcoat damage - Repair and paint



Damage 14: Boot lid / rear door: Rear door - right side - Dent / paintcoat damage - Repair and paint



Damage 14: Boot lid / rear door: Rear door - right side - Dent / paintcoat damage - Repair and paint



Damage 15: Side panel - rear left side: Side panel - Dent / paintcoat damage - Repair and paint



Damage 15: Side panel - rear left side: Side panel - Dent / paintcoat damage - Repair and paint



Damage 15: Side panel - rear left side: Side panel - Dent / paintcoat damage - Repair and paint



Damage 15: Side panel - rear left side: Side panel - Dent / paintcoat damage - Repair and paint



Damage 15: Side panel - rear left side: Side panel - Dent / paintcoat damage - Repair and paint



Damage 16: Boot lid / rear door: Rear door - left side - Deformed - Replace



Damage 16: Boot lid / rear door: Rear door - left side - Deformed - Replace



Damage 16: Boot lid / rear door: Rear door - left side - Deformed - Replace



Damage 16: Boot lid / rear door: Rear door - left side - Deformed - Replace



Damage 16: Boot lid / rear door: Rear door - left side - Deformed - Replace



Damage 16: Boot lid / rear door: Rear door - left side - Deformed - Replace



Wear and tear 1: Body: Partition wall - Scratch(es) - No deduction




Wear and tear 2: Boot lid / rear door: Rear door - right side (Innen) - Dent / paintcoat damage - No deduction




Wear and tear 3: Roof: Roof - dent(s) - No deduction



Wear and tear 3: Roof: Roof - dent(s) - No deduction




Wear and tear 3: Roof: Roof - dent(s) - No deduction



Missing part 1: Equipment: Vehicle key (2) - Missing - Replace



Accident 1: Rear, Side right



Accident 1: Rear, Side right




Accident 1: Rear, Side right



Accident 1: Rear, Side right



Accident 1: Rear, Side right



Accident 1: Rear, Side right



Accident 1: Rear, Side right



Accident 1: Rear, Side right



Accident 1: Rear, Side right

TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Hartmann Compound Professionals
Arnoldschacht 9-11
44894 Bochum



Accident 1: Rear, Side right



Repainting 1: Door - rear right side



Repainting 1: Door - rear right side