TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Hartmann Fleet Professionals GmbH
Leerenstraße 25
29683 Bad Fallingbostel

Expertise

Protocol number: 48073657
Order No. / Reference: 26983551
Inspection date: 12 Oct 2026

Manufacturer: Skoda	Model: Octavia Combi 2.0 TDI DSG 4x4 Clever
VIN: TMBLJ8NXXNY097005	





Vehicle details

Manufacturer / Type / Model / Equipment	
Skoda Octavia Combi 2.0 TDI DSG 4x4 Clever	
Vehicle Identification number	TMBLJ8NXXNY097005
Mileage (Read)	124,147 km
First registration	2 Jun 2022
Number of holders	1
Next periodical technical inspection	06/2027
(Report not on hand)	
Fuel type	Diesel
Engine displacement / Cylinder	1,968 ccm / 4
Power	110 kW
Gearbox / Number of gears	Automatic / 7
Type of drive	All-wheel drive
Type of vehicle	Station wagon
Colour / colour code	Graphit-Grau Metallic
Doors / Seats	5 / 5
Upholstery type	Cloth
Colour of upholstery	Black

Vehicle details

Maintenance booklet / proof	digital proof / complete	**Next maintenance in**	15,800 km
Last service on / at	07/2026 at 117,463 km		
Key is / should be	2 / 2	**FZG documents**	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	GJ917162
Previous damage / Accident	Detectable	**Repainting**	Detectable
Inspection conditions	sufficient	**Lifting equipment / pit**	No
Test drive	Not performed	**Engine function test**	Performed
Manufacturer key number/ type code number	8004 / AVH 00219		
Emission standard	EURO6	**fine dust sticker**	
Permitted total weight	2,117 kg	**Empty weight**	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	205/55 R17 91V	Summer tyres on Light alloy	Michelin	3mm / 3mm
2)	205/55 R17 91V	Summer tyres on Light alloy	Michelin	5mm / 5mm

Additional tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	205/60 R16 92V	Winter tyres on Light alloy	Goodyear	4mm / 4mm
2)	205/60 R16 92V	Winter tyres on Light alloy	Goodyear	5mm / 5mm

Replacement

Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
	Tirefit	Expiration date 03/2026		

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

Equipment

Standard equipment

- Cornering lights integrated into fog lights
- Storage compartments (Four roof grab handles, rear with coat hooks; holder for the warning vest under the driver's seat; storage compartments in the front door panels with 1.5l bottle holders; storage compartments in the rear door panels with 0.5l bottle holders; ticket holder on the windshield; coat hooks on the B-pillars; storage compartments in the doors with felt lining)
- All-wheel drive 4x4
- Trailer hitch preparation including trailer stabilization
- Extended warranty for 3 years, max. 50,000 km
- Anti-lock braking system (ABS)
- Electrically adjustable and heated exterior mirrors
- Heated windshield washer nozzles including 5l washer fluid reservoir
- Glasses compartment in the headliner
- Roof rails, black
- Diesel particulate filter
- Third brake light
- Electronic transverse differential lock (XDS+)
- Driving light assistant (Coming Home / Leaving Home function)
- High beam assist
- Front radar assistant including city emergency braking function and pedestrian and cyclist detection
- Tinted windows
- Heated rear window
- Rear window wiper including windshield washer system
- ISOFIX preparations on the front passenger seat and the outer rear seats including top tether anchorage
- Removable boot cover
- Headrests (5) front and rear height adjustable
- LED fog lights
- LED taillights in crystal glass look and animated turn signals
- Remote release of the rear seat backrests in the trunk
- Steering wheel: height and reach adjustable
- Steering wheel: Leather steering wheel with multifunction buttons and paddle shifters (leather steering wheel and gearshift lever with leather elements - infotainment and driver assistance system operation)
- Multifunction display in the instrument cluster
- Upholstery: Cloth
- Radio accessories: 2 USB-C ports on the front
- Radio accessories: 8 speakers
- Radio accessories: Digital radio reception DAB+
- Radio accessories: Voice control
- Rain sensor
- Tire mobility kit (tire repair spray incl. compressor)
- Rear view camera
- Electromechanical power steering
- Safety lights in the front side doors
- Seats: Height-adjustable driver and passenger seats (including lumbar support)
- Storage compartment in the luggage compartment with cargo element
- Airbag for driver and front passenger (passenger airbag can be deactivated)
- Airbag, driver's knee airbag
- Airbag, head airbags
- Airbag, front side airbags
- Airbag: Center airbag front
- Ambient lighting (dashboard, front trim strips and footwell with selectable color climate) in the interior as well as logo projector on the outside)
- Traction control (ASR)
- Electrically folding exterior mirrors
- Hill start assist including auto-hold function
- Hydraulic brake assist (HBA)
- Grey headliner
- Decorative strip in silver finish with ambient lighting
- Tachometer
- Electronic parking brake
- Electronic Stability Control (ESC)
- Driving profile selection
- Electric windows front and rear, including anti-pinch protection and child safety lock
- Cruise control system
- Transmission: 7-speed dual-clutch transmission (DSG)
- Green tec: Start/stop system including brake energy recuperation
- Interior mirror automatically dimming
- Child safety lock for the rear doors and windows
- Climatronic air conditioning (3-zone) (separately adjustable for driver, front passenger and rear passengers, including air-conditioned and illuminated glove compartment)
- LED license plate lights
- LED headlights with LED daytime running lights
- Steering wheel: Heated steering wheel including heated front seats
- Manual headlight range adjustment
- Rear center armrest with pass-through option
- Front center armrest, including storage compartment
- Engine drag torque control (MSR)
- Front and rear parking sensors
- Radio: Bolero music system with capacitive 10" color display
- Radio accessories: Bluetooth hands-free system
- Radio accessories: SmartLink (Apple CarPlay - Android Auto)
- Tire pressure monitoring
- Wheels: 17" Pulsar AERO alloy wheels, black gloss turned (7J x 17, ET 46 with 205/55 R17 tires)
- Seat belts (Three three-point seat belts in the rear)
- Seats: Heated rear seats
- Seats: Manually adjustable ergonomic front seats (massage function - electrically adjustable lumbar support - extendable leg rest)
- Speed limiter

- Seats: Rear seat backrest split 60:40, foldable
- SKODA Care Connect (SOS emergency call function (eCall+ including automatic activation in the event of an accident with airbag deployment) - Mobility service (connection option for rapid assistance in case of breakdown) - Information service (connection option to the hotline for all questions relating to vehicle functions) - Free remote vehicle access for 1 year (Remote Access) with access to vehicle data and functions via smartphone, e.g. parking position, activating hazard warning lights, current fuel level)
- Immobiliser
- Lane keeping assistant (Lane Assist)
- 12V socket in the trunk
- 230V socket and USB charging port (230V socket and 2 x USB charging ports in the rear as well as USB charging port in the rearview mirror)
- Phone: Wireless SmartLink for Apple CarPlay
- Glazing: Acoustic glazing in the front side windows and Sunset (dark tinted rear window and rear side windows)
- Lashing eyes in the trunk
- Central locking including remote control integrated into the key and EASY Start

Extra equipment

- Luggage net partition
- Package: Columbus infotainment package (Columbus navigation system - Infotainment Online (3-year subscription) - Digital instrument cluster (Virtual Cockpit) - Phonebox - KESSY (Keyless entry and start-stop system))
- Paint finish: Metallic
- Swiveling trailer hitch including trailer stabilization and adapter
- Comfort opening with electric tailgate operation (Combi) (incl. semi-automatic luggage compartment cover)
- Package: Travel (DSG) (Traveller assistance system: - Traffic sign recognition - Predictive and adaptive cruise control (pACC) - Adaptive lane keeping assist - Emergency and traffic jam assist - Capacitive steering wheel with hands-off detection - Adaptive cruise control (ACC) (control range 210 km/h) - Driver fatigue detection - Driving profile selection - Automatically dimming exterior mirror (driver's side))

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. No lifting equipment or pit was available for inspecting the vehicle. Therefore, inspection of the vehicle's underside was only possible to a limited extent.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.

Value reducing factors

No.	Component group	Description
1	Equipment	Tirefit filler - Expired - Replace
2	Roof	Roof rail - left side - dent(s) - Smooth repair work
3	Side panel - rear left side	Side panel - dent(s) - Smart repair
4	Wheel / tyres	Alloy rim - front left side - Scratch(es) - Loss in value
5	Bonnet	Bonnet - dent(s) - Smooth repair work
6	Door - rear right side	Door (Wellig) - Unprofessionally repaired - Lacquer
7	Door - front right side	Door (Wellig und Einschlüsse) - Unprofessionally repaired - Lacquer
8	Vehicle glazing	Windscreen - Broken / torn - repair according to calculation

Previous damages

No.	Previous damage	Extent of damage (Net)
1	Side - left, Provided by user / customer, from 13 Oct 2025	1.324,10 €
2	Side right, Provided by user / customer, from 12 Nov 2025	1.622,19 €
3	Side right, Provided by user / customer, from 3 Aug 2022	1.940,06 €
4	Side right, Provided by user / customer, from 20 Aug 2023	2.183,59 €

Repainting

No.	Repainting
1	Mudguard - right side, Professionally carried out
2	Bonnet, Professionally carried out
3	Side panel - rear left side, Professionally carried out
4	Side panel - rear right side, Professionally carried out
5	Door - rear right side, Unprofessionally carried out
6	Door - front right side, Unprofessionally carried out

Paint coat thickness measurement

Mudguard - right side	243 µm	Bonnet	236 µm
Side panel - rear left side	215 µm	Side panel - rear right side	294 µm
Door - rear right side	442 µm	Door - front right side	231 µm

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
  (Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
  (Functional testing of driver assistance systems is not included in the scope of services!)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

According to available information previous damages were repaired at the vehicle. Traces of repairs, which allow conclusions about the area of repair, were not recognizable during the inspection.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)



Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel

Figure 9: Interior 360° view (Online Link)



Figure 10: Cargo area




Figure 11: VIN



Figure 12: Mounted tyres




Figure 13: Documents



Figure 14: Additional tyres



Figure 15: Additional tyres



Figure 16: Navigation



Figure 17: Misc.



Figure 18: Misc.



Figure 19: Misc.



Figure 20: Misc.



Figure 21: Misc.



Figure 22: Misc.



Figure 23: Misc.



Figure 24: Misc.



Figure 25: Misc.



Figure 26: Misc.



Figure 27: Misc.



Figure 28: Misc.



Damage 1: Equipment: Tirefit filler - Expired - Replace



Damage 2: Roof: Roof rail - left side - dent(s) - Smooth repair work



Damage 2: Roof: Roof rail - left side - dent(s) - Smooth repair work



Damage 2: Roof: Roof rail - left side - dent(s) - Smooth repair work



Damage 3: Side panel - rear left side: Side panel - dent(s) - Smart repair



Damage 3: Side panel - rear left side: Side panel - dent(s) - Smart repair



Damage 3: Side panel - rear left side: Side panel - dent(s) - Smart repair



Damage 3: Side panel - rear left side: Side panel - dent(s) - Smart repair




Damage 3: Side panel - rear left side: Side panel - dent(s) - Smart repair




Damage 4: Wheel / tyres: Alloy rim - front left side - Scratch(es) - Loss in value




Damage 4: Wheel / tyres: Alloy rim - front left side - Scratch(es) - Loss in value




Damage 4: Wheel / tyres: Alloy rim - front left side - Scratch(es) - Loss in value



Damage 5: Bonnet: Bonnet - dent(s) - Smooth repair work



Damage 5: Bonnet: Bonnet - dent(s) - Smooth repair work




Damage 5: Bonnet: Bonnet - dent(s) - Smooth repair work



Damage 5: Bonnet: Bonnet - dent(s) - Smooth repair work



Damage 5: Bonnet: Bonnet - dent(s) - Smooth repair work




Damage 5: Bonnet: Bonnet - dent(s) - Smooth repair work



Damage 5: Bonnet: Bonnet - dent(s) - Smooth repair work




Damage 6: Door - rear right side: Door (Wellig) - Unprofessionally repaired - Lacquer



Damage 6: Door - rear right side: Door (Wellig) - Unprofessionally repaired - Lacquer




Damage 6: Door - rear right side: Door (Wellig) - Unprofessionally repaired - Lacquer




Damage 6: Door - rear right side: Door (Wellig) - Unprofessionally repaired - Lacquer



Damage 6: Door - rear right side: Door (Wellig) - Unprofessionally repaired - Lacquer




Damage 6: Door - rear right side: Door (Wellig) - Unprofessionally repaired - Lacquer




Damage 6: Door - rear right side: Door (Wellig) - Unprofessionally repaired - Lacquer




Damage 7: Door - front right side: Door (Wellig und Einschlüsse) - Unprofessionally repaired - Lacquer




Damage 7: Door - front right side: Door (Wellig und Einschlüsse) - Unprofessionally repaired - Lacquer




Damage 7: Door - front right side: Door (Wellig und Einschlüsse) - Unprofessionally repaired - Lacquer



Damage 7: Door - front right side: Door (Wellig und Einschlüsse) - Unprofessionally repaired - Lacquer



Damage 7: Door - front right side: Door (Wellig und Einschlüsse) - Unprofessionally repaired - Lacquer



Damage 7: Door - front right side: Door (Wellig und Einschlüsse) - Unprofessionally repaired - Lacquer



Damage 7: Door - front right side: Door (Wellig und Einschlüsse) - Unprofessionally repaired - Lacquer



Damage 8: Vehicle glazing: Windscreen - Broken / torn - repair according to calculation



Damage 8: Vehicle glazing: Windscreen - Broken / torn - repair according to calculation



Damage 8: Vehicle glazing: Windscreen - Broken / torn - repair according to calculation



Repainting 1: Mudguard - right side




Repainting 1: Mudguard - right side



Repainting 2: Bonnet



Repainting 2: Bonnet



Repainting 3: Side panel - rear left side



Repainting 3: Side panel - rear left side



Repainting 4: Side panel - rear right side



Repainting 4: Side panel - rear right side



Repainting 5: Door - rear right side



Repainting 5: Door - rear right side



Repainting 6: Door - front right side



Repainting 6: Door - front right side