MACADAM









PEUGEOT 3008: GP-236-DH

Vinnumber:	**VF3MRHNSUPS069599**	Versionname:	**PEUGEOT 3008 PureTech 130 S&S EAT8 Active Pack VP [5P] bva 8-130CH-7cv (SUV)**
First Registrationdate:	**26/05/2023**	Fiscalpower:	
Expertise Mileage:	**153492**	Power Kw:	**96**
Bodytype:	**SUV**	Body colour	**White**
Gearbox:	**Automatic**	Paint type	**Metalic**
Transmission:	**Front**	Interior colour	**Black**
Fueltype:	**Petrol**	Type of rims (mounted)	**Aluminium**
Engine functioning	**Yes**	Dashboard color	**Black**
Battery functioning	**Yes**		
Vehicle running	**Yes**		
Number of doors	**5**		
Number of seats	**5**		
Number head rests	**5**		
Type of rims (mounted)	**Aluminium**		
Category	**Passenger Car**		

Options

Number of keys total	**2**	Radio	
Number keys remote	**2**	Central consol F	
Windows electric F		Luggage cover	
Windows electric R		Headlights Xenon/LED/Laser	
Cruise Control		Rear parking sensors	
Steering wheel multifunctional		Rear view camera	
Steering wheel leather		Seat cover lining	**Lining Other**
Type of climate control	**Autom climate control**		

Tyres

Summer tyres:	**215/65/17/103 V**			
	Fr.L.	**Continental: 30%**	Fr.R.	**Continental: 25%**
	Re.L.	**Continental: 35%**	Re.R.	**Continental: 35%**

Tyre profile depth FL	**6.1**
Tyre profile depth FR	**6.4**
Tyre profile depth RL	**5.9**
Tyre profile depth RR	**5.9**
Tyre size FL	**215/65 R 17 103 V**
Tyre size FR	**215/65 R 17 103 V**
Tyre size RL	**215/65 R 17 103 V**
Tyre size RR	**215/65 R 17 103 V**
Tyre type FL	**Summer**
Tyre type FR	**Summer**
Tyre type RL	**Summer**
Tyre type RR	**Summer**
Tyre make FL	**256**
Tyre make FR	**256**
Tyre make RL	**256**
Tyre make RR	**256**

Assistance equipment

Interior, Stain, Cleaning









Outside rear-view mirror housing L, Scratch(es), Polish




Windscreen, Stone chip(s), Windscreen repair 2 stonechips






Outside rear-view mirror housing R, Scratch(es), Paint




Side repeater R, Scratch(es), Replace




Internal boot lining R, Scratch(es), Replace





Internal boot lining L, Scratch(es), Repair/replace (lump sum)





Boot lid covering R, Scratch(es), Repair/replace (lump sum)




Bumper moulding R, Broken, Replace




ALPHABET

Historique Maintenance

Immatriculation: **GP-236-DH** Date de 1ère immatriculation: **26/05/2023**

Modèle: **Peugeot 3008 PureTech 130 S&S EAT8 Active Pack VP [5P] bva 8-130CH-7cv (SUV)**

Date	Kilométrage	Fournisseur	Descriptif
11/05/2026	144.980	CHOPARD ESTEREL TRANS EN PROVENCE	REVISION
	0		LIQUIDE DE REFROIDISSEMENT RPLT
	0		FILTRE CLIM RPLT
08/01/2026	124.325	CHOPARD ESTEREL SCP	REVISION
	0		BOITIER D ALLUMAGE RPLT
	0		FILTRE A AIR RPLT
	0		FILTRE CLIM RPLT
27/11/2025	117.067	CONTITRADE FRANCE	PERMUTATIONS PNEUS
22/08/2025	103.619	FLEET SOLUTIONS FRANCE	REMPLACEMENT PNEUS ETE
	0		REMPLACEMENT PNEUS ETE
13/08/2025	102.371	CHOPARD AZUR	DIVERS FREIN
	0		REVISION
	0		FILTRE CLIM RPLT
	0		PLAQUETTES AV RPLT
22/04/2025	87.450	CONTITRADE FRANCE	PERMUTATIONS PNEUS
02/04/2025	84.263	CHOPARD AZUR	BALAIS ESSUIE GLACE AV
	0		BOITIER D ALLUMAGE RPLT
	0		FILTRE A AIR RPLT
	0		LIQUIDE DE FREIN
	0		FILTRE CLIM RPLT
	0		BALAI ESSUIE GLACE AR
	0		REVISION
16/12/2024	63.851	CONTITRADE FRANCE	PERMUTATIONS PNEUS
08/11/2024	63.193	CHOPARD ESTEREL SCP	REVISION
03/06/2024	42.429	CHOPARD ESTEREL SCP	FILTRE CLIM RPLT
	0		REVISION
	0		BOITIER D ALLUMAGE RPLT
	0		FILTRE A AIR RPLT
21/05/2024	40.499	CONTITRADE FRANCE	PERMUTATIONS PNEUS
10/05/2024	40.214	CONTITRADE FRANCE	PERMUTATIONS PNEUS
10/01/2024	21.134	CONTITRADE FRANCE	REMPLACEMENT PNEUS HIVER
19/12/2023	20.644	CHOPARD ESTEREL SCP	REVISION