MACADAM







## Peugeot 508 (KKL): 2CQZ987

| | | | |
|---|---|---|---|
| Vinnumber: | **VR3FRHNSTNY583171** | Versionname: | **508 SW GT 1.2 PureTech 130pk/cv S&S 5p EAT8** |
| First Registrationdate: | **25/10/2022** | Fiscalpower: | |
| Expertise Mileage: | **114422** | Power Kw: | **96** |
| Bodytype: | | Type of rims (mounted) | **Aluminium** |
| Gearbox: | **Automatic** | | |
| Transmission: | | | |
| Fueltype: | **Petrol** | | |
| Maintenance | **OK** | | |
| Maintenance | **plus 17500 km** | | |
| Battery functioning | **Yes** | | |
| Type of rims (mounted) | **Aluminium** | | |
| Certificate of Conformity | **Yes** | | |
| Category | **Passenger Car** | | |
| Registration Certificate Car (BE) | **Yes** | | |

## Options

| | | | |
|---|---|---|---|
| Number of keys total | **2** | Type of Tow bar | **No Tow bar** |
| GPS | | | |
| Type of Maintenance book | **Digital maintenance** | | |
| Type of GPS storage | **HD** | | |

## Tyres

| | | | | |
|---|---|---|---|---|
| Summer tyres: | **235/45/18/98 Y** | | | |
| | Fr.L. | **Semperit: 4 mm** | Fr.R. | **Semperit: 5 mm** |
| | Re.L. | **Michelin: 4 mm** | Re.R. | **Michelin: 4 mm** |

| | |
|---|---|
| Tyre profile depth FL | **4.0** |
| Tyre profile depth FR | **5.0** |
| Tyre profile depth RL | **4.0** |
| Tyre profile depth RR | **4.0** |
| Tyre size FL | **235/45 R 18 98 Y** |
| Tyre size FR | **235/45 R 18 98 Y** |
| Tyre size RL | **235/45 R 18 98 W** |
| Tyre size RR | **235/45 R 18 98 W** |
| Tyre type FL | **Summer** |
| Tyre type FR | **Summer** |
| Tyre type RL | **Summer** |
| Tyre type RR | **Summer** |
| Tyre make FL | **2477** |
| Tyre make FR | **2477** |
| Tyre make RL | **261** |
| Tyre make RR | **261** |

## Assistance equipment

| | | | |
|---|---|---|---|
| Repair kit | **Yes** | Compressor | **Yes** |

## Bumper F, Scratch(es), Acceptable




## Bonnet, Dent(s), Acceptable





Wing FL, Scratch(es), Acceptable




Alloy rim FL polished, Scratch(es), Repair and paint (complete)







Outside rear-view mirror housing L, Scratch(es), Acceptable




Door FL, Scratch(es), Acceptable





Door RL, Dent(s) and scratch(es), Acceptable





Alloy rim RL polished, Scratch(es), Repair and paint (complete)







Boot lid covering R, Scratch(es), Replace




Bumper R, Dent(s), Acceptable




Alloy rim RR polished, Scratch(es), Repair and paint (complete)








Wing RR, Dent(s), Acceptable




Door RR, Scratch(es), Acceptable




Step R, Dent(s) and scratch(es), Acceptable




Outside rear-view mirror housing R, Scratch(es), Acceptable




Alloy rim FR polished, Scratch(es), Repair and paint (complete)





Tyre FR, Tear, Replace




Door FR, Dent(s), Acceptable




# Onderhoudshistorie van: VR3FRHNSTNY583171

ALPHABET

| | |
|---|---|
| **Kenteken** | 2CQZ987 |
| **Merk Model** | Peugeot 508 SW GT 1.2 PureTech 130pk/cv S&S 5p EAT8 |
| **Brandstofsoort** | Benzine |
| **Datum deel1** | 10/25/22 |

| Datum reparatie | Kilometerstand | Reparatie omschrijving | Bewerking |
|---|---|---|---|
| 10/2/26 | 113,434 | nazicht technische keuring | Uitvoeren |
| 9/16/26 | 111,999 | distributieriem | Vervangen |
| 9/16/26 | 111,999 | onderhoud 4e jaar | Uitvoeren |
| 9/16/26 | 111,999 | riem of multiriem | Vervangen |
| 12/23/25 | 92,121 | 90000 km | Uitvoeren |
| 12/23/25 | 92,121 | oliezeef | Vervangen |
| 4/25/25 | 70,861 | 70000 km | Uitvoeren |
| 4/25/25 | 70,861 | ruitenwisserrubber vooraan | Vervangen |
| 8/13/24 | 50,899 | 50000 km | Uitvoeren |
| 8/13/24 | 50,899 | brandstof hoofdfilter | Vervangen |
| 8/13/24 | 50,899 | luchtfilter | Vervangen |
| 8/13/24 | 50,899 | luchtfilter interieur | Vervangen |
| 8/13/24 | 50,899 | oliezeef | Vervangen |
| 11/14/23 | 29,874 | 30000 km | Uitvoeren |
| 11/14/23 | 29,874 | oliezeef | Vervangen |
| 11/14/23 | 29,874 | ruitenwisserrubber vooraan | Vervangen |
| 5/11/23 | 15,516 | controle niveaus | Uitvoeren |
| 4/27/23 | 14,603 | controle niveaus | Uitvoeren |
| 4/6/23 | 12,075 | diagnose | Uitvoeren |
| 4/6/23 | 12,075 | parkeersensor vooraan | Vervangen |