TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Hartmann Fleet Professionals GmbH
Industriestraße 11
36272 Niederaula

Expertise

Protocol number: 48476875
Order No. / Reference: 27191629
Inspection date: 3 Nov 2026

Manufacturer: Skoda	Model: Octavia Combi 2.0 TDI DSG Style
VIN: TMBJG8NX9RY100424	





Vehicle details

Manufacturer / Type / Model / Equipment	
Skoda Octavia Combi 2.0 TDI DSG Style	
Vehicle Identification number	TMBJG8NX9RY100424
Mileage (Read)	183,955 km
First registration	19 Feb 2024
Number of holders	1
Next periodical technical inspection	02/2027
(Report not on hand)	
Fuel type	Diesel
Engine displacement / Cylinder	1,968 ccm / 4
Power	85 kW
Gearbox / Number of gears	Automatic / 7
Type of drive	Front drive
Type of vehicle	Station wagon
Colour / colour code	Reflexsilber metallic
Doors / Seats	5 / 5
Upholstery type	Cloth
Colour of upholstery	Grey-Black
Re-import	no
Vehicle with smoke odor	no
readiness to drive	Roadworthy

TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Hartmann Fleet Professionals GmbH
Industriestraße 11
36272 Niederaula

Vehicle details

Maintenance booklet / proof	digital proof / complete	**Next maintenance in**	22,600 km
Last service on / at	08/2026 at 180,305 km		
Key is / should be	2 / 2	**FZG documents**	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	GY985026
Previous damage / Accident	Detectable	**Repainting**	Detectable
Inspection conditions	sufficient	**Lifting equipment / pit**	yes
Test drive	Not performed	**Engine function test**	Performed
readiness to drive	Roadworthy		
Manufacturer key number/ type code number	8004 / AWK 00687		
Emission standard	EURO6	**fine dust sticker**	
Permitted total weight	1,970 kg	**Empty weight**	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	205/55 R17 91V	Summer tyres on Light alloy	Michelin	2mm / 2mm
2)	205/55 R17 91V	Summer tyres on Light alloy	unterschiedliche Hersteller	5mm / 5mm

Additional tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	205/60 R16 96H	Winter tyres on Light alloy	Continental	5mm / 5mm
2)	205/60 R16 96H	Winter tyres on Light alloy	Pirelli	5mm / 5mm

Replacement

Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
	Tirefit	Expiration date 10/2027		

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

Equipment

Standard equipment

- Storage compartment in the luggage compartment with cargo element
- Airbag, driver's knee airbag
- Airbag, front side airbags
- Ambient lighting
- Traction control (ASR)
- Automatically dimming exterior mirror (driver's side)
- Exterior mirrors with memory function
- Heated windshield washer nozzles including 5l washer fluid reservoir
- Glasses compartment in the headliner
- AERO anodized roof rails
- Diesel particulate filter
- Tachometer
- Electronic parking brake including auto-hold function
- Electronic Stability Control (ESC)
- Electric windows front and rear, including anti-pinch protection and child safety lock
- Cruise control system
- Tinted windows
- Heated rear window
- Rear window wiper including windshield washer system
- ISOFIX preparations on the front passenger seat and the outer rear seats including top tether anchorage
- Climatronic air conditioning (2-zone)
- Headrests (5) front and rear height adjustable
- LED taillights in crystal glass look and animated turn signals
- Remote release of the rear seat backrests in the trunk
- Steering wheel: Leather steering wheel with multifunction buttons and paddle shifters.
- Front center armrest, including storage compartment
- Fatigue detection
- Upholstery: Cloth
- Radio accessories: 2 USB-C ports on the front
- Radio accessories: Bluetooth hands-free system
- Radio accessories: SmartLink
- Rain sensor and driving light assistant
- Tire mobility kit
- Electromechanical power steering
- Safety lights in the front side doors
- Seats: Electrically adjustable front seats with memory function
- SKODA Care Connect
- Lane keeping assistant (Lane Assist)
- 12V socket in the trunk
- Phone: Wireless SmartLink for Apple CarPlay
- Lashing eyes in the trunk
- Central locking including remote control integrated into the key and EASY Start
- Storage compartments
- Airbag, driver and passenger
- Airbag, head airbags
- Airbag: Center airbag front
- Anti-lock braking system (ABS)
- Center section of the dashboard with fabric covering
- Electrically adjustable and heated exterior mirrors
- Electrically folding exterior mirrors
- Hill start assist
- Hydraulic brake assist (HBA)
- Grey headliner
- Decorative strip in silver square with ambient lighting
- Digital Cockpit Plus
- Third brake light
- Electronic transverse differential lock (XDS+)
- Driving profile selection
- Front radar assistant including city emergency braking function and pedestrian and cyclist detection
- Transmission: 7-speed dual-clutch transmission (DSG)
- Green tec: Start/stop system including brake energy recuperation
- Interior mirror automatically dimming
- Kessy, keyless entry and start-stop system
- Child safety lock for the rear doors and windows
- Removable boot cover
- LED fog lights
- LED license plate lights
- LED headlights with LED daytime running lights
- Steering wheel: height and reach adjustable
- Manual headlight range adjustment
- Rear center armrest with pass-through option
- Engine drag torque control (MSR)
- Front and rear parking sensors
- Radio: Bolero music system with 10" display
- Radio accessories: 8 speakers
- Radio accessories: Digital radio reception DAB+
- Radio accessories: Voice control
- Tire pressure monitoring
- Wheels: 17" Rotare AERO alloy wheels
- Seat belts
- Seats: Heated front seats
- Seats: Height-adjustable driver and passenger seats
- Seats: Rear seat backrest split 60:40, foldable
- Speed limiter
- Lane change and parking assist as well as exit warning
- Telephone: Phonebox with inductive charging function (connection via external antenna)
- Immobiliser

Extra equipment

- Package: Infotainment package Business Columbus (Style, RS) DSG (Columbus navigation system - Infotainment Online (3-year term), online map updates: for navigation, traffic situation, petrol stations and parking space search - 3 USB charging ports - Head-Up Display - Adaptive Cruise Control (ACC) - Traveller Assist system: - Traffic sign recognition - Adaptive Lane Keeping Assist - Emergency and traffic jam assist - Capacitate steering wheel with Hands Off Detection)
- Luggage net partition
- Paint finish: Metallic
- Rear view camera

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. Lifting equipment and/or a pit were available for examining the vehicle.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.
readiness to drive	The vehicle was roadworthy at the time of inspection.

Value reducing factors

No.	Component group	Description
1	Equipment	Vehicle key (Batterie) - Empty - Replace
2	Seat - rear	Upholstery (Fussmatte rechts und Teppich) - Soiled - Clean
3	Boot lid / rear door	Boot lid - Glued / labelled - De-glue / neutralise
4	Bonnet	Bonnet (Matte Stellen vom Finish) - Paint defect - Smart repair
5	Side panel - rear left side	Side panel - Scratch(es) - Paint
6	Rear bumper	Rear bumper - Scratch(es) - Paint
7	Front bumper	Front bumper (Viele) - Stone chips - Paint

Wear and tear

No.	Component group	Description
1	Wheel / tyres	Tyre - front (links und rechts 2,2mm) - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.

Repainting

No.	Repainting
1	Roof rail - right side, Professionally carried out, Invoice of repair done Non-existent
2	Bonnet, Unprofessionally carried out, Invoice of repair done Non-existent

Paint coat thickness measurement

Roof	105 µm	Roof rail - left side	105 µm
Roof rail - right side	171 µm	Boot lid / rear door	102 µm
Mudguard - left side	108 µm	Mudguard - right side	104 µm
Bonnet	215 µm	Side panel - rear left side	104 µm
Side panel - rear right side	103 µm	Door - rear left side	109 µm
Door - rear right side	110 µm	Door - front left side	105 µm
Door - front right side	101 µm		

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
  (Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
  (Functional testing of driver assistance systems is not included in the scope of services!)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Comments

- Sommerbereifung vorne 2,25mm rechts, 2,71mm links

- Winterradsatz ist kein Bestandteil des Auslieferumfangs.

TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Hartmann Fleet Professionals GmbH
Industriestraße 11
36272 Niederaula



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)




Figure 5: Interior - front




Figure 6: Interior - front



Figure 7: Interior - rear



Figure 8: Interior - rear



Figure 9: Instrument cluster



Figure 10: Instrument panel



Figure 11: Instrument panel

Figure 12: Interior 360° view (Online Link)



Figure 13: Cargo area




Figure 14: VIN




Figure 15: VIN



Figure 16: Mounted tyres




Figure 17: Mounted tyres



Figure 18: Mounted tyres



Figure 19: Mounted tyres



Figure 20: Mounted tyres



Figure 21: Documents



Figure 22: Additional tyres



Figure 23: Navigation



Figure 24: Misc.



Figure 25: Misc.



Figure 26: Misc.



Figure 27: Misc.



Figure 28: Misc.



Figure 29: Misc.



Figure 30: Misc.



Figure 31: Misc.



Figure 32: Misc.



Figure 33: Misc.



Figure 34: Misc.



Figure 35: Misc.



Figure 36: Misc.



Figure 37: Misc.



Figure 38: Misc.



Figure 39: Misc.



Figure 40: Misc.



Figure 41: Misc.



Figure 42: Misc.



Figure 43: Misc.



Figure 44: Misc.



Figure 45: Misc.



Figure 46: Misc.



Figure 47: Diagonal front



Figure 48: Diagonal front




Figure 49: Diagonal rear



Figure 50: Diagonal rear




Figure 51: Engine compartment



Figure 52: Sill



Figure 53: Sill




Damage 1: Equipment: Vehicle key (Batterie) - Empty - Replace



Damage 2: Seat - rear: Upholstery (Fussmatte rechts und Teppich) - Soiled - Clean



Damage 2: Seat - rear: Upholstery (Fussmatte rechts und Teppich) - Soiled - Clean



Damage 2: Seat - rear: Upholstery (Fussmatte rechts und Teppich) - Soiled - Clean



Damage 2: Seat - rear: Upholstery (Fussmatte rechts und Teppich) - Soiled - Clean



Damage 3: Boot lid / rear door: Boot lid - Glued / labelled - De-glue / neutralise



Damage 3: Boot lid / rear door: Boot lid - Glued / labelled - De-glue / neutralise



Damage 4: Bonnet: Bonnet (Matte Stellen vom Finish) - Paint defect - Smart repair



Damage 4: Bonnet: Bonnet (Matte Stellen vom Finish) - Paint defect - Smart repair




Damage 4: Bonnet: Bonnet (Matte Stellen vom Finish) - Paint defect - Smart repair




Damage 4: Bonnet: Bonnet (Matte Stellen vom Finish) - Paint defect - Smart repair



Damage 4: Bonnet: Bonnet (Matte Stellen vom Finish) - Paint defect - Smart repair



Damage 4: Bonnet: Bonnet (Matte Stellen vom Finish) - Paint defect - Smart repair



Damage 4: Bonnet: Bonnet (Matte Stellen vom Finish) - Paint defect - Smart repair



Damage 4: Bonnet: Bonnet (Matte Stellen vom Finish) - Paint defect - Smart repair



Damage 5: Side panel - rear left side: Side panel - Scratch(es) - Paint



Damage 5: Side panel - rear left side: Side panel - Scratch(es) - Paint



Damage 6: Rear bumper: Rear bumper - Scratch(es) - Paint



Damage 6: Rear bumper: Rear bumper - Scratch(es) - Paint



Damage 6: Rear bumper: Rear bumper - Scratch(es) - Paint



Damage 6: Rear bumper: Rear bumper - Scratch(es) - Paint



Damage 7: Front bumper: Front bumper (Viele) - Stone chips - Paint



Damage 7: Front bumper: Front bumper (Viele) - Stone chips - Paint



Damage 7: Front bumper: Front bumper (Viele) - Stone chips - Paint



Damage 7: Front bumper: Front bumper (Viele) - Stone chips - Paint



Damage 7: Front bumper: Front bumper (Viele) - Stone chips - Paint



Damage 7: Front bumper: Front bumper (Viele) - Stone chips - Paint



Damage 7: Front bumper: Front bumper (Viele) - Stone chips - Paint




Damage 7: Front bumper: Front bumper (Viele) - Stone chips - Paint



Damage 7: Front bumper: Front bumper (Viele) - Stone chips - Paint



Damage 7: Front bumper: Front bumper (Viele) - Stone chips - Paint



Repainting 1: Roof rail - right side



Repainting 1: Roof rail - right side



Repainting 2: Bonnet



Repainting 2: Bonnet



Roof rail - right side: 171 µm



Bonnet: 215 µm