AUDI Q3 SPORTBACK

Vehicle information

Make:	**AUDI**	License:	**2BTF336**
Gearbox:		Body color:	
Model:	**Q3 SPORTBACK**	VIN:	**WAUZZZF31N1098487**
Fuel type:		Power:	**110 kW**
Version:	**1.4 45 TFSI E S TRONIC**	First registration	**15/03/2022**
Mileage:	**93695 km**	N° of doors:	


Damage summary


Front	1
Interior	2
Right	1
Roof & others	2

Commercial pictures


































Options according to the inspector

GPS	**Yes**

Damages


Bodywork
Damaged
Acceptable
Roof & others










Door FR
Scratch(es)
Paint
Right

Ignition key
Missing
Replace
Interior




Interior

Damaged


Acceptable

Interior










Roof

Chemical polution

Paint

Roof & others









Windscreen
Stone chip(s)
Replace
Front







Tyres

Front Left
All season
Aluminium
235/55/18/104/V
Bridgestone
3.0 mm
Front Right
All season
Aluminium
235/55/18/104/V
Bridgestone
3.0 mm
Rear Left
All season
Aluminium
235/55/18/104/V
Michelin
5.0 mm
Rear Right
All season
Aluminium
235/55/18/104/V
Michelin
5.0 mm

Checks

Category	**Passenger Car**	Certificate of Conformity	**Yes**
Compressor	**Yes**	Maintenance	**OK**
Maintenance	**in 4800 km**	Number of charging cables (normal)	**0**
Number of charging cables (rapid charge)	**0**	Number of keys total	**1**
Registration Certificate Car (BE)	**Yes**	Registration Certificate Home (BE)	**No**
Repair kit	**Yes**	Reset to factory settings	**Yes, vehicle is reset to factory settings**
Statutory inspection	**15/03/2027**	Statutory inspection	**OK**
Type of Maintenance book	**Digital maintenance**		

Information on the content and the scope of the inspection report:

- The assessment is based on the sales standards specified by the customer.
- Acceptable usage damages according to the sales standards are not always documented in this status report.
- The specified repair methods and/or resulting repair times have been determined, taking into account modern industrial repair methods.
- The purchasing dealer should assess individual repair costs.
- The inspection was carried out in a non-disassembly condition. Macadam cannot be held responsible for any missing information. For further information, please contact the seller.