TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Hartmann Fleet Professionals GmbH
Leerenstraße 25
29683 Bad Fallingbostel

Expertise

Protocol number: 48072116
Order No. / Reference: 27097586
Inspection date: 12 Oct 2026

Manufacturer: Skoda	Model: Kodiaq 2.0 TDI 4x4 DSG Sportline
VIN: TMBLN9NS9M8519150	





Vehicle details

Manufacturer / Type / Model / Equipment	
Skoda Kodiaq 2.0 TDI 4x4 DSG Sportline	
Vehicle Identification number	TMBLN9NS9M8519150
Mileage (Read)	197,138 km
First registration	8 Jul 2021
Number of holders	2
Fuel type	Diesel
Engine displacement / Cylinder	1,968 ccm / 4
Power	147 kW
Gearbox / Number of gears	Automatic / 7
Type of drive	All-wheel drive
Type of vehicle	SUV
Colour / colour code	Metal Grey Metallic (F7Y)
Doors / Seats	5 / 5
Upholstery type	Alcantara / Leather
Colour of upholstery	Black

Vehicle details

Maintenance booklet / proof	digital proof / complete	**Next maintenance in**	23,800 km
Last service on / at	08/2026 at 190,889 km		
Key is / should be	3 / 3	**FZG documents**	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	GD048592
Previous damage / Accident	Detectable	**Repainting**	Detectable
Inspection conditions	sufficient	**Lifting equipment / pit**	yes
Test drive	Not performed	**Engine function test**	Performed
Manufacturer key number/ type code number	8004 / AVW 00276		
Emission standard	EURO6	**fine dust sticker**	
Permitted total weight	2,369 kg	**Empty weight**	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	235/50 R19 99V	Summer tyres on Light alloy	Pirelli	5mm / 5mm
2)	235/50 R19 99V	Summer tyres on Light alloy	Pirelli	5mm / 5mm

Additional tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	235/55 R18 104H	Winter tyres on Light alloy	Dunlop	6mm / 6mm
2)	235/55 R18 100H	Winter tyres on Light alloy	Continental	6mm / 6mm

Replacement

Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
N	145/85 R18 103M	Summer tyres on Steel	Sonstige	3 mm

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

Equipment

Standard equipment

- Storage compartment on the left wheel arch
- Storage compartments (ticket holder on the windshield, closed storage compartment on the driver's side, 4 roof grab handles, rear with coat hooks, coat hooks on the B-pillar, high-visibility vest compartment in the front doors, sunglasses compartment in the headliner, storage compartments in the door panels (front and rear) with bottle holders (1.5l front, 1l rear), cup holder in the front center console with "Easy-Open" bottle opening, storage pockets on the front seatbacks)
- Traction control (ASR)
- Electrically adjustable and heated exterior mirrors with integrated side indicators
- Hydraulic brake assist
- Cargo elements in the trunk
- Roof rails, black
- Diesel particulate filter
- Third brake light (in the rear spoiler (LED))
- Easy Start (start-stop button instead of the ignition lock)
- Electronic parking brake including auto-hold function
- Electronic transverse differential lock (XDS+)
- Driving light assistant and rain sensor ((tunnel light, coming and leaving home function))
- Electric windows front and rear (including anti-pinch protection and child safety lock)
- front and rear floor mats
- Front and rear footwell lighting
- Transmission: 7-speed dual-clutch transmission (DSG)
- Green tec (Start/Stop automatic including brake energy recuperation)
- Aero rear window wiper including windshield washer system
- Climatronic air conditioning (2-zone) (fully automatic, separately adjustable for driver and front passenger, including humidity sensor, odor and allergen filter and air-conditioned glove compartment)
- LED ambient lighting (decorative strips in the door panels with selectable color climate, LED reading lights in the front, LED lighting for the make-up mirrors in the sun visors)
- LED taillights
- Steering wheel: Sport leather steering wheel (DSG) with multifunction buttons (including paddle shifters)
- Front center armrest, including storage compartment
- Fog lights with integrated LED daytime running lights
- Rear parking sensors
- Progressive steering
- Radio accessories: Digital radio reception DAB+
- Radio accessories: Wireless SmartLink (Apple CarPlay)
- Tire mobility kit (tire repair spray incl. compressor)
- Wheels: 19" alloy wheels Triglav anthracite polished (7Jx19 tires 235/50 R19 99V ET43)
- Heated windshield washer nozzles
- Electromechanical power steering
- Seats: Heated front and outer rear seats
- Storage compartments behind the wheel arches in the trunk
- Airbag for driver and front passenger (passenger airbag can be deactivated)
- Airbag, driver's knee airbag
- Airbag, head airbags
- Airbag, front side airbags
- Allergen filter
- Permanent all-wheel drive
- Anti-lock braking system (ABS)
- Electrically folding exterior mirrors including interior and exterior mirrors with automatic dimming.
- Hill start assist
- Care Connect: Proactive services (10-year term) (Remote Access (1-year term))
- Carbon decorative inlay with SPORTLINE logo
- Tachometer
- Third vehicle key
- eCall (automatic emergency call function in case of an accident with airbag deployment)
- ESC Electronic Stability Control
- Driving profile selection
- Chassis: Adaptive chassis DCC including off-road assistant
- Front radar assistant including city emergency braking function with pedestrian detection
- Cruise control
- Tinted windows
- Illuminated glove compartment
- Heated rear window
- Rear spoiler
- ISOFIX preparation on the outer rear seats (including top tether)
- Boot cover, roll-up and removable
- Front headrests are fixed, rear headrests are height-adjustable.
- LED headlights with LED daytime running lights (incl. adaptive front headlights (AFS): lighting system with fully automatic and situation-dependent light control (city, country road, motorway and bad weather mode), cornering lights, automatic headlight range control)
- Rear center armrest with cup holders and pass-through option
- MSR (Motor drag torque control)
- Network program in the trunk
- Upholstery: Microfiber Sport-Black
- Radio accessories: 8 speakers
- Radio accessories: SmartLink (MirrorLink, Android Auto and Apple CarPlay)
- Tire pressure monitoring
- Rear seat backrest split 60:40, foldable, longitudinally adjustable, backrest angle adjustable
- Headlights washer / wiper system
- Kodiaq safety belts (Height-adjustable three-point seat belts in the front, with belt tensioners - Three three-point seat belts in the rear - Belt fastening indicator in the front and in the second row of seats)

- Seats: Electrically adjustable front seats with memory function
- Seats: Driver and front passenger seats are height-adjustable (including adjustable lumbar support)
- Speed limiter
- 12V socket - in the center console and in the trunk
- Bumpers painted in body color (exterior mirrors and door handles painted in body color)
- Sunset (rear window and rear side windows tinted dark)
- Telephone: Comfort hands-free telephone system including phone box (with inductive charging function (connection via external antenna))
- Central locking with remote control
- Skoda Care Connect (SOS emergency call function (Emergency Call including automatic activation in the event of an accident with airbag deployment), Mobility service (connection for rapid assistance in case of breakdown), Information service (connection to the hotline for all questions regarding vehicle functions), Free remote vehicle access for 1 year (Remote Access) with access to vehicle data and functions via smartphone)
- Lashing eyes in the trunk
- Immobiliser

Extra equipment

- Swiveling trailer hitch (with electric release, including trailer stabilization)
- Digital instrument cluster (Virtual Cockpit) (with, among other functions: time, outside temperature, current fuel consumption, average fuel consumption, distance traveled, driving time, average speed, fuel range, service interval indicator, door and trunk lid warning, display of information from radio, navigation system and telephone (if available))
- Package: Business Columbus (Scout, Sportline) (Columbus dynamic radio navigation system - 9.2" capacitive color display - Color multifunction display in the instrument cluster - Driver fatigue detection - Traffic sign recognition - 230 V socket and USB port (Type-C) on the back of the front center armrest - Electric tailgate operation - Luggage net partition - Infotainment Online (3-year subscription))
- Radio accessories: CANTON sound system (9 speakers, 1 subwoofer, digital equalizer, 575W)
- Seats: Remote release of the rear seat backrests (2nd row) in the boot
- Engine underbody protection
- Variable loading floor in the trunk
- Traveller assistance system (DSG) (Adaptive Cruise Control ACC (control range up to 210 km/h) - Lane Assist - Adaptive Lane Guidance - Traffic Jam and Emergency Assist - Traffic Sign Recognition)
- High beam assist
- Kessy - keyless entry and start-stop system
- Paint finish: Metallic
- Steering wheel: Heated sports leather steering wheel (DSG) with multifunction buttons (including paddle shifters)
- Proactive occupant protection including rear side airbags
- Radio: Columbus infotainment system (Scout, Sportline) (Columbus dynamic radio navigation system - Capacitive 9.2" color display - Color multifunction display in the instrument cluster - Phonebox with inductive charging function (connection via external antenna) - Infotainment Online (1-year subscription))
- Wheels: 18" steel spare wheel, space-saving (tire 145/85 R18 incl. jack, wheel bolt wrench, load floor cover replaces tire mobility kit)
- Auxiliary heater with remote control
- 360° surround view camera (area view) including reversing camera

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. Lifting equipment and/or a pit were available for examining the vehicle.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.

Value reducing factors

No.	Component group	Description
1	Boot lid / rear door	Rear spoiler - Scratch(es) - Smart repair
2	Rear bumper	Rear bumper - Scratch(es) - Smart repair
3	Side panel - rear right side	Side panel - Scratch(es) - Smart repair
4	Bonnet	Bonnet - Dent / paintcoat damage - Loss in value
5	Side panel - rear left side	Side panel (Einschluss und wellig) - Unprofessionally repaired - Smart repair
6	Door - rear left side	Door (Wellig-Mehrkosten möglich) - Unprofessionally repaired - Smart repair
7	Wheel / tyres	Tyre - right - Porous / cracked - Replace
8	Roof	Roof - Corrosion - Repair and paint

Wear and tear

No.	Component group	Description
1	Trim / covers	Door trim - rear right side - dent(s) - No deduction
2	Boot lid / rear door	Boot lid - Dent / paintcoat damage - No deduction
3	Mudguard - right side	Mudguard - right side - Scratch(es) - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.

Missing parts

Description
Equipment - Umbrella

Previous damages

No.	Previous damage	Extent of damage (Net)
1	Side - left, Provided by user / customer, from 9 Apr 2022	1.304,58 €
2	Rear, Provided by user / customer, from 25 Jun 2026	1.457,09 €
3	Side - left, Provided by user / customer, from 4 Dec 2025	3.852,24 €

Repainting

No.	Repainting
1	Door - front left side, Professionally carried out, Invoice of repair done Non-existent
2	Side panel - rear left side, Unprofessionally carried out, Invoice of repair done Non-existent
3	Door - rear left side, Unprofessionally carried out, Invoice of repair done Non-existent

Paint coat thickness measurement

Side panel - rear left side	356 µm	Door - rear left side	190 µm
Door - front left side	200 µm		

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
  (Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
  (Functional testing of driver assistance systems is not included in the scope of services!)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

According to available information previous damages were repaired at the vehicle. Traces of repairs, which allow conclusions about the area of repair, were not recognizable during the inspection.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)




Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel

Figure 9: Interior 360° view (Online Link)



Figure 10: Cargo area




Figure 11: VIN



Figure 12: Mounted tyres



Figure 13: Documents



Figure 14: Additional tyres



Figure 15: Additional tyres




Figure 16: Navigation



Figure 17: Misc.



Figure 18: Misc.




Figure 19: Misc.




Figure 20: Misc.



Figure 21: Misc.




Figure 22: Misc.



Figure 23: Misc.



Figure 24: Misc.




Figure 25: Misc.



Figure 26: Misc.



Figure 27: Misc.




Figure 28: Misc.



Figure 29: Misc.



Figure 30: Misc.




Figure 31: Misc.



Figure 32: Misc.



Damage 1: Boot lid / rear door: Rear spoiler - Scratch(es) - Smart repair



Damage 1: Boot lid / rear door: Rear spoiler - Scratch(es) - Smart repair




Damage 2: Rear bumper: Rear bumper - Scratch(es) - Smart repair



Damage 2: Rear bumper: Rear bumper - Scratch(es) - Smart repair




Damage 2: Rear bumper: Rear bumper - Scratch(es) - Smart repair




Damage 3: Side panel - rear right side: Side panel - Scratch(es) - Smart repair



Damage 3: Side panel - rear right side: Side panel - Scratch(es) - Smart repair




Damage 3: Side panel - rear right side: Side panel - Scratch(es) - Smart repair




Damage 4: Bonnet: Bonnet - Dent / paintcoat damage - Loss in value




Damage 4: Bonnet: Bonnet - Dent / paintcoat damage - Loss in value




Damage 4: Bonnet: Bonnet - Dent / paintcoat damage - Loss in value



Damage 4: Bonnet: Bonnet - Dent / paintcoat damage - Loss in value



Damage 5: Side panel - rear left side: Side panel (Einschluss und wellig) - Unprofessionally repaired - Smart repair



Damage 5: Side panel - rear left side: Side panel (Einschluss und wellig) - Unprofessionally repaired - Smart repair



Damage 5: Side panel - rear left side: Side panel (Einschluss und wellig) - Unprofessionally repaired - Smart repair



Damage 5: Side panel - rear left side: Side panel (Einschluss und wellig) - Unprofessionally repaired - Smart repair



Damage 6: Door - rear left side: Door (Wellig-Mehrkosten möglich) - Unprofessionally repaired - Smart repair



Damage 6: Door - rear left side: Door (Wellig-Mehrkosten möglich) - Unprofessionally repaired - Smart repair



Damage 6: Door - rear left side: Door (Wellig-Mehrkosten möglich) - Unprofessionally repaired - Smart repair



Damage 6: Door - rear left side: Door (Wellig-Mehrkosten möglich) - Unprofessionally repaired - Smart repair



Damage 6: Door - rear left side: Door (Wellig-Mehrkosten möglich) - Unprofessionally repaired - Smart repair



Damage 7: Wheel / tyres: Tyre - right - Porous / cracked - Replace




Damage 7: Wheel / tyres: Tyre - right - Porous / cracked - Replace




Damage 7: Wheel / tyres: Tyre - right - Porous / cracked - Replace




Damage 8: Roof: Roof - Corrosion - Repair and paint



Damage 8: Roof: Roof - Corrosion - Repair and paint



Damage 8: Roof: Roof - Corrosion - Repair and paint



Damage 8: Roof: Roof - Corrosion - Repair and paint



Missing part 1: Equipment: Umbrella - Missing - Replace



Repainting 1: Door - front left side




Repainting 1: Door - front left side



Repainting 2: Side panel - rear left side



Repainting 2: Side panel - rear left side



Repainting 3: Door - rear left side

TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Hartmann Fleet Professionals GmbH
Leerenstraße 25
29683 Bad Fallingbostel



Repainting 3: Door - rear left side