MACADAM







Peugeot 5008 (KKL): 2BGW816

Vinnumber:	**VF3MCYHZUMS230166**	Versionname:	**5008 Active Pack 1.5 BlueHDi S/S 130pk/cv 5p EAT8**
First Registrationdate:	**22/11/2021**	Fiscalpower:	
Expertise Mileage:	**121304**	Power Kw:	**96**
Bodytype:		Type of rims (mounted)	**Aluminium**
Gearbox:	**Automatic**		
Transmission:			
Fueltype:	**Diesel**		
Maintenance	**OK**		
Maintenance	**plus 15800 km**		
Battery functioning	**Yes**		
Type of rims (mounted)	**Aluminium**		
Certificate of Conformity	**Yes**		
Category	**Passenger Car**		
Registration Certificate Car (BE)	**Yes**		

Options

Number of keys total	**2**	Luggage cover	
GPS		Type of Tow bar	**Tow bar removable**
Type of Maintenance book	**Digital maintenance**		
Type of GPS storage	**HD**		

Tyres

Summer tyres:	**215/65/17/99 V**			
	Fr.L.	**Pirelli: 3 mm**	Fr.R.	**Pirelli: 3 mm**
	Re.L.	**Pirelli: 5 mm**	Re.R.	**Pirelli: 4 mm**

Tyre profile depth FL	**3.0**
Tyre profile depth FR	**3.0**
Tyre profile depth RL	**5.0**
Tyre profile depth RR	**4.0**
Tyre size FL	**215/65 R 17 99 V**
Tyre size FR	**215/65 R 17 99 V**
Tyre size RL	**215/65 R 17 99 V**
Tyre size RR	**215/65 R 17 99 V**
Tyre type FL	**Summer**
Tyre type FR	**Summer**
Tyre type RL	**Summer**
Tyre type RR	**Summer**
Tyre make FL	**264**
Tyre make FR	**264**
Tyre make RL	**264**
Tyre make RR	**264**

Assistance equipment

Repair kit	**Yes**	Compressor	**Yes**

Seat cover FR, Stain, Cleaning




Seat cover FL, Stain, Acceptable




Bumper spoiler F, Scratch(es), Smart repair





Bumper F, Scratch(es), Spot repair





Bonnet, Scratch(es), Acceptable




Windscreen, Stone chip(s), Windscreen repair






Wing trim FL, Scratch(es), Replace




Door RL, Dent(s) and scratch(es), Acceptable




Door FL, Scratch(es), Acceptable




Wing RL, Scratch(es), Acceptable




Step L, Dent(s) and scratch(es), Spot repair




Rear bulkhead lining, Scratch(es), Acceptable




Internal boot lining L, Scratch(es), Smart repair




Internal boot lining R, Scratch(es), Smart repair




Bumper R, Scratch(es), Acceptable




Wiper arm rear, Broken, Replace




Rear window, Scratch(es), Acceptable




Bumper R, Dent(s), Acceptable





Wing RR, Dent(s), Acceptable




Wing trim FR, Scratch(es), Replace




Roof pillar R, Scratch(es), Acceptable

Door RR, Dent(s) and scratch(es), Spot repair




Door FR, Dent(s), Acceptable




Step R, Dent(s) and scratch(es), Spot repair




Onderhoudshistorie van: VF3MCYHZUMS230166

ALPHABET

Kenteken	2BGW816
Merk Model	Peugeot 5008 Active Pack 1.5 BlueHDi S/S 130pk/cv 5p EAT8
Brandstofsoort	Diesel
Datum deel1	11/22/21

Datum reparatie	Kilometerstand	Reparatie omschrijving	Bewerking
2/12/26	107,168	diagnose	Uitvoeren
11/6/25	105,004	brandstof hoofdfilter	Vervangen
11/6/25	105,004	luchtfilter	Vervangen
11/6/25	105,004	luchtfilter interieur	Vervangen
11/6/25	105,004	nazicht technische keuring	Uitvoeren
11/6/25	105,004	oliezeef	Vervangen
11/6/25	105,004	remblokken achter	Vervangen
11/6/25	105,004	remblokken vooraan	Vervangen
11/6/25	105,004	remvloeistof	Vervangen
11/6/25	105,004	ruitenwisserrubber achter	Vervangen
11/6/25	105,004	ruitenwisserrubber vooraan	Vervangen
9/6/24	79,917	75000 km	Uitvoeren
9/6/24	79,917	luchtfilter interieur	Vervangen
9/6/24	79,917	oliezeef	Vervangen
9/7/23	51,939	50000 km	Uitvoeren
9/7/23	51,939	brandstof hoofdfilter	Vervangen
9/7/23	51,939	luchtfilter	Vervangen
9/7/23	51,939	luchtfilter interieur	Vervangen
9/7/23	51,939	oliezeef	Vervangen
9/7/23	51,939	remvloeistof	Vervangen
11/7/22	24,199	25000 km	Uitvoeren
11/7/22	24,199	oliezeef	Vervangen