



Skoda Superb (KKL): 2AHD597

Vinnumber:	TMBJN9NP6M7062404	Versionname:	Superb Combi Ambition 1.5TSi 150pk/cv 5p DSG7
First Registrationdate:	1/04/2021	Fiscalpower:	
Expertise Mileage:	78269	Power Kw:	110
Bodytype:		Type of rims (mounted)	Aluminium
Gearbox:	Automatic		
Transmission:			
Fueltype:			
Maintenance	OK		
Maintenance	3100.0		
Maintenance	199 dagen		
Battery functioning	Yes		
Type of rims (mounted)	Aluminium		
Certificate of Conformity	Yes		
Category	Passenger Car		
Registration Certificate Car (BE)	Yes		

Options

Number of keys total	2	Luggage cover	
GPS		Type of Tow bar	Tow bar collapsible
Type of Maintenance book	Digital maintenance		
Type of GPS storage	HD		

Tyres

215/60/16/95 V				
Summer tyres:	Fr.L.	Continental: 4 mm	Fr.R.	Continental: 4 mm
	Re.L.	Continental: 4 mm	Re.R.	Continental: 4 mm
Tyre profile depth FL				4.0
Tyre profile depth FR				4.0
Tyre profile depth RL				4.0
Tyre profile depth RR				4.0
Tyre size FL				215/60 R 16 95 V
Tyre size FR				215/60 R 16 95 V
Tyre size RL				215/60 R 16 95 V
Tyre size RR				215/60 R 16 95 V
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				256
Tyre make FR				256
Tyre make RL				256
Tyre make RR				256

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		


Gear shift lever knob, Worn, Acceptable



Interior covering A pillar L, Scratch(es), Acceptable



Bumper F, Scratch(es), Spot repair



Door FL, Scratch(es), Acceptable



Wing RL, Scratch(es), Acceptable



Internal boot lining L, Scratch(es), Acceptable



Internal boot lining R, Scratch(es), Acceptable



Rear bulkhead lining, Scratch(es), Acceptable



Luggage compartment cover, Scratch(es), Acceptable



Boot lid covering R, Scratch(es), Acceptable



Tailgate / Boot, Scratch(es), Acceptable



Bumper R, Scratch(es), Repair and paint (complete)



Wing RR, Scratch(es), Acceptable



Wing FR, Scratch(es), Acceptable



Kenteken	2AHD597
Merk Model	Skoda Superb Combi Ambition 1.5TSi 150pk/cv 5p DSG7
Brandstofsoort	Benzine
Datum deel1	4/1/21

Datum reparatie	Kilometerstand	Reparatie omschrijving	Bewerking
12/10/24	51,367	batterij	Vervangen
12/10/24	51,367	bougie	Vervangen
12/10/24	51,367	Inspectie met olie vervanging (vast in	Uitvoeren
12/10/24	51,367	klein materiaal	
12/10/24	51,367	luchtfILTER interieur	Vervangen
12/10/24	51,367	ruitenswisserrubber achter	Vervangen
12/10/24	51,367	ruitenswisserrubber vooraan	Vervangen
12/10/24	51,367	ruitenswisservloeistof	Bijvullen/-laden
6/6/23	20,857	airco systeem reiniging	Uitvoeren
6/6/23	20,857	batterij	Vervangen
6/6/23	20,857	klein materiaal	Uitvoeren
6/6/23	20,857	luchtfILTER interieur	Vervangen
6/6/23	20,857	Onderhoudsbeurt met oliewissel (variab	Uitvoeren
6/6/23	20,857	remvloeistof	Vervangen
6/6/23	20,857	ruitenswisserrubber achter	Vervangen
6/6/23	20,857	ruitenswisserrubber vooraan	Vervangen
6/6/23	20,857	ruitenswisservloeistof	Bijvullen/-laden