



SKODA OCTAVIA: 2ARA713

Vinnumber:	TMBJP7NX3MY183061	Versionname:	
First Registrationdate:	17/06/2021	Fiscalpower:	
Expertise Mileage:	103796	Power Kw:	
Bodytype:		Body colour	Grey
Gearbox:	MAN 6 VIT	Type of rims (mounted)	Aluminium
Transmission:	Front		
Fueltype:	Petrol		
Maintenance	OK		
Number of doors	5		
Number of seats	5		
Number head rests	5		
Type of rims (mounted)	Aluminium		
Certificate of Conformity	Yes		
Category	Passenger Car		
Registration Certificate Car (BE)	Yes		
Registration Certificate Home (BE)	No		

Options

Number of keys total	2	Central consol F	
Number keys remote	2	Luggage cover	
Windows electric F		Front parking sensors	
Windows electric R		Rear parking sensors	
Board Computer		Roof bar alu	
Cruise Control		Type of Tow bar	No Tow bar
Steering wheel multifunctional			
Steering wheel leather			
Seats F heated			
Type of headlighting	Headlighting LED		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		
Type of radio	Multimedia		
Type of GPS storage	HD		

Tyres

205/60/16/92 V				
Summer tyres:	Fr.L.	Kumho: 3 mm	Fr.R.	Kumho: 3 mm
	Re.L.	Kumho: 6 mm	Re.R.	Kumho: 6 mm
Tyre profile depth FL				3.0
Tyre profile depth FR				3.0
Tyre profile depth RL				6.0
Tyre profile depth RR				6.0
Tyre size FL				205/60 R 16 92 V
Tyre size FR				205/60 R 16 92 V
Tyre size RL				205/60 R 16 92 V
Tyre size RR				205/60 R 16 92 V
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				2482
Tyre make FR				2482
Tyre make RL				2482
Tyre make RR				2482

Assistance equipment

Spare wheel	Yes	Jack	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	1389,59
Interior, Dirty, Cleaning	32,07



Engine insulation, Damaged, Replace	35,45
-------------------------------------	-------



Wing RL, Dent(s) and scratch(es), Repair and paint (complete)	459,03
---	--------



Door FL, Scratch(es), Acceptable	0,00
----------------------------------	------



Central pillar L, Scratch(es), Spot repair	127,11
--	--------



Bumper R, Dent(s) and scratch(es), Replace and paint	735,93
--	--------





Alloy rim RR, Scratch(es), Acceptable

0,00

