



BMW 5 Tourin

Vinnumber:	WBA71CG080CK39973	Versionname:	
First Registrationdate:	8/04/2022	Fiscalpower:	
Expertise Mileage:	140117	Power Kw:	
Bodytype:		Body colour:	Grey
Gearbox:	Automatic	Type of rims (mounted):	Aluminium
Transmission:		Parking lot:	3623
Fueltype:	Hybrid Petrol		
Maintenance:	OK		
Type of rims (mounted):	Aluminium		
Certificate of Conformity:	Yes		
Category:	Passenger Car		
Registration Certificate Car (BE):	Yes		

Options

Number of keys total:	1	Seats electric F L:	
Cruise Control:		Seats electric F R:	
Steering wheel multifunctional:		Luggage cover:	
Seats F heated:		Front parking sensors:	
Radio multimedia:		Rear parking sensors:	
Type of headlighting:	Headlighting LED	Type of Tow bar:	No Tow bar
Type of GPS:	GPS big screen color		
Type of Lining:	Lining leather		
Type of climate control:	Autom climate control		
Type of GPS storage:	HD		

Limited Technical Inspection

Tyres

245/45/18/100 Y				
Summer tyres:	Fr.L.	Goodyear: 3 mm	Fr.R.	Goodyear: 3 mm
	Re.L.	Pirelli: 7 mm	Re.R.	Pirelli: 7 mm
Tyre profile depth FL				3.0
Tyre profile depth FR				3.0
Tyre profile depth RL				7.0
Tyre profile depth RR				7.0
Tyre size FL				245/45 R 18 100 Y
Tyre size FR				245/45 R 18 100 Y
Tyre size RL				245/45 R 18 100 Y
Tyre size RR				245/45 R 18 100 Y
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				259
Tyre make FR				259
Tyre make RL				264
Tyre make RR				264

Assistance equipment

Number of charging cables (normal):	0
Number of charging cables (rapid charge):	1

Total cost ex VAT	4317,22
Ignition key, Missing, Replace	420,10



Bumper F, Scratch(es), Repair and paint (complete) 355,89



Bonnet, Hail damage, Paintless dent repair (hail) 224,56



Alloy rim RL, Scratch(es), Acceptable 0,00



Wing RL, Chemical polution, Acceptable 0,00



Wing FL, Chemical polution, Acceptable 0,00



Alloy rim FL, Scratch(es), Acceptable 0,00



Charging cable (normal), Missing, Check 0,00



Boot lid covering R, Scratch(es), Smart repair 116,69



Rear window, Scratch(es), Replace 848,10



Parking sensor R, Not functioning (well), Replace 213,77



Parking sensor R, Not functioning (well), Replace 213,77



Bumper R, Scratch(es), Repair and paint (complete) 355,89



Mirror side repeater R, Broken, Replace 62,91



Wing RR, Chemical polution, Repair and paint (complete) 517,89



Roof, Hail damage, Repair and paint (complete) 987,65



