



SKODA SUPERB COMBI: [Redacted]

Vinnumber:	TMBJW7NP1M7034690	Versionname:	1.4 TSI iV 160kW DSG6 Sportline
First Registrationdate:	14/12/2020	Fiscalpower:	
Expertise Mileage:	132558	Power Kw:	160
Bodytype:		Body colour:	Grey
Gearbox:	Automatic	Type of rims (mounted):	Aluminium
Transmission:		Parking lot:	2101
Fueltype:	Hybrid Petrol		
Type of rims (mounted):	Aluminium		
Certificate of Conformity:	Yes		
Category:	Passenger Car		
Registration Certificate Car (BE):	Yes		

Options

Number of keys total	2	Seats electric F L	
Cruise Control		Luggage cover	
Steering wheel multifunctional		Front parking sensors	
Seats F heated		Rear parking sensors	
Radio multimedia		Type of Tow bar	No Tow bar
Type of headlighting	Headlighting LED		
Type of GPS	GPS big screen color		
Type of Lining	Lining artificial leather and alcantara		
Type of climate control	Autom climate control		

Limited Technical Inspection

Tyres

235/45/18/92 H				
Winter tyres:	Fr.L.	Michelin: 5 mm	Fr.R.	Michelin: 5 mm
	Re.L.	Michelin: 5 mm	Re.R.	Michelin: 5 mm
Tyre profile depth FL				5.0
Tyre profile depth FR				5.0
Tyre profile depth RL				5.0
Tyre profile depth RR				5.0
Tyre size FL				235/45 R 18 92 H
Tyre size FR				235/45 R 18 92 H
Tyre size RL				235/45 R 18 92 H
Tyre size RR				235/45 R 18 92 H
Tyre type FL				Winter
Tyre type FR				Winter
Tyre type RL				Winter
Tyre type RR				Winter
Tyre make FL				261
Tyre make FR				261
Tyre make RL				261
Tyre make RR				261

Assistance equipment

Number of charging cables (normal)	1
Number of charging cables (rapid charge)	1

Total cost ex VAT	903,01
Windscreen, Scratch(es), Replace	0,00



Bonnet, Chemical polution, Polish	0,00
-----------------------------------	------



Alloy rim FL, Scratch(es), Repair and paint (complete)	133,03
--	--------



Rear window, Scratch(es), Acceptable	0,00
--------------------------------------	------



Bumper R, Scratch(es), Repair and paint (complete)	355,89
--	--------



Alloy rim FR, Scratch(es), Repair and paint (complete)	133,03
--	--------



Door trim RR, Missing, Replace	148,03
--------------------------------	--------



Alloy rim RR, Scratch(es), Repair and paint (complete)	133,03
--	--------



Roof pillar R, Dent(s), Acceptable	0,00
------------------------------------	------

