



### BMW 1

Vinnumber:	<b>WBA7M710407L16824</b>	Versionname:	
First Registrationdate:	<b>26/05/2022</b>	Fiscalpower:	
Expertise Mileage:	<b>91575</b>	Power Kw:	
Bodytype:		Body colour:	<b>Black</b>
Gearbox:	<b>Automatic</b>	Type of rims (mounted):	<b>Aluminium</b>
Transmission:		Parking lot:	<b>1713</b>
Fueltype:	<b>Diesel</b>		
Type of rims (mounted):	<b>Aluminium</b>		
Certificate of Conformity:	<b>Yes</b>		
Category:	<b>Passenger Car</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

### Options

Number of keys total:	<b>2</b>	Luggage cover:	
Cruise Control:		Front parking sensors:	
Steering wheel multifunctional:		Rear parking sensors:	
Radio multimedia:		Type of Tow bar:	<b>No Tow bar</b>
Type of headlighting:	<b>Headlighting LED</b>		
Type of GPS:	<b>GPS big screen color</b>		
Type of Lining:	<b>Lining fabrics</b>		
Type of climate control:	<b>Autom climate control</b>		

### Limited Technical Inspection

### Tyres











205/55/16/92 H				
Summer tyres:	Fr.L.	<b>Bridgestone: 5 mm</b>	Fr.R.	<b>Bridgestone: 5 mm</b>
	Re.L.	<b>Bridgestone: 5 mm</b>	Re.R.	<b>Bridgestone: 5 mm</b>
Tyre profile depth FL				<b>5.0</b>
Tyre profile depth FR				<b>5.0</b>
Tyre profile depth RL				<b>5.0</b>
Tyre profile depth RR				<b>5.0</b>
Tyre size FL				<b>205/55 R 16 92 H</b>
Tyre size FR				<b>205/55 R 16 92 H</b>
Tyre size RL				<b>205/55 R 16 92 H</b>
Tyre size RR				<b>205/55 R 16 92 H</b>
Tyre type FL				<b>Summer</b>
Tyre type FR				<b>Summer</b>
Tyre type RL				<b>Summer</b>
Tyre type RR				<b>Summer</b>
Tyre make FL				<b>255</b>
Tyre make FR				<b>255</b>
Tyre make RL				<b>255</b>
Tyre make RR				<b>255</b>

### Assistance equipment

Number of charging cables (normal):	<b>0</b>
Number of charging cables (rapid charge):	<b>0</b>

Total cost ex VAT	<b>737,44</b>
Seat cover FL, Stain, Cleaning	<b>29,16</b>



Seat cover FR, Stain, Cleaning	29,16
	
Seat cover R, Stain, Cleaning	29,16
	
Wing RL, Bad repair, Check	0,00
	
Door RL, Scratch(es), Acceptable	0,00
	
Door FL, Scratch(es), Acceptable	0,00
	
Alloy rim FL, Scratch(es), Acceptable	0,00
	
Rubber seal for boot lid, Broken, Replace	85,35
	
Bumper R, Scratch(es), Acceptable	0,00
	
Tailgate / Boot, Scratch(es), Acceptable	0,00
	
Wing RR, Dent(s) and scratch(es), Repair and paint (complete)	431,58
	
Alloy rim RR, Scratch(es), Repair and paint (complete)	133,03



Bodywork, Not original part, Remove lettering

0,00

