



Audi E-tron:			
Vinnumber:	WAUZZZGE4PB019486	Versionname:	AUDI E-TRON 55 Quattro Competition 408PK 5d/p AUT(GENCAE)
First Registrationdate:	15/12/2022	Fiscalpower:	
Expertise Mileage:	101650	Power Kw:	
Bodytype:		Body colour:	Black
Gearbox:	Automatic	Type of rims (mounted):	Aluminium
Transmission:		Parking lot:	2118
Fueltype:	Electric		
Maintenance:	OK		
Type of rims (mounted):	Aluminium		
Certificate of Conformity:	Yes		
Category:	Passenger Car		
Registration Certificate Car (BE):	Yes		
Registration Certificate Home (BE):	No		

Options			
Number of keys total:	2	Seats electric F L:	
Cruise Control:		Seats electric F R:	
Steering wheel multifunctional:		Sun Roof electric:	
Seats F heated:		Luggage cover:	
Radio multimedia:		Front parking sensors:	
Type of headlighting:	Headlighting LED	Rear parking sensors:	
Type of GPS:	GPS big screen color	Type of Tow bar:	Tow bar removable
Type of Lining:	Lining semi-artificial leather		
Type of climate control:	Autom climate control		
Type of GPS storage:	HD		

Limited Technical Inspection

Tyres

265/45/21/108 Y				
Summer tyres:	Fr.L.	Vredestein: 7 mm	Fr.R.	Vredestein: 7 mm
	Re.L.	Vredestein: 7 mm	Re.R.	Vredestein: 7 mm
Tyre profile depth FL				7.0
Tyre profile depth FR				7.0
Tyre profile depth RL				7.0
Tyre profile depth RR				7.0
Tyre size FL				265/45 R 21 108 Y
Tyre size FR				265/45 R 21 108 Y
Tyre size RL				265/45 R 21 108 Y
Tyre size RR				265/45 R 21 108 Y
Tyre type FL				All seasons
Tyre type FR				All Seasons
Tyre type RL				All seasons
Tyre type RR				All Seasons
Tyre make FL				2480
Tyre make FR				2480
Tyre make RL				2480
Tyre make RR				2480

Assistance equipment			
Repair kit:	Yes	Compressor:	Yes
Number of charging cables (normal):	1		
Number of charging cables (rapid charge):	1		
Total cost ex VAT:			2582,92
Backrest cover FL, Worn, Acceptable:			0,00



Bumper spoiler F, Broken, Replace 92,80



Bumper grille, Crack, Replace 259,04



Bumper F, Dent(s) and scratch(es), Repair and paint (complete) 415,40



Windscreen, Crack, Replace 0,00



Alloy rim FL, Scratch(es), Repair and paint (complete) 133,03



Door FL, Dent(s), Acceptable 0,00



Alloy rim RL, Scratch(es), Repair and paint (complete) 133,03



Interior covering C pillar R, Scratch(es), Replace 85,78



Bumper R, Dent(s) and scratch(es), Repair and paint (complete) 415,40



Bumper R, Scratch(es), Repair and paint (complete) 355,89



Bumper [redacted] ing R, Crack, Replace and paint 426,49



Alloy rim RR, Scratch(es), Repair and paint (complete) 133,03



Wing trim RR, Scratch(es), Acceptable 0,00



Door trim RR, Scratch(es), Repair and paint (complete) 0,00



Door RR, Dent(s) and scratch(es), Repair and paint (complete) 0,00



Door FR, Dent(s) and scratch(es), Acceptable 0,00



Outside rear-view mirror housing R, Scratch(es), Acceptable 0,00



Alloy rim FR, Scratch(es), Repair and paint (complete) 133,03



Wing trim FR, Scratch(es), Acceptable

0,00

