

MACADAM



Renault Clio

Vinnumber:	VF1RJA00367412924	Versionname:	
First Registrationdate:	26/05/2021	Fiscalpower:	
Expertise Mileage:	76928	Power Kw:	67
Bodytype:		Body colour:	Grey
Gearbox:	MAN 6 VIT	Type of rims (mounted):	Steel
Transmission:		Parking lot:	1207
Fueltype:	Petrol		
Type of rims (mounted):	Steel		
Certificate of Conformity:	Yes		
Category:	Passenger Car		
Registration Certificate Car (BE):	Yes		
Registration Certificate Home (BE):	No		

Options

Number of keys total:	2	Luggage cover:	
Cruise Control:		Rear parking sensors:	
Steering wheel multifunctional:		Type of Tow bar:	No Tow bar
Radio multimedia:			
Type of headlighting:	Headlighting LED		
Type of GPS:	GPS big screen color		
Type of Lining:	Lining fabrics		
Type of climate control:	Manual climate control		

Limited Technical Inspection

Tyres

195/55/16/87 H				
Summer tyres:	Fr.L.	Continental: 4 mm	Fr.R.	Continental: 4 mm
	Re.L.	Continental: 4 mm	Re.R.	Continental: 4 mm
Tyre profile depth FL				4.0
Tyre profile depth FR				4.0
Tyre profile depth RL				4.0
Tyre profile depth RR				4.0
Tyre size FL				195/55 R 16 87 H
Tyre size FR				195/55 R 16 87 H
Tyre size RL				195/55 R 16 87 H
Tyre size RR				195/55 R 16 87 H
Tyre type FL				All seasons
Tyre type FR				All Seasons
Tyre type RL				All seasons
Tyre type RR				All Seasons
Tyre make FL				256
Tyre make FR				256
Tyre make RL				256
Tyre make RR				256

Assistance equipment

Spare wheel:	Yes	Jack:	Yes
Number of charging cables (normal):	0		
Number of charging cables (rapid charge):	0		

Total cost ex VAT	644,03
Bumper F, Scratch(es), Repair and paint (complete)	237,26



Bonnet, Dent(s), Acceptable 0,00



Bumper moulding F, Scratch(es), Acceptable 0,00



Wheel cover FL, Scratch(es), Replace 22,50



Outside rear-view mirror housing L, Scratch(es), Acceptable 0,00



Tailgate / Boot, Dent(s), Paintless dent repair 95,47



Bumper R, Scratch(es), Spot repair 148,33



Wheel cover FR, Scratch(es), Replace 22,50



Wheel cover RR, Scratch(es), Replace 22,50



Roof, Dent(s), Acceptable 0,00



Roof, Dent(s), Paintless dent repair 95,47

