



PEUGEOT 5008: GK-982-MV

Vinnumber:	VF3MCYHZUNS138564	Versionname:	PEUGEOT 5008 BlueHDi 130 S&S EAT8 GT Pack VP [5P] bva 8-130CH-7cv (SUV)
First Registrationdate:	14/11/2022	Fiscalpower:	
Expertise Mileage:	191547	Power Kw:	96
Bodytype:	SUV	Body colour:	Black
Gearbox:	Automatic	Paint type:	Metallic
Transmission:	Front	Interior colour:	Black
Fueltype:	Diesel	Type of rims (mounted):	Aluminium
Engine functioning:	Yes	Dashboard color:	Black
Battery functioning:	Yes		
Vehicle running:	Yes		
Number of doors:	5		
Number of seats:	7		
Number head rests:	7		
Type of rims (mounted):	Aluminium		
Category:	Passenger Car		

Options

Number of keys total	2	Radio	
Number keys remote	2	Central consol F	
GPS big screen color		Luggage cover	
GPS storage		Headlights Xenon/LED/Laser	
GPS storage	HD	Front parking sensors	
Windows electric F		Rear parking sensors	
Windows electric R		Rear view camera	
Cruise Control		Seat cover lining	Lining Other
Steering wheel multifunctional			Lining Leather
Steering wheel leather			
Seats F heated			
Type of climate control	Autom climate control		

Tyres

205/55/19/97 V				
Summer tyres:	Fr.L.	Michelin: 50%	Fr.R.	Michelin: 40%
	Re.L.	Michelin: 30%	Re.R.	Michelin: 35%
Tyre profile depth FL				4.8
Tyre profile depth FR				5.6
Tyre profile depth RL				6.1
Tyre profile depth RR				5.8
Tyre size FL				205/55 R 19 97 V
Tyre size FR				205/55 R 19 97 V
Tyre size RL				205/55 R 19 97 V
Tyre size RR				205/55 R 19 97 V
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				261
Tyre make FR				261
Tyre make RL				261
Tyre make RR				261

Assistance equipment

Seat cover FL, Tear, Replace



Inner door sill RR, Dent(s) and scratch(es), Repair and paint (complete)



Seat cover FR, Stain, Cleaning



Inner door sill RL, Scratch(es), Paint



Alloy rim FR, Scratch(es), Repair/replace (lump sum)



Alloy rim RR, Scratch(es), Repair/replace (lump sum)



Alloy rim RL, Scratch(es), Repair/replace (lump sum)



Alloy rim FL, Scratch(es), Repair/replace (lump sum)



Bonnet, Stone chip(s), Paint



Windscreen, Stone chip(s), Replace



Windscreen glue kit, Required to install glazing, Repair/replace (lump sum)



Internal boot lining L, Scratch(es), Replace



Historique Maintenance

Immatriculation: **GK-982-MV** Date de 1ère immatriculation: **14/11/2022**

Modèle: **Peugeot 5008 BlueHDi 130 S&S EAT8 GT Pack VP [5P] bva 8-130CH-7cv (SUV)**

Date	Kilométrage	Fournisseur	Descriptif
26/02/2026	180.125	GARAGE HOUTIN	KIT ACCESSOIRES RPLT
	0		KIT DISTRIBUTION RPLT
05/02/2026	179.180	GARAGE HOUTIN	LIQUIDE DE FREIN
	0		BALAIS ESSUIE GLACE AV AR
	0		REVISION
18/09/2025	159.274	GARAGE HOUTIN	REVISION ET CLIM
	0		FILTRE A AIR RPLT
	0		REVISION
30/04/2025	136.525	GARAGE HOUTIN	PLAQUETTES AV RPLT
	0		REVISION
	0		PLAQUETTES AR RPLT
21/11/2024	115.025	GARAGE HOUTIN	LIQUIDE DE FREIN
	0		REVISION ET CLIM ET AIR ET CARBURANT
	0		BALAIS ESSUIE GLACE AV AR
	0		COURROIE ACCESSOIRES RPLT
11/07/2024	93.205	GARAGE HOUTIN	REVISION ET CLIM
15/02/2024	67.680	GARAGE HOUTIN	REVISION
12/10/2023	49.884	GARAGE HOUTIN	REVISION ET CLIM
	0		BALAIS ESSUIE GLACE AV AR
	0		PLAQUETTES AR RPLT
25/09/2023	47.066	PROFIL PLUS	REMPLACEMENT PNEUS ETE
07/04/2023	20.643	GARAGE HOUTIN	REVISION