

MACDAM

Polestar Polestar 2 '19 BEV

Vehicle information




Make:	Polestar	License:	
Gearbox:	Automatic	Body color:	
Model:	Polestar 2 '19 BEV	VIN:	LPSVSEDEEML023419
Fuel type:	Electric	Power:	300 kW
Version:	78kWh Pilot Plus	First registration	14/06/2021
Mileage:	144760 km	N° of doors:	

Damage summary

Front	1
Left	3
Rear	1
Right	2

Commercial pictures





Options according to the inspector

Central consol F	Yes	GPS	Yes	Headlights Xenon/LED/Laser	Yes
Hook	Yes	Panoramic roof	Yes	Radio multimedia	Yes
Rear view camera	Yes	Telephone equipment	Yes		

Damages

A-pillar right
Scratch(es)
Repair and paint (complete)
Front




Scratch(es)
Repair and paint (complete)
Left



Scratch(es)
Repair and paint (complete)
Right



Bumper R
Scratch(es)
Repair and paint (complete)
Rear



Door RL
Scratch(es)
Repair and paint (complete)
Left



Door RR
Scratch(es)
Repair and paint (complete)
Right



Wing RL
Scratch(es)
Repair and paint (complete)
Left



Tyres	
	Front Left
	Summer
	245/45/19/102/V
	Michelin
	4.3 mm
	Front Right
	Summer
	245/45/19/102/V
	Michelin
	6.2 mm
	Rear Left
	Summer
	245/45/19/102/V
	Pirelli
	6.3 mm
	Rear Right
	Summer
	245/45/19/102/V
	Michelin
	6.6 mm

Checks			
Certificate of Conformity	No	CO2 Emission	0
Digital maintenance	Yes	GPS storage	Yes
GPS storage	HD	Luggage cover	Yes
Number head rests	5	Number of charging cables (rapid charge)	1
Number of keys total	2	Reset to factory settings	Yes, vehicle is reset to factory settings
Service book	Yes	User's manual	Yes

Information on the content and the scope of the inspection report:

- The assessment is based on the sales standards specified by the customer.
- Acceptable usage damages according to the sales standards are not always documented in this status report.
- The specified repair methods and/or resulting repair times have been determined, taking into account modern industrial repair methods.
- The purchasing dealer should assess individual repair costs.
- The inspection was carried out in a non-disassembly condition. Macadam cannot be held responsible for any missing information. For further information, please contact the seller.