



Peugeot Expert:

Vinnumber:	VF3VAYHVKL7051364	Versionname:	
First Registrationdate:	7/10/2020	Fiscalpower:	
Expertise Mileage:	110396	Power Kw:	
Bodytype:		Body colour:	Grey
Gearbox:	MAN 6 VIT	Type of rims (mounted):	Steel
Transmission:		Parking lot:	3814
Fueltype:	Diesel		
Maintenance:	OK		
Type of rims (mounted):	Steel		
Certificate of Conformity:	Yes		
Category:	Passenger Car		
Registration Certificate Car (BE):	Yes		

Options

Number of keys total:	2	Rear parking sensors:	
Cruise Control:		Type of Tow bar:	Tow bar fixed
Steering wheel multifunctional:			
Radio multimedia:			
Type of headlighting:	Headlighting Halogen		
Type of GPS:	GPS big screen color		
Type of Lining:	Lining fabrics		
Type of climate control:	Manual climate control		
Type of GPS storage:	HD		

Limited Technical Inspection

Tyres

225/55/17/101 W				
Summer tyres:	Fr.L.	BF Goodrich: 4 mm	Fr.R.	BF Goodrich: 4 mm
	Re.L.	Michelin: 2 mm	Re.R.	Michelin: 2 mm
Tyre profile depth FL				4.0
Tyre profile depth FR				4.0
Tyre profile depth RL				2.0
Tyre profile depth RR				2.0
Tyre size FL				225/55 R 17 101 W
Tyre size FR				225/55 R 17 101 W
Tyre size RL				225/55 R 17 101 W
Tyre size RR				225/55 R 17 101 W
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				2485
Tyre make FR				2485
Tyre make RL				261
Tyre make RR				261

Assistance equipment

Number of charging cables (normal):	0		
Number of charging cables (rapid charge):	0		
Total cost ex VAT:			3213,78
Engine insulation, Damaged, Replace:			150,20



Bumper F, Dent(s) and scratch(es), Acceptable 0,00



Wheel cover FL, Scratch(es), Acceptable 0,00



Tyre repair kit, Missing, Check 0,00



Internal boot lining R, Scratch(es), Smart repair 116,69



Internal boot lining L, Scratch(es), Smart repair 116,69



Boot lid covering R, Scratch(es), Smart repair 116,69



Boot carpet, Damaged, Replace 1335,63



Boot cover, Missing, Replace 230,95



Bumper R, Dent(s) and scratch(es), Replace and paint 1070,34





Wheel cover FR, Scratch(es), Replace

76,59



Door FR, Scratch(es), Acceptable

0,00



Wing RR, Scratch(es), Acceptable

0,00



Wheel cover RR, Scratch(es), Acceptable

0,00

