


TOYOTA YARIS:

Vinnumber:	VNKKD3D340A684474	Versionname:	1.5 VVT-i Hybrid Comfort e-CVT
First Registrationdate:	4/05/2020	Fiscalpower:	
Expertise Mileage:	79606	Power Kw:	54
Bodytype:		Body colour	Black
Gearbox:	Automatic	Type of rims (mounted)	Aluminium
Transmission:		Parking lot	3824
Fueltype:	Hybrid Petrol		
Type of rims (mounted)	Aluminium		
Certificate of Conformity	Yes		
Category	Passenger Car		
Registration Certificate Car (BE)	Yes		

Options

Number of keys total	2	Rear parking sensors	
Cruise Control		Type of Tow bar	No Tow bar
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS base		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		
Type of GPS storage	HD		

Limited Technical Inspection
Tyres

	175/65/15/84 H			
Summer tyres:	Fr.L.	Bridgestone: 5 mm	Fr.R.	Bridgestone: 4 mm
	Re.L.	Dunlop: 5 mm	Re.R.	Dunlop: 5 mm
Tyre profile depth FL				5.0
Tyre profile depth FR				4.0
Tyre profile depth RL				5.0
Tyre profile depth RR				5.0
Tyre size FL				175/65 R 15 84 H
Tyre size FR				175/65 R 15 84 H
Tyre size RL				175/75 R 15 84 H
Tyre size RR				175/65 R 15 84 H
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				255
Tyre make FR				255
Tyre make RL				257
Tyre make RR				257

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		


Total cost ex VAT	4540,41
Door panel FL, Burned, Smart repair	116,69



Seat cover R, Burned, Smart repair	116,69
------------------------------------	--------



Door panel RL, Scratch(es), Acceptable	0,00
--	------



Interior, Worn, Forfeit	65,46
-------------------------	-------



Floor covering FL, Burned, Smart repair	116,69
---	--------




Interior, Worn, Acceptable	0,00
----------------------------	------




Floor covering R, Burned, Smart repair	116,69
--	--------




Seat cover FR, Stain, Cleaning	29,16
--------------------------------	-------



Bumper F, Scratch(es), Repair and paint (complete)	237,26
--	--------



Bonnet, Scratch(es), Acceptable	0,00
---------------------------------	------



Bumper moulding F, Deformed / Strained, Replace

67,50



Alloy rim FL polished, Scratch(es), Repair and paint (complete)

204,21



Door FL, Dent(s) and scratch(es), Repair and paint (complete)

594,66



Door RL, Dent(s) and scratch(es), Repair and paint (complete)

594,66



Central pillar L, Chemical polution, Acceptable

0,00



Wing RL, Dent(s) and scratch(es), Repair and paint (complete)

583,29



Alloy rim RL polished, Scratch(es), Acceptable

0,00



Outer sill L, Dent(s) and scratch(es), Repair and paint (complete)

466,85



Step L, Dent(s) and scratch(es), Spot repair

178,08



Boot lid covering R, Scratch(es), Acceptable

0,00



Luggage compartment cover, Worn, Acceptable

0,00



Internal boot lining L, Scratch(es), Smart repair

116,69



Bumper R, Scratch(es), Acceptable

0,00



Bumper moulding R, Scratch(es), Acceptable

0,00



Alloy rim FR polished, Scratch(es), Repair and paint (complete)

204,21




Outside rear-view mirror R, complete, Scratch(es), Acceptable

0,00



Wing RR, Dent(s) and scratch(es), Repair and paint (complete)

375,00





Door RR, Scratch(es), Repair and paint (complete)

356,62



Door FR, Scratch(es), Acceptable

0,00

