



RENAULT KADJAR: 1

Vinnumber:	VF1RFE00364582307	Versionname:	Blue dCi 115 Corporate Edition
First Registrationdate:	3/12/2019	Fiscalpower:	
Expertise Mileage:	111535	Power Kw:	85
Bodytype:		Body colour	Blue
Gearbox:	MAN 6 VIT	Type of rims (mounted)	Aluminium
Transmission:		Parking lot	3509
Fueltype:	Diesel		
Maintenance	OK		
Type of rims (mounted)	Aluminium		
Certificate of Conformity	Yes		
Category	Passenger Car		
Registration Certificate Car (BE)	Yes		
Registration Certificate Home (BE)	No		

Options

Number of keys total	2	Luggage cover	
Cruise Control		Front parking sensors	
Steering wheel multifunctional		Rear parking sensors	
Radio multimedia		Type of Tow bar	Tow bar collapsible
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS base		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		
Type of GPS storage	HD		

Limited Technical Inspection

Tyres

		215/60/17/96 H		
Summer tyres:	Fr.L.	Vredestein: 5 mm	Fr.R.	Vredestein: 6 mm
	Re.L.	Michelin: 6 mm	Re.R.	Michelin: 5 mm
Tyre profile depth FL				5.0
Tyre profile depth FR				6.0
Tyre profile depth RL				6.0
Tyre profile depth RR				5.0
Tyre size FL				215/60 R 17 96 H
Tyre size FR				215/60 R 17 96 H
Tyre size RL				215/60 R 17 96 H
Tyre size RR				215/60 R 17 96 H
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				2480
Tyre make FR				2480
Tyre make RL				261
Tyre make RR				261

Assistance equipment

Spare wheel	Yes	Jack	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	1891,04
Engine insulation, Damaged, Replace	154,44



Engine insulation, Damaged, Replace 154,44



Bonnet, Chemical pollution, Polish 0,00



Rubber seal for boot lid, Broken, Replace 106,31



Bumper R, Scratch(es), Replace 480,92




Bumper trim R, Scratch(es), Smart repair 116,69




Wing trim RR, Scratch(es), Replace 137,61



Alloy rim RR, Scratch(es), Acceptable 0,00



Door RR, Bad repair, Repair and paint (complete) 445,79



Door FR, Scratch(es), Acceptable 0,00



Outside rear-view mirror housing R, Scratch(es), Repair and paint (complete)

161,81



Alloy rim FR, Scratch(es), Repair and paint (complete)

133,03

