

MACADAM ITALY S.R.L. Piazza Belgioioso, 2 - 20121 Milano (MI) Tel. - Fax Piva: 12729790969				Report No.		Expert's report for Alphabet Italia				Type of insurance Perizia									
				Policyholder				Opposite party				Opposite party company							
				Operation 2026		Claim number		Code / Agency				Date accident 14/07/2026							
				Expert code		Adjuster code		Policy number				Injured person can recover the VAT							
Date assignment 14/07/2026		Date first survey 21/07/2026		Place POMEZIA		C/O VAR		Repairs TO START		Photo Lien in favor of									
Ownership certificate Alphabet Italia - Via Romano Guardini 24 38121 Trento (TN)										Formerly plate									
Lessee / Co-owner										Date of overhaul									
Vehicle (Brand - Model - Version) RENAULT Captur 2ª serie Captur Blue dCi 115 CV EDC Business								Plate GC978YP		Vin Chassis VF1RJB00065965953									
Usage status FAIR		Km 209281		Tyres % 90		Color GRIGIO		Type of enamel METALLIZED/DOUBLE		Consistency of damage Type of Expert's report NOT DEFINITIVE									
Equipment																			
Approval code		For commercial vehicles		Carrying Qls 0		Tare, Q 0						Wheelbase		Seats No. 0					
Commercial value (C)		Wrecked car value		Value by difference		Ancillary expenses						Axles 0							
Damaged items / restoration operations								SR		LA		VE		ME		D.M. S.C.		Costs of spare parts * (VAT excluded)	
1 727129450R Windshield								S		S		S							
1 Codice Ricambio Kit incollaggio cristalli								S		S		S							
1 620260503R Front bumper lower part								S		S		S							
1 620848708R Front bumper grille								S		S		S							
1 850B24277R Rear central bumper								S		S		S							
1 850705503R Rear bumper lower cladding								S		S		S							
1 788A20700R Rear wheel arch trim R								S		S		S							
1 638127184R Front wheel arch trim R								S		S		S							
1 620227396R Front bumper upper part								M		M		M							
1 821002058R Rear door R								M		L		M							
1 821015086R Rear door L								M		M		M							
1 801012941R Front door L								M		M		M							
1 850173301R Rear side bumper L								L		L		L							
1 850165525R Rear side bumper R								L		L		L							
1 760393260R rear mudguard L								L		L		L							
1 Codice Ricambio Rettifica cerchio lega post. L																			
1 Codice Ricambio Igienizzazione interni																			

New for old value (N)	Remarks PNEUM FULDA 215/60R17 SPIA SERVICE ACCESA E CHIAMATA SOS DA CONTROLLARE.
-----------------------	--