

BMW X5 '18


Vehicle information

Make:	BMW	License:	
Gearbox:	Automatic	Body color:	
Model:	X5 '18	VIN:	WBATA610209E18826
Fuel type:	Plug-in hybrid	Power:	290 kW
Version:	X5 xDrive45e	First registration	12/11/2020
Mileage:	180920 km	N° of doors:	

Damage summary

Front	2
Left	1
Rear	3
Right	1

Commercial pictures




Options according to the inspector

Central consol F	Yes GPS	Yes Headlights Xenon/LED/Laser	Yes
Panoramic roof	Yes Radio multimedia	Yes Sun Roof electric	Yes
Telephone equipment	Yes		

Damages

Bonnet

Stone chip(s)
Repair and paint (complete)
Front



Bumper F

Scratch(es)
Repair and paint (complete)
Front



Bumper moulding R

Scratch(es)
Replace and paint
Rear



Bumper trim R

Scratch(es)

Replace

Rear



Door FR

Scratch(es)

Repair and paint (complete)

Right




Door RL

Scratch(es)

Repair and paint (complete)

Left




Tailgate / Boot

Scratch(es)

Repair and paint (complete)

Rear



Tyres

Front Left

Winter

265/50/19/110/H

Michelin

5.7 mm

Front Right

Winter

265/50/19/110/H

Michelin

5.7 mm

Rear Left

Winter

265/50/19/110/H

Michelin

6.2 mm

Rear Right

Winter

265/50/19/110/H

Michelin

5.2 mm

Checks

Certificate of Conformity	No CO2 Emission	37
Customer data reset (contacts, e-mails, messages)	Yes Digital maintenance	Yes
GPS storage	Yes GPS storage	HD
Luggage cover	Yes Number head rests	5
Number of charging cables (normal)	1 Number of charging cables (rapid charge)	1
Number of keys total	2 Service book	N/A
User's manual	Yes	

Information on the content and the scope of the inspection report:

- The assessment is based on the sales standards specified by the customer.
- Acceptable usage damages according to the sales standards are not always documented in this status report.
- The specified repair methods and/or resulting repair times have been determined, taking into account modern industrial repair methods.
- The purchasing dealer should assess individual repair costs.
- The inspection was carried out in a non disassembly condition. Macadam cannot be held responsible for any missing information. For further information, please contact the seller.